



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20001313/Aqd3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 09-04-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 4275H	Veh. Inspected	SJL 6816S
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000364/FW	Excess (\$)	0.00
Assign From	HENRY IRENE JAMES	Assign Date	22/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PREVIA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JTEGD52M20A012771	Colour	GREY
Odometer	178865	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	HABILEAD	6 mm
L/H Front Tyre	215/60 R16	HABILEAD	6 mm
R/H Rear Tyre	215/60 R16	HABILEAD	6 mm
L/H Rear Tyre	215/60 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/01/2020	Inspection Date	22/01/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------