



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 35504

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 21/01/2020
CLAIM NO. : 11489
POLICY NO. : MC/00628328

VEHICLE NO. : FBK4037L
MAKE/MODEL : YAM / MT-09

FROM : HASRIANAH

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER SET MT-09	REPLACE	1.00	\$63.00	SCR 63.00 ✓
2	BAR HANDLE (RIZOMA)MT-09	REPLACE	1.00	\$252.00	su 252.00 x
3	BEARING STEERING CONE LOWER P/N: 27589	REPLACE	1.00	\$82.00	17 82.00 q
4	BEARING STEERING CONE UPPER P/N: 64122	REPLACE	1.00	\$56.00	17 56.00 x
5	BOLT P/N: 46879	REPLACE	1.00	\$3.00	nee 3.00 ✓
6	BOLT	REPLACE	4.00	\$2.00	nee 8.00 ✓
7	BOTTLE BRAKE OIL	REPLACE	1.00	\$35.00	nee 35.00 ✓
8	BOX REAR KAPPA K58L P/N: 64327	REPLACE	1.00	\$1,050.00	su 1,050.00 x
9	BRACKET MASTER CYLINDER(DMV)	REPLACE	1.00	\$105.00	cm 105.00 ✓
10	BRACKET 5	REPLACE	1.00	\$97.00	su 97.00 ✓
11	BRACKET MASTER CYLINDER P/N: 58787	REPLACE	1.00	\$38.00	31 38.00 ✓
12	BRACKET UNDER FORK P/N: 56483	REPLACE	1.00	\$667.00	n 667.00 x
13	CABLE THROTTLE P/N: 63046	REPLACE	1.00	\$56.00	cu 56.00 ✓

*35504 *

bizSAFE₃



Address: No. 6, Delta lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-4-0103
ISSUED: 2015

Quotation Nos. : 35504

(Page 2 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
14	CAP GRIP P/N: 63033	REPLACE	1.00	\$19.00	19.00
15	COLLAR	REPLACE	4.00	\$6.00	24.00
16	COVER 1 P/N: 62947	REPLACE	1.00	\$119.00	119.00
17	COVER 1	REPLACE	1.00	\$149.00	149.00
18	COVER 2	REPLACE	1.00	\$119.00	119.00
19	COVER COOLANT P/N: 51074	REPLACE	1.00	\$28.00	28.00
20	COVER GRIP (GRAB ON) P/N: 56090	REPLACE	1.00	\$29.00	29.00
21	COVER HEADLAMP (R&G) P/N: 62955	REPLACE	1.00	\$110.00	110.00
22	COVER PANNEL INNER 3	REPLACE	1.00	\$20.00	20.00
23	COVER SIDE 2	REPLACE	1.00	\$90.00	90.00
24	COVER TANK P/N: 58434	REPLACE	1.00	\$31.00	31.00
25	CRASH BAR (GIVI) P/N: 58427	REPLACE	1.00	\$356.00	356.00
26	DAMPER P/N: 58433	REPLACE	1.00	\$2.00	2.00
27	DAMPER P/N: 58433	REPLACE	1.00	\$2.00	2.00
28	DAMPER	REPLACE	2.00	\$3.00	6.00
29	DAMPER, HEADLIGHT 1	REPLACE	1.00	\$12.00	12.00
30	DAMPER, HEADLIGHT 2	REPLACE	1.00	\$12.00	12.00
31	EMBLEM P/N: 47701	REPLACE	1.00	\$26.00	26.00
32	EMBLEM P/N: 47701	REPLACE	1.00	\$26.00	26.00
33	EMBLEM 3D P/N: 51083	REPLACE	1.00	\$38.00	38.00
34	EMBLEM 3D P/N: 51083	REPLACE	1.00	\$38.00	38.00
35	EMBLEM YAMAHA	REPLACE	1.00	\$16.00	16.00

*35504 *

bizSAFE₃

Address: No. 6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2003-1-0000
 002 Y001 2010

Quotation Nos. : 35504

(Page 3 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
36	FOOTREST FRONT LH P/N: 34788	REPLACE	1.00	\$45.00	45.00
37	GASKET HOSE BRAKE P/N: 45943	REPLACE	2.00	\$3.00	6.00
38	GRAPHIC 1 P/N: 62948	REPLACE	1.00	\$16.00	16.00
39	HEADLIGHT ASSY P/N: 62953	REPLACE	1.00	\$1,199.00	1,199.00
40	LABEL, CAUTION P/N: 63029	REPLACE	1.00	\$7.00	7.00
41	LABEL, FUEL P/N: 63021	REPLACE	1.00	\$7.00	7.00
42	LABOUR P/N: 06766 - FOR DISMANTLING & ASSEMBLING OF PARTS QUOTED	Supply/Install	20.00	\$63.00	1,260.00
43	LIGHT TOUREX WITH BRACKET SET	REPLACE	1.00	\$259.00	259.00
44	METER ASSY	REPLACE	1.00	\$829.00	829.00
45	MIRROR RH P/N: 51069	REPLACE	1.00	\$61.00	61.00
46	NUT (WINDSCREEN) P/N: 46834	REPLACE	4.00	\$5.00	20.00
47	NUT SPRING P/N: 45260	REPLACE	6.00	\$2.00	12.00
48	NUT SPRING P/N: 45260	REPLACE	6.00	\$2.00	12.00
49	NUT SPRING P/N: 45260	REPLACE	3.00	\$2.00	6.00
50	OIL BRAKE (MOTUL) RBF 600 P/N: 44153	REPLACE	1.00	\$37.00	37.00
51	PANEL 1 P/N: 58410	REPLACE	1.00	\$105.00	105.00
52	PANEL 2 P/N: 51066	REPLACE	1.00	\$103.00	103.00
53	PANEL INNER RH P/N: 64168	REPLACE	1.00	\$194.00	194.00
54	PIN COTTER	REPLACE	1.00	\$5.00	5.00
55	PLUG, SPEC'L SHAPE	REPLACE	2.00	\$2.00	4.00
56	PUMP MASTER CYCLINDER R3 SET	REPLACE	1.00	\$363.00	363.00
57	RUBBER COVER 4 LED TOUREX LIGHT	REPLACE	1.00	\$28.00	28.00

*35504 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERTIFIED TO ISO 9001:2015
 ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
58	RUBBER FOOTREST FRONT P/N: 34783	REPLACE	1.00	\$21.00	21.00
59	SCREW (VISOR) P/N: 20898	REPLACE	4.00	\$5.00	20.00
60	SCREW PAN P/N: 24202	REPLACE	1.00	\$2.00	2.00
61	SEAL STEERING CONE P/N: 27596	REPLACE	1.00	\$31.00	31.00
62	SHIFT PEDAL ASSY P/N: 63018	REPLACE	1.00	\$89.00	89.00
63	SIDESTAND FOOT (SWMOTECH) MT-09 TRACER P/N: 52039	REPLACE	1.00	\$149.00	149.00
64	SIGNAL FRONT ASSY LH P/N: 62951	REPLACE	1.00	\$38.00	38.00
65	SIGNAL FRONT RH P/N: 51077	REPLACE	1.00	\$38.00	38.00
66	STAY P/N: 58440	REPLACE	1.00	\$180.00	180.00
67	STAY SIDE 1 P/N: 58422	REPLACE	1.00	\$31.00	31.00
68	STAY SIDE 1 P/N: 58417	REPLACE	1.00	\$31.00	31.00
69	STAY, FLASHER 1 P/N: 65162	REPLACE	1.00	\$3.00	3.00
70	STAY, SUPPORT 1 P/N: 63031	REPLACE	1.00	\$24.00	24.00
71	STICKER GRAPHIC 2	REPLACE	1.00	\$16.00	16.00
72	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	19.00
73	WASHER PLATE P/N: 28656	REPLACE	1.00	\$5.00	5.00
74	WINDSHIELD (MRA) MT-09	REPLACE	1.00	\$210.00	210.00

SUB TOTAL
GST @ 7 %

\$9,269.00
\$648.83

GRAND TOTAL

\$9,917.83

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

*35504 *

LKK Auto Consultants hence notify the Repairer of the following:

- * To be repaired (P/L) during recovery
- * Parts names, quantities and specifications
- * To be repaired on "Without Prejudice" basis
- * To be repaired on "As is" basis
- * To be repaired on "As is" basis
- * To be repaired on "As is" basis

Acknowledge & Accepted By

Acknowledged by Repairer
Signature:
Date:

bizSAFE₃



p- 5928
1M
5336.1
5746.1
202
4546.88



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197002288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 35934

Supplementary 1 To QTN: 35504

DATE : 06/04/2020
CLAIM NO. : 11489
POLICY NO. : MC/00628328
FROM : RAYMOND

VEHICLE NO. : FBK4037L
MAKE/MODEL : YAM / MT-09

S/N	Description	Action	Qty	Unit Price	Amount
1	LEVER BRAKE P/N: 66101	Replace	1.00	\$77.00	77.00
SUB TOTAL					\$77.00
GST @ 7 %					\$5.39
GRAND TOTAL					\$82.39

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*35934 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 35504

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 21/01/2020
CLAIM NO. : 11489
POLICY NO. : MC/00628328

FROM : HASRIANAH

VEHICLE NO. : FBK4037L
MAKE/MODEL : YAM / MT-09

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER SET MT-09	REPLACE	1.00	\$63.00	56.70
				Disc %: 10.00	
2	BOLT	REPLACE	1.00	\$3.00	2.70
	P/N: 46879			Disc %: 10.00	
3	BOLT	REPLACE	4.00	\$2.00	7.20
				Disc %: 10.00	
4	BOTTLE BRAKE OIL	REPLACE	1.00	\$35.00	31.50
				Disc %: 10.00	
5	BRACKET MASTER CYLINDER(DMV)	REPLACE	1.00	\$105.00	94.50
				Disc %: 10.00	
6	BRACKET 5	REPLACE	1.00	\$97.00	87.30
				Disc %: 10.00	
7	BRACKET MASTER CYLINDER	REPLACE	1.00	\$38.00	34.20
	P/N: 58787			Disc %: 10.00	
8	CABLE THROTTLE	REPLACE	1.00	\$56.00	50.40
	P/N: 63046			Disc %: 10.00	
9	CAP GRIP	REPLACE	1.00	\$19.00	17.10
	P/N: 63033			Disc %: 10.00	
10	COLLAR	REPLACE	4.00	\$6.00	21.60
				Disc %: 10.00	
11	COVER 1	REPLACE	1.00	\$119.00	107.10
	P/N: 62947			Disc %: 10.00	
12	COVER 1	REPLACE	1.00	\$149.00	134.10
				Disc %: 10.00	
13	COVER 2	REPLACE	1.00	\$119.00	107.10
				Disc %: 10.00	

*35504 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2022-140383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
58	SIGNAL FRONT ASSY LH P/N: 62951	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
59	SIGNAL FRONT RH P/N: 51077	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
60	STAY P/N: 58440	REPLACE	1.00	\$180.00 Disc %: 10.00	162.00
61	STAY SIDE 1 P/N: 58422	REPLACE	1.00	\$31.00 Disc %: 10.00	27.90
62	STAY SIDE 1 P/N: 58417	REPLACE	1.00	\$31.00 Disc %: 10.00	27.90
63	STAY, FLASHER 1 P/N: 65162	REPLACE	1.00	\$3.00 Disc %: 10.00	2.70
64	STAY, SUPPORT 1 P/N: 63031	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
65	STICKER GRAPHIC 2	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
66	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	10.00
67	WASHER PLATE P/N: 28656	REPLACE	1.00	\$5.00 Disc %: 10.00	4.50
68	WINDSHIELD (MRA) MT-09	REPLACE	1.00	\$210.00 Disc %: 10.00	189.00
69	LEVER BRAKE P/N: 66101	Replace	1.00	\$77.00 Disc %: 10.00	69.30

SUB TOTAL

\$5,746.10

GST @ 7 %

\$402.23

GRAND TOTAL

\$6,148.33

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*35504 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
 ISO 9001:2015