



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 35504

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 21/01/2020
CLAIM NO. : 11489
POLICY NO. : MC/00628328

FROM : HASRIANAH

VEHICLE NO. : FBK4037L
MAKE/MODEL : YAM / MT-09

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER SET MT-09	REPLACE	1.00	\$63.00	Sum 63.00 ✓
2	BAR HANDLE (RIZOMA)MT-09	REPLACE	1.00	\$252.00	Sum 252.00 x
3	BEARING STEERING CONE LOWER P/N: 27589	REPLACE	1.00	\$82.00	17 82.00 x
4	BEARING STEERING CONE UPPER P/N: 64122	REPLACE	1.00	\$56.00	17 56.00 x
5	BOLT P/N: 46879	REPLACE	1.00	\$3.00	3.00 ?
6	BOLT	REPLACE	4.00	\$2.00	8.00 ?
7	BOTTLE BRAKE OIL	REPLACE	1.00	\$35.00	35.00 ?
8	BOX REAR KAPPA K58L P/N: 64327	REPLACE	1.00	\$1,050.00	Sum 1,050.00 x
9	BRACKET MASTER CYLINDER(DMV)	REPLACE	1.00	\$105.00	one 105.00 ✓
10	BRACKET 5	REPLACE	1.00	\$97.00	Sum 97.00 ✓
11	BRACKET MASTER CYLINDER P/N: 58787	REPLACE	1.00	\$38.00	38 38.00 ✓
12	BRACKET UNDER FORK P/N: 56483	REPLACE	1.00	\$667.00	2 667.00 x
13	CABLE THROTTLE P/N: 63046	REPLACE	1.00	\$56.00	one 56.00 ✓

*35504 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
14	CAP GRIP P/N: 63033	REPLACE	1.00	\$19.00	19.00
15	COLLAR	REPLACE	4.00	\$6.00	24.00
16	COVER 1 P/N: 62947	REPLACE	1.00	\$119.00	119.00
17	COVER 1	REPLACE	1.00	\$149.00	149.00
18	COVER 2	REPLACE	1.00	\$119.00	119.00
19	COVER COOLANT P/N: 51074	REPLACE	1.00	\$28.00	28.00
20	COVER GRIP (GRAB ON) P/N: 56090	REPLACE	1.00	\$29.00	29.00
21	COVER HEADLAMP (R&G) P/N: 62955	REPLACE	1.00	\$110.00	110.00
22	COVER PANNEL INNER 3	REPLACE	1.00	\$20.00	20.00
23	COVER SIDE 2	REPLACE	1.00	\$90.00	90.00
24	COVER TANK P/N: 58434	REPLACE	1.00	\$31.00	31.00
25	CRASH BAR (GIVI) P/N: 58427	REPLACE	1.00	\$356.00	356.00
26	DAMPER P/N: 58433	REPLACE	1.00	\$2.00	2.00
27	DAMPER P/N: 58433	REPLACE	1.00	\$2.00	2.00
28	DAMPER	REPLACE	2.00	\$3.00	6.00
29	DAMPER, HEADLIGHT 1	REPLACE	1.00	\$12.00	12.00
30	DAMPER, HEADLIGHT 2	REPLACE	1.00	\$12.00	12.00
31	EMBLEM P/N: 47701	REPLACE	1.00	\$26.00	26.00
32	EMBLEM P/N: 47701	REPLACE	1.00	\$26.00	26.00
33	EMBLEM 3D P/N: 51083	REPLACE	1.00	\$38.00	38.00
34	EMBLEM 3D P/N: 51083	REPLACE	1.00	\$38.00	38.00
35	EMBLEM YAMAHA	REPLACE	1.00	\$16.00	16.00

*35504 *

bizSAFE₃CERT NO: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
36	FOOTREST FRONT LH P/N: 34788	REPLACE	1.00	\$45.00	45.00
37	GASKET HOSE BRAKE P/N: 45943	REPLACE	2.00	\$3.00	6.00
38	GRAPHIC 1 P/N: 62948	REPLACE	1.00	\$16.00	16.00 ?
39	HEADLIGHT ASSY P/N: 62953	REPLACE	1.00	\$1,199.00	1,199.00
40	LABEL, CAUTION P/N: 63029	REPLACE	1.00	\$7.00	7.00
41	LABEL, FUEL P/N: 63021	REPLACE	1.00	\$7.00	7.00
42	LABOUR P/N: 06766 - FOR DISMANTLING & ASSEMBLING OF PARTS QUOTED	Supply/Install	20.00	\$63.00	1,260.00
43	LIGHT TOUREX WITH BRACKET SET	REPLACE	1.00	\$259.00	259.00
44	METER ASSY	REPLACE	1.00	\$829.00	829.00
45	MIRROR RH P/N: 51069	REPLACE	1.00	\$61.00	61.00
46	NUT (WINDSCREEN) P/N: 46834	REPLACE	4.00	\$5.00	20.00
47	NUT SPRING P/N: 45260	REPLACE	6.00	\$2.00	12.00
48	NUT SPRING P/N: 45260	REPLACE	6.00	\$2.00	12.00
49	NUT SPRING P/N: 45260	REPLACE	3.00	\$2.00	6.00
50	OIL BRAKE (MOTUL) RBF 600 P/N: 44153	REPLACE	1.00	\$37.00	37.00
51	PANEL 1 P/N: 58410	REPLACE	1.00	\$105.00	105.00 ?
52	PANEL 2 P/N: 51066	REPLACE	1.00	\$103.00	103.00 ?
53	PANEL INNER RH P/N: 64168	REPLACE	1.00	\$194.00	194.00 ?
54	PIN COTTER	REPLACE	1.00	\$5.00	5.00 ?
55	PLUG, SPEC'L SHAPE	REPLACE	2.00	\$2.00	4.00 ?
56	PUMP MASTER CYCLINDER R3 SET	REPLACE	1.00	\$363.00	363.00 ?
57	RUBBER COVER 4 LED TOUREX LIGHT	REPLACE	1.00	\$28.00	28.00 ?

*35504 *

bizSAFE₃CERT NO. 2002-1-0383
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
58	RUBBER FOOTREST FRONT P/N: 34783	REPLACE	1.00	\$21.00	21.00 ✓
59	SCREW (VISOR) P/N: 20898	REPLACE	4.00	\$5.00	20.00 ✓
60	SCREW PAN P/N: 24202	REPLACE	1.00	\$2.00	2.00 ✓
61	SEAL STEERING CONE P/N: 27596	REPLACE	1.00	\$31.00	31.00 X
62	SHIFT PEDAL ASSY P/N: 63018	REPLACE	1.00	\$89.00	89.00 ✓
63	SIDESTAND FOOT (SWMOTECH) MT-09 TRACER P/N: 52039	REPLACE	1.00	\$149.00	149.00 ✓
64	SIGNAL FRONT ASSY LH P/N: 62951	REPLACE	1.00	\$38.00	38.00 ✓
65	SIGNAL FRONT RH P/N: 51077	REPLACE	1.00	\$38.00	38.00 ✓
66	STAY P/N: 58440	REPLACE	1.00	\$180.00	180.00 ?
67	STAY SIDE 1 P/N: 58422	REPLACE	1.00	\$31.00	31.00 ?
68	STAY SIDE 1 P/N: 58417	REPLACE	1.00	\$31.00	31.00 ?
69	STAY, FLASHER 1 P/N: 65162	REPLACE	1.00	\$3.00	3.00 ?
70	STAY, SUPPORT 1 P/N: 63031	REPLACE	1.00	\$24.00	24.00 ?
71	STICKER GRAPHIC 2	REPLACE	1.00	\$16.00	16.00 ?
72	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	19.00 10
73	WASHER PLATE P/N: 28656	REPLACE	1.00	\$5.00	5.00 ✓
74	WINDSHIELD (MRA) MT-09	REPLACE	1.00	\$210.00	210.00 ✓

SUB TOTAL

\$9,269.00

GST @ 7 %

\$648.83

GRAND TOTAL

\$9,917.83

50% deposit required before ordering of parts. Resurvey before/after spray painting

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

*35504 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledge & Accepted By

bizSAFE₃CERT NO: 2002-1-0383
SIC 0021, 2010

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	 HASRIANAH				

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*35504 *

bizSAFE₃



CERT NO : 2002-1-0283
ISO 9001 : 2015