

ASSIGNMENT

Surveyor:

MARCUS

DOI: 22/01/2020

Date / Time : 22/01/2020

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SGE 5899G

Claim No. : \_\_\_\_\_

Name of Insured : KE JIN SHAN

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II :SS D.O.A : 21/01/2020 09:40

Place of Accident : AYE TWDS KEPPEL

Is driver the owner? (YES / NO) Nature of Accident : \_\_\_\_\_

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age : \_\_\_\_\_

Insured Liability : % Final ? Yes / No

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

SLK 9383K



INSRS: HUP MOTOR  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

SLK 9383K }  
SGE 5899G } NA/FWD20001326/h4; DOA: 21.01.2020

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: OKS

Repair Cost:

SS 7,200

( 11 days) Reduction: 51 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 05.03.20

Confirm with: DAVID

Email ☒ Call ☐

Final Liability:

%

(W) (Agreed / Agreed) BOLA S/N No. : 28 (See 01/10/20)

If NO or B 28, Ass. Lia : UP

Repair Cost:

SS 7,200.00

Loss of Rental (LOR):

SS 1,500.00

( 15 days) x 100

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only ☒

LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 200

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 8,700.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 05.03.20

Confirm with: DAVID

Email ☒ Call ☐

Payee 1:

SS 8,700.00

Name 1: HUP MOTOR TRADING & SERVICE

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 1400

COPY SENT  
12/3/2020



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles



stream

Price Range

Depreciation

&gt; 10 year(s)

Vehicle Type

Home » Used Cars » Tay Motor &amp; Credit Pte Ltd » Honda Stream 1.8A (COE till 04/2022)

## Honda Stream 1.8A (COE till 04/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



TAY MOTOR &amp; CREDIT PTE LTD

Our Accreditations:



Price \$20,800

Depreciation \$9,220 /yr

Reg Date 26-Apr-2007  
(2yrs 3mths 2days COE left)

Mileage N.A.

Manufactured 2007

Road Tax \$1,271 /yr

Transmission Auto

Dereg Value \$11,727 as of today (change)

OMV \$17,340

COE \$26,004

ARF \$19,074

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight 1,350 kg

No. of Owners 3

Type of Vehicle MPV

## Features

ABS Braking System, SRS Airbags, Responsive & Reliable 1.8L I-VTEC Engine, 5 Speed Auto Transmission. View specs of the Honda Stream

## Accessories

Leather Seats, Sports Rims, Pioneer Touchscreen DVD, Reverse Sensors/Camera, UV Solar Films.

## Description

Very Good Condition And Well Maintained Interior, Well Maintained With Regular Servicing, No Repair Needed, Can Drive Off With No Worries, High Value For Your Car When You Trade In With Us.

## Category

COI Compare

[https://www.sgcarmart.com/used\\_cars/info.php?ID=877739&DL=1091](https://www.sgcarmart.com/used_cars/info.php?ID=877739&DL=1091)


Location Map

Shortlist

Compare

Report Error

More

## Seller Information

## Tay Motor &amp; Credit Pte

23 vehicles for sale. 13 sold in

210 Turf Club Road Lot A3/1  
Car Mall @ The Grandstand  
Search cars nearby

JC  
Jason Loh  
Ben Poh

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

MCF  
HANGOUT

Das WeltAuto.

Exclusive pre-owned car guide session.  
Child seat tutorial. Kids activities.

15 February 2020 | 11 am

stream

Price Range ▾

Depreciation ▾

&gt; 10 year(s) ▾

Vehicle Type ▾



Home » Used Cars » CarQuotz Singapore » Honda Stream 1.8A (COE till 02/2022)

## Honda Stream 1.8A (COE till 02/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

CARQUOTZ *Nothing without Solution*

Price \$17,998

Depreciation ① \$8,720 /yr

Reg Date 15-Feb-2007  
(2yrs 22days COE left)

Mileage 144,089 km (11.1k /yr)

Manufactured ③ 2006

Road Tax ② \$1,271 /yr

Transmission Auto

Dereg Value ① \$10,744 as of today (change)

OMV ① \$16,422

COE ② \$26,039

ARF ② \$18,065

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight ① 1,350 kg

No. of Owners ① 4

Type of Vehicle MPV

## Features

Powerful Yet Reliable 1.8L SOHC 16V I-VTEC Engine, Smooth 5 Speed Auto Transmission, ABS, Airbags, Digital Climatic Aircon. View specs of the Honda Stream (2005-2007)

## Accessories

Auto Climatic Aircon, Leather Seats, Sports Rims, Reverse Sensors And Camera, UV Films, Knockdown Rear Seats, Steering Control.

## Description

Drive With Assurance With 5 Star Reviews! Warranty Till 1/2021, Genuine And Transparent Deal! Flexible Bank/In-house Up To 100% Loan Monthly \$849, Selling At The Most Reasonable Price With A Peace Of Mind! STA Inspection Are Welcome! Fully Refurbished! New 2k Premium Paintwork/Customize Leather Seat! View To Believe! | y 10AM To 9PM, Visit Us For A Test Drive Today!

Compare

[https://www.sgcarmart.com/used\\_cars/info.php?ID=880927&DL=3382](https://www.sgcarmart.com/used_cars/info.php?ID=880927&DL=3382)

Location Map

Shortlist

Compare

Report Error

More

## Seller Information

CarQuotz Singapore

Customer Review

5.0 ★★★★★

CarQuotz recommended

Hamizan S

1/3

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 361D

**Vehicle Details**

Vehicle No.: SLK9383K

Vehicle to be Exported: No

Intended Deregistration Date: 23 Jan 2020

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8 A

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: R18A1726406

Chassis No.: RN61023358

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$17,738.00

Original Registration Date: 16 Feb 2007

First Registration Date: 16 Feb 2007

Transfer Count: 3

Actual ARF Paid: \$19,512.00

**Intended PARF Rebate Details**

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 15 Feb 2022

COE Category: B - Car (1601cc &amp; above)

COE Period(Years): 5

PQP Paid: \$26,039.00

COE Rebate Amount: \$10,760.00

**Total Rebate Amount: \$10,760.00****Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Jan 2020

OK

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2978/01/20

Your Ref:

Date: 21st JAN 2020

QAMARUL AZHAR BIN AHMAD KAMIL  
BLK 744, WOODLANDS CIRCLE, #06-772  
SINGAPORE 730744

Estimate cost of repair to HONDA STREAM 1.8 (A) LA S/Wgn - SLK 9383 K

|  |             |            |        |
|--|-------------|------------|--------|
| 1 pc front bonnet                                      | Buy/Bus     | \$ 638.90  | ✓      |
| 8 pcs front bonnet inner seal clips                    | @ \$ 5.90   | 11 47.20   | X      |
| 2 pos o/s & n/s head lamp assy                         | @ \$ 791.20 | 1 1,582.00 | ✓      |
| 2 pos o/s & n/s head lamp lower bracket                | @ \$ 50.70  | one 101.40 | ✓      |
| 1 pc front grille                                      | one         | 254.20     | ✓      |
| 1 pc front grille top chrome moulding                  | scr         | 296.70     | ✓      |
| 1 pc front grille 'H' emblem                           | one         | 25.90      | ✓      |
| 6 pcs front grille clips                               | @ \$ 3.90   | 11 23.40   | X      |
| 1 pc front bumper                                      | Buy/Bus     | 635.60     | ✓      |
| 1 pc front bumper reinforcement                        | Buy         | 239.70     | ✓      |
| 2 pcs front bumper o/s & n/s side retainer             | @ \$ 34.80  | Buy 69.60  | ✓      |
| 16 pcs front bumper top & low clips                    | @ \$ 3.90   | one 62.40  | 35     |
| 2 pcs front bumper o/s & n/s top retainer              | @ \$ 25.40  | 11 50.80   | X      |
| 2 pcs front bumper o/s & n/s side bracket clips        | @ \$ 5.90   | 11 11.80   | X      |
| 1 pc front bumper centre lower air scoop grille        | 11          | 98.80      | X      |
| 1 pc front bumper sponge damper                        | 11          | 68.00      | X      |
| 1 pc front number plate & frame                        | one         | 60.00      | 405.~  |
| 8 pcs front support panel top garnish cover clips      | @ \$ 3.90   | 11 31.20   | X      |
| 1 pc tail gate door                                    | Buy/Bus     | 1,063.90   | ✓      |
| 1 pc tail gate door 'STREAM' emblem                    | one         | 34.70      | ✓      |
| 1 pc tail gate door 'H' emblem                         | 11          | 23.90      | X      |
| 1 pc rear number plate & frame                         | one         | 60.00      | X      |
| 1 pc tail gate door inner trim board cover             | 11          | 163.90     | X      |
| 16 pcs tail gate door inner trim board clips           | @ \$ 5.90   | 11 94.40   | X      |
| 1 pc tail gate door inner handle garnish               | 11          | 29.30      | X      |
| 1 pc tail gate door inner lock                         | Buy/Bus     | 119.80     | ✓      |
| 1 pc tail gate door lock stricker                      | 11          | 28.50      | X      |
| 1 pc tail gate door rear windscreen glass top moulding | one         | 36.70      | ✓      |
| 1 pc tail gate door rear windscreen lower moulding     | one         | 45.60      | ✓      |
| 2 pcs tail gate door windscreen o/s & n/s moulding     | @ \$ 34.30  | one 68.60  | ✓      |
| 1 pc tail gate door windscreen inner damper rubber     | one         | 45.00      | ✓      |
| 1 pc rear windscreen sealant                           | one         | 60.00      | 405.~  |
| 1 pc rear bumper                                       | Buy/Bus     | 678.20     | ✓      |
| 16 pcs rear bumper top & low clips                     | @ \$ 3.90   | one 62.40  | 35     |
| 2 pcs rear bumper o/s & n/s sponge damper              | @ \$ 28.00  | 11 56.00   | X      |
| 2 pcs rear bumper o/s & n/s side retainer              | @ \$ 26.40  | Buy 52.80  | ✓      |
| 2 pcs rear bumper o/s & n/s side bracket               | @ \$ 13.60  | 11 27.20   | X      |
| 1 pc rear bumper tow bar cover                         | one         | 24.80      | ✓      |
| 2 pcs rear bumper o/s & n/s tow bar bracket            | @ \$ 99.90  | 11 199.80  | X      |
| 1 set rear bumper reverse sensor                       | Buy/Bus     | 287.80     | 2805.~ |
| 1 pc tail gate door weatherstrip                       | one         | 143.20     | X      |
| 1 pc n/s tail lamp assy                                | one         | 409.80     | ✓      |
| 1 pc rear end panel                                    | Buy/Bus     | 333.10     | ✓      |
| 1 pc rear end panel top garnish                        | one         | 135.60     | ✓      |
| 6 pcs rear end panel top garnish clips                 | @ \$ 4.50   | 11 27.00   | X      |

\$ 8,610.00

Balance C/P..... 6777.7



# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2978/01/20

Your Ref:

Date: 21st JAN 2020

QAMARUL AZHAR BIN AHMAD KAMIL.,

Balance B/P.....\$ 8,610.00

- 1 pc spare tyre carrier
- 1 pc spare tyre carrier lock
- 1 pc rear floor board panel
- 1 pc n/s floor board cover
- 1 pc rear floor board panel insulator

11 153.20X  
11 27.60X  
11 1,145.30X  
11 168.80X  
11 142.70X

\$ 10,247.60  
Less 20% \$ 2,049.52  
\$ 8,198.08

To wiring check up & adjust headlight alignment, including front & rear wiring system & transfer rear wiring system into new tail gate door.

70.00 30

To remove & refix rear windscreen glass & necessary parts.

150.00 120

To transfer tail gate door inner trim board cover, lock, hinge, shock absorber, wiper motor, third brake light, licence garnish, spoiler & necessary parts.

180.00 60

To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, spare tyre, carrier & necessary parts.

150.00 80

To jack, straighten & knocking out rear exhaust & tail pipe.

11 120.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, rear n/s fender, rear floor board panel & necessary parts, to weld, renew & align above parts.

2,700.00 1200

To respray Tuff-Kote on all affected accident parts.

180.00 100

To putty & respray painting on all affected accident parts.

2,900.00 1800

\$ 4,648.08

Dollars : Forteen Thousand Six Mundred Forty Eight And Cents Eight Only.

8092.7

HUP MOTOR TRADING & SERVICE

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Tuesday, 4 February 2020 10:38 AM  
**To:** 'David Ang'  
**Cc:** CS A Team; Marcus Chua (LKKAuto); assignments; Admin A  
**Subject:** RE: RE : ACCIDENT ON : 21/01/2020, INVOLVING CLIENT'S (SLK 9383 K) & THIRD PARTY (SGE 5899 G, CHINA TAIPING INSURED) & OTHER : SHA 2616 K, ALONG A.Y.E.TWDS KEPPEL

### Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

*"Wishing you a Happy and Prosperous New Year"*



Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** David Ang <hupmotor@gmail.com>

**Sent:** Friday, 31 January 2020 12:11 PM



**To:** Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

**Cc:** CS A Team <cs-a@lkkauto.com>; Marcus Chua (LKKAUTO) <MarcusChua@lkkauto.com>; assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>

**Subject:** Re: RE : ACCIDENT ON : 21/01/2020, INVOLVING CLIENT'S (SLK 9383 K) & THIRD PARTY (SGE 5899 G, CHINA TAIPING INSURED) & OTHER : SHA 2616 K, ALONG A.Y.E.TWDS KEPPEL

Dear Hsiao Tong,

We attach the accident vehicle involved screen photo for your reference & attention, from our client's vehicle front & rear portion damaged, can see the rear portion was serious damaged, due to the strong impact causing client's vehicle to hit on the infront taxi, base on the impact, causing client's had more than 4 days MC, forcing client's had to log the police report,

Any way, Traffic Police will be handle this case & our client's solicitors will be assist for his property claims & injury claims soonest, Please let us hear from yours & insured of SGE 5899 G soonest, (by 14 days) Failing, client's will appoint solicitors to handle the claims.

On Thu, 30 Jan 2020 at 17:15, Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

**Without Prejudice**

Dear Sirs/Mdm,

Attached is a copy of our insured accident statement for your easy reference. Our insured reported that your client had hit onto the taxi before our insured hit onto your client vehicle.

Our respective handler, Asher will look into matter and get back to you.

Thank you.

*"Wishing you a Happy and Prosperous New Year"*



Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** David Ang <[hupmotor@gmail.com](mailto:hupmotor@gmail.com)>

**Sent:** Thursday, 30 January 2020 11:36 AM

**To:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Cc:** CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Marcus Chua (LKKAuto) <[MarcusChua@lkkauto.com](mailto:MarcusChua@lkkauto.com)>

**Subject:** Re: RE : ACCIDENT ON : 21/01/2020, INVOLVING CLIENT'S (SLK 9383 K) & THIRD PARTY (SGE 5899 G, CHINA TAIPING INSURED) & OTHER : SHA 2616 K, ALONG A.Y.E.TWDS KEPPEL

Dear Sirs,

Any update for us, as client's & his solicitors (handing injury claims) are chasing,

On Wed, 29 Jan 2020 at 13:59, David Ang <[hupmotor@gmail.com](mailto:hupmotor@gmail.com)> wrote:

Dear Sirs,

Upon today, we are still waiting for yours reply for direct settlement, Please revert & confirm the liability, reference & OIC,

On Wed, 22 Jan 2020 at 19:20, David Ang <[hupmotor@gmail.com](mailto:hupmotor@gmail.com)> wrote:

Dear Sirs,

Attach our estimate bill, GIA third party insurer search fee, Client's GIA report, Police report, insurance certificate & log card for your reference & attention,

We had assign your in-house surveyor (Mr Marcus Chua) to survey client's damaged vehicle on today,

Kindly revert & confirm client's third party property claims liability, reference & OIC, as we are looking for direct settlement,

Best Regards  
David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service  
Blk 9004 Tampines St 93  
#01-120  
Singapore 528838

Best Regards  
David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service  
Blk 9004 Tampines St 93  
#01-120  
Singapore 528838

Best Regards  
David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service  
Blk 9004 Tampines St 93  
#01-120  
Singapore 528838

Best Regards  
David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service  
Blk 9004 Tampines St 93  
#01-120  
Singapore 528838

## Mei Kwan (LKKAUTO)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Thursday, 23 January, 2020 11:17 AM  
**To:** Irene Tay; Mei Kwan (LKKAUTO); Asher Sng (LKKAUTO)  
**Cc:** Claims Dept of CTI  
**Subject:** OUR REF : SNM20D200460/SGE5899G/IRENE - Accident Involving SGE5899G (OI : CTI REF - TBA) AND SLK9383K (TP : LKK REF - CC6/CTI20001331/Uea3) on 20/01/2020  
**Attachments:** TP ESTIMATE + TP GIA REPORT-.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Irene,

Please revert LKK.

Note : officer in charge – Irene Tay 63896192

**\*\*\* Kindly quote our reference number when replying.**

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>  
**Sent:** Thursday, January 23, 2020 10:46 AM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Cc:** Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving SGE5899G (OI : CTI REF - TBA) AND SLK9383K (TP : LKK REF - CC6/CTI20001331/Uea3) on 20/01/2020

Dear Sir / Madam,

We refer to the above matter.

We have received a new assignment from M/s Hup Motor Trading & Service - Tampines and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-20-012458

Date of Request: 21/01/2020

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 21/01/2020  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. SGE5899G  
Accident Date 21/01/2020

**Enquiry Result**

| TP Vehicle No. | Insurer                                       | Period of Insurance   | Insurer Tel. No. |
|----------------|---|-----------------------|------------------|
| SGE5899G       | China Taiping Insurance (Singapore) Pte. Ltd. | 31/03/2019-31/03/2020 | 6389 6111        |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-20-012458

Date of Request: 21/01/2020

Your Ref No: Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 21/01/2020  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. SGE5899G  
Accident Date 21/01/2020

| DESCRIPTION                      | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry               | 1.87         |
| GST Amount                       | 0.13         |
| Total Amount Due (GST Inclusive) | 2.00         |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |   |                              |            |  |
|---|---|------------------------------|------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD   |   | Ref : CC6/CTI20001331/Uea3n2 |            |  |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909   |   | Date : 13-03-2020            |            |  |
|   |   | Code : CTI                   |            |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |   |                              |            |  |
| Insured Veh.  | SGE 5899G   | Veh. Inspected               | SLK 9383K  |  |
| Policy No.  | DMPCSN1913611900  | Coverage (\$)                | 0.00       |  |
| Claim No.   | SNM20D200460  | Excess (\$)                  | 0.00       |  |
| Assign From   |   | Assign Date                  | 22/01/2020 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>   |   |                              |            |  |
| Make & Model  | HONDA STREAM (A)  | c.c                          | 1799       |  |
| Engine No.  | HIDDEN  | Year of Reg.                 | 2007       |  |
| Chassis No.   | RN61023358  | Colour                       | BLACK      |  |
| Odometer  | 237915  | Steering                     | IN ORDER   |  |
| Brakes  | IN ORDER  | Modification                 | SPORTS RIM |  |
| General   | GOOD  |                              |            |  |
| <b>3. Conditions of Tyres</b>   |   |                              |            |  |
|   | Size  | Make                         | Balance    |  |
| R/H Front Tyre  | 215/45 ZR17   | DUNLOP                       | 6 mm       |  |
| L/H Front Tyre  | 215/45 ZR17   | DUNLOP                       | 6 mm       |  |
| R/H Rear Tyre   | 215/45 ZR17   | DUNLOP                       | 6 mm       |  |
| L/H Rear Tyre   | 215/45 ZR17   | DUNLOP                       | 6 mm       |  |
| <b>4. Description of Damages</b>  |   |                              |            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.<br>DAMAGES SEE DETAILS.  |   |                              |            |  |
| <b>5. General Information</b>   |   |                              |            |  |
| Accident Date   | 21/01/2020  | Inspection Date              | 22/01/2020 |  |
| Survey held at  | HUP MOTOR TRADING & SERVICE<br>BLK 9004 TAMPINES ST 93<br>#01-120<br>SINGAPORE 528838 |                              |            |  |
| <b>5a. Remarks</b>  |   |                              |            |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                              |            |  |
| <b>5b. Estimate Days of Repair</b>  |   |                              |            |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:   |   | 11 Working Days              |            |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 9383K

| Qty | Description of Parts                                | Condition         | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                         |                   |                           |                   |
| 1   | FRONT BONNET  | BENT / BUCKLED    | 638.90                    | 638.90            |
| 8   | FRONT BONNET INNER SEAL CLIPS @\$5.90               | NOT NECESSARY     | 47.20                     | -                 |
| 2   | O/S & N/S HEAD LAMP ASSY @\$791.20                  | CRACKED           | 1,582.40                  | 1,582.00          |
| 2   | O/S & N/S HEAD LAMP LOWER BRACKET @\$50.70          | CRACKED           | 101.40                    | 101.40            |
| 1   | FRONT GRILLE  | CRACKED           | 254.20                    | 254.20            |
| 1   | FRONT GRILLE TOP CHROME MOULDING                    | SCRATCHED         | 296.70                    | 296.70            |
| 1   | FRONT GRILLE "H" EMBLEM                             | NECESSARY         | 25.90                     | 25.90             |
| 6   | FRONT GRILLE CLIPS @\$3.90                          | NOT NECESSARY     | 23.40                     | -                 |
| 1   | FRONT BUMPER  | DENTED / DEFORMED | 635.60                    | 635.60            |
| 1   | FRONT BUMPER REINFORCEMENT                          | BENT              | 239.70                    | 239.70            |
| 2   | FRONT BUMPER O/S & N/S SIDE RETAINER @\$34.80       | BENT              | 69.60                     | 69.60             |
| 16  | FRONT BUMPER TOP & LOW CLIPS @\$3.90                | NECESSARY         | 62.40                     | 35.00             |
| 2   | FRONT BUMPER O/S & N/S TOP RETAINER @\$25.40        | NOT NECESSARY     | 50.80                     | -                 |
| 2   | FRONT BUMPER O/S & N/S SIDE BRACKET CLIPS @\$5.90   | NOT NECESSARY     | 11.80                     | -                 |
| 1   | FRONT BUMPER CENTRE LOWER AIRSCOOP GRILLE           | NOT NECESSARY     | 98.80                     | -                 |
| 1   | FRONT BUMPER SPONGE DAMPER                          | NOT NECESSARY     | 68.00                     | -                 |
| 8   | FRONT SUPPORT PANEL TOP GARNISH COVER CLIPS @\$3.90 | NOT NECESSARY     | 31.20                     | -                 |
| 1   | TAIL GATE DOOR                                      | BADLY DENTED      | 1,063.90                  | 903.20            |
| 1   | TAIL GATE DOOR "STREAM" EMBLEM                      | NECESSARY         | 34.70                     | 34.70             |
| 1   | TAIL GATE DOOR "H" EMBLEM                           | NOT NECESSARY     | 23.90                     | -                 |
| 1   | REAR NUMBER PLATE & FRAME                           | SERVICEABLE       | 60.00                     | -                 |
| 1   | TAIL GATE DOOR INNER TRIM BOARD COVER               | NOT NECESSARY     | 163.90                    | -                 |
| 16  | TAIL GATE DOOR INNER TRIM BOARD CLIPS @\$5.90       | NOT NECESSARY     | 94.40                     | -                 |
| 1   | TAIL GATE DOOR INNER HANDLE GARNISH                 | NOT NECESSARY     | 29.30                     | -                 |
| 1   | TAIL GATE DOOR INNER LOCK                           | DENTED / JAMMED   | 119.80                    | 119.80            |
| 1   | TAIL GATE DOOR LOCK STRICKER                        | NOT NECESSARY     | 28.50                     | -                 |
| 1   | TAIL GATE DOOR REAR WINDSCREEN GLASS TOP MOULDING   | NECESSARY         | 36.70                     | 36.70             |
| 1   | TAIL GATE DOOR REAR WINDSCREEN LOWER MOULDING       | NECESSARY         | 45.60                     | 45.60             |

Report Ref No. CC6/CTI20001331/Uea3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| 2   | TAIL GATE DOOR WINDSCREEN O/S & N/S MOULDING @\$34.30 | NECESSARY            | 68.60                     | 68.60             |
| 1   | TAIL GATE DOOR WINDSCREEN INNER DAMPER RUBBER         | NECESSARY            | 45.00                     | 45.00             |
| 1   | REAR BUMPER   | DISTORTED            | 678.20                    | 654.00            |
| 16  | REAR BUMPER TOP & LOW CLIPS @\$3.90                   | NECESSARY            | 62.40                     | 35.00             |
| 2   | REAR BUMPER O/S & N/S SPONGE DAMPER @\$28.00          | NO SUCH PARTS        | 56.00                     | -                 |
| 2   | REAR BUMPER O/S & N/S SIDE RETAINER @\$26.40          | BENT                 | 52.80                     | 52.80             |
| 2   | REAR BUMPER O/S & N/S SIDE BRACKET @\$13.60           | NOT NECESSARY        | 27.20                     | -                 |
| 1   | REAR BUMPER TOW BAR COVER                             | TORN                 | 24.80                     | 24.80             |
| 2   | REAR BUMPER O/S & N/S TOW BAR BRACKET @\$99.90        | NOT NECESSARY        | 199.80                    | -                 |
| 1   | TAIL GATE DOOR WEATHERSTRIP                           | SERVICEABLE          | 143.20                    | -                 |
| 1   | N/S TAIL LAMP ASSY                                    | CRACKED              | 409.80                    | 409.80            |
| 1   | REAR END PANEL  | BADLY DENTED         | 333.10                    | 333.10            |
| 1   | REAR END PANEL TOP GARNISH                            | TWISTED              | 135.60                    | 135.60            |
| 6   | REAR END PANEL TOP GARNISH CLIPS @\$4.50              | NOT NECESSARY        | 27.00                     | -                 |
| 1   | SPARE TYRE CARRIER                                    | NOT NECESSARY        | 153.20                    | -                 |
| 1   | SPARE TYRE CARRIER LOCK                               | NOT NECESSARY        | 27.60                     | -                 |
| 1   | REAR FLOOR BOARD PANEL                                | TO REPAIR SEE LABOUR | 1,145.30                  | -                 |
| 1   | N/S FLOOR BOARD COVER                                 | NOT NECESSARY        | 168.80                    | -                 |
| 1   | REAR FLOOR BOARD PANEL INSULATOR                      | NOT NECESSARY        | 142.70                    | -                 |
|     | LESS 20% DISCOUNT                                     |                      | -1,967.96                 | -1,355.54         |
|     |   |                      | 7,871.84                  | 5,422.16          |
| 1   | FRONT NUMBER PLATE & FRAME (SN)                       | CRACKED              | 60.00                     | 40.00             |
| 1   | REAR WINDSCREEN SEALANT (SN)                          | NECESSARY            | 60.00                     | 40.00             |
| 1   | SET REAR BUMPER REVERSE SENSOR (SN)                   | SHORTED              | 287.80                    | 200.00            |
|     | LESS 20% DISCOUNT                                     |                      | -81.56                    | -                 |
|     |   |                      | 326.24                    | 280.00            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
|     | <b>LABOUR</b>   |               |                           |                   |
|     | TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT,INCLUDING FRONT & REAR WIRING SYSTEM & TRANSFER REAR WIRING SYSTEM INTO NEW TAIL GATE DOOR.   |               | 70.00                     | 30.00             |
|     | TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS.  |               | 150.00                    | 120.00            |
|     | TO TRANSFER TAIL GATE DOOR INNER TRIM BOARD COVER,LOCK,HINGE,SHOCK ABSORBER,WIPER MOTOR,THIRD BRAKE LIGHT,LICENCE GARNISH,SPOILER & NECESSARY PARTS.  |               | 180.00                    | 60.00             |
|     | TO REMOVE & REFIX REAR CUSHION SEAT,CARPET,FLOOR MAT,GARNISH,FLOOR BOARD COVER,SPARE TYRE,CARRIER & NECESSARY PARTS.  |               | 150.00                    | 80.00             |
|     | TO JACK,STRAIGHTEN & KNOCKING OUT REAR EXHAUST & TAIL PIPE.   | NOT NECESSARY | 120.00                    | -                 |
|     | LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT FRONT SUPPORT PANEL,REAR N/S FENDER,REAR FLOOR BOARD PANEL & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS. |               | 2,700.00                  | 1,200.00          |
|     | TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.  |               | 180.00                    | 100.00            |
|     | TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.   |               | 2,900.00                  | 1,800.00          |
|     |   |               | 6,450.00                  | 3,390.00          |
|     | <b>GRAND TOTAL</b>  |               | <b>14,648.08</b>          | <b>9,092.16</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>   |               |                           | <b>7,200.00</b>   |

Report Ref No. CC6/CTI20001331/Uea3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.