

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.01.2020

Time: 12:21:15

Page: 1

Like

CHINA

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305375522
 REGN NO : SHC8017P
 MILEAGE : 0000000000
 MAKE : MERCEDES BENZ
 MODEL : E220CDI(E6)
 DATE OF REGN : 13.05.2015
 DATE/TIME IN : 18.01.2020 08:15
 ACCIDENT DATE : 18.01.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-2282-G	212VB REAR BUMPER ASSY	1 L	1,510.00	20.00	1,208.00	cra	
0002 04-01-0202-0740-G	212VC REAR BUMPER REINFOR	1 L	722.87	20.00	578.30	xnn	
0003 04-01-0202-2283-G	212VB REAR BUMPER LOWER C	1 L	325.00	20.00	260.00	xnn xnn	
0004 04-01-0202-3886-G	212VB BUMPER BRACKET RR/L	1 L	135.00	20.00	108.00	xnn Br	
0005 04-01-0202-3986-G	212VB BUMPER BRACKET RR/R	1 L	135.00	20.00	108.00	xnn Br	1,645 +? 135
0006 09-01-0299-2005-A	(212/211B) REVERSE SENSOR	1 N	388.00	2.00	388.00	xnn	1,780 -20%
0007 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	0.20	50.00	wec	
						SUB-TOTAL :	2,700.30 + 50 Net 1,474
0000 L	PANEL BEATING (repair Bootlid alignment out)				500.00	\$460	
0001 23-502	SPRAYPAINT ON AFFECTED AREA				300.00	\$200	
0002 20-22	REMOVE/REFIX REVERSE SENSOR				120.00	\$80	740
						SUB-TOTAL :	920.00 2214 -20% 1,731.20

Ravi (LKR)

20/1/2020 1300hrs

Ravasanm@lkrauto.com

88622778 (LIS)

aft repair photo.

#1,750

(3) 3x 4x 5x 6x 7x 8x 9x 10x 11x 12x 13x 14x 15x 16x 17x 18x 19x 20x 21x 22x 23x 24x 25x 26x 27x 28x 29x 30x 31x 32x 33x 34x 35x 36x 37x 38x 39x 40x 41x 42x 43x 44x 45x 46x 47x 48x 49x 50x 51x 52x 53x 54x 55x 56x 57x 58x 59x 60x 61x 62x 63x 64x 65x 66x 67x 68x 69x 70x 71x 72x 73x 74x 75x 76x 77x 78x 79x 80x 81x 82x 83x 84x 85x 86x 87x 88x 89x 90x 91x 92x 93x 94x 95x 96x 97x 98x 99x 100x