

Surveyor

REF: CS1 / LAW 2000 1344 / Eq d302

Special Instruction: HS: \$3350-00

ASSIGNMENT (Office)

From (Person): Jaslin Wong Thomas & Leong Date/Time: 22/01/2020

Third Parties: Claimant: Surveyor: Oh Appraisal Workshop: Hua chin (2000)

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FU1852U Insured: JSK 7438 at Workshop m/s Hua chin (2000) Tel: 6896 6619 of 50 Bukit Batok street 23 #02-02 Policy No: Claim No: CPW/jc/1904010 Sum Insured: Excess: Make of Veh: D.O.A. 25/12/2017 (Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT Date/Time: Confirmed with Final Fig, days (Red \$ / %; Original 5 days) Date/Time: 30/01/20 Submit Final Fig \$2,950/2, 4 days (Red \$ 1300 / 39 %; Original 5 days)

Table with 2 columns: Date/Time, Action/Instruction. Includes handwritten entries for FU1852U-X and JSK 7438-X, and a signature dated 30/1/2020.

RECEIVED 30 JAN 2020

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : Salvage Value : Nett Value :

Inspected/ Evaluated by:

Fee Charged: Basic & Add Transport Photos Others Total

Table for Fee Charged with Date: 300 and Total: 300.

- 1) Date/Time 30/1/20 File Pass to t/m... 2) Date/Time File Return to 3) Date/Time File Pass to 4) Date/Time File Return to 5) Date/Time File Pass to 6) Date/Time File Return to

Nivitha (LKK Auto)

From: CPW <cpw@wongthomasleong.com.sg>
Sent: Wednesday, 22 January 2020 3:05 PM
To: assignments@lkkauto.com
Subject: Our Ref: CPW/jc/1904010 - MC/MC 5234/2018
Attachments: police report-FU 1852U.pdf; police report-JSK 7438.pdf; Certificate of Insurance.pdf; repair bill.pdf; survey report by Oh Appraisal.pdf

Dear Sirs

**Accident on 25 December 2017 involving FU 1852U and JSK 7438 along Tuas South Avenue 7
Case No: MC/MC 5234/2018**

1. We act for Zurich General Insurance Malaysia Berhad, the insurers of motorcycle No JSK 7438.
2. Our clients' insured is the defendant in the above suit commenced by the owner/rider of motorcycle No FU 1852U. Our clients would like to appoint you to conduct a paper survey of the plaintiff's motorcycle No FU 1852U.
3. We attach herewith the following for your attention and necessary action:-
 - a. police report by the rider of motorcycle No FU 1852U.
 - b. police report by the rider of motorcycle No JSK 7438.
 - c. Certificate of Insurance for vehicle No FU 1852U.
 - d. Repairer' Invoice No 1300.
 - e. Surveyor's Invoice No 2018/0004 and report together with 13 pages of coloured photographs.
4. Kindly let us have your report **as soon as possible**. Thank you.


Regards
Jaslin (secretary to Ms Chong)
Wong Thomas & Leong
133 New Bridge Road #10-01
Chinatown Point
Singapore 059413
DID: 6231 0292

OH APPRAISAL SERVICESBLK 34,#02-309,TOA PAYOH,LORONG 5
SINGAPORE (310034)Mobile : 97982959 Fax : 63975857 email : oh3434@yahoo.com.sg
Business Regn No 53214975X

INVOICE

Mr. Teo Bong Hui
C/O Goh JP & Wong Advocates &
Solicitors
133 New Bridge Road #16-09
Chinatown Point (S) 059413Invoice No :2018/0004
Our Ref :FU1852U/TP5004
Date :08 January 2018

Claim Type	Third Party	Date of Accident	25-12-2017
Vehicle No.	FU1852U	Date of Inspection	03-01-2018
No	Description		Amount (S\$)
1	Survey fees inclusive of Transportation and Photographs (51) copies		
		Total	411.00
Singapore Dollar: Four Hundred and Eleven Dollars			
All payments made payable to : Oh Appraisal Services			



For Oh Appraisal Services

INVOICE

No: 1300



樺志摩哆服務中心 HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE

50, Bukit Batok Street 23, #02-02 Midview Building Singapore 659578

Tel: 6896 6619 Fax: 6267 8616

Co Reg. No. 52923612E

Importers & Exporters of Motor Cycle Spare Parts and Accessories

M

GOH JP & WONG LLC /
TEO BONG HUI

賣號
先生

日期
Date

16/1/2018

數量 Quantity	貨名 Particulars	單 Rate \$	價 ¢	銀 Amount \$	額 ¢
	LUMP SUM REPAIR BILL FOR FU18524			3,350	00

PLEASE RECEIVE IN GOOD ORDER AND CONDITION THE ABOVE ITEMS
GOODS SUPPLIED ARE NOT RETURNABLE

貨物出門，一概不準退換

總共
TOTAL \$

3,350 00

客戶簽名與公司印章

Customer's Signature & Company Stamp

樺志摩哆服務中心

HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE



ORIGINAL COPY

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5092752241 **Cover** : Third Party

- | | |
|---|----------------|
| 1. Index mark and Registration Number of Vehicle | : FU1852U |
| Chassis Number | : TA2000005009 |
| 2. Name of Policyholder | : TEO BONG HUI |
| 3. Effective Date of Insurance | : 18 Jul 2017 |
| 4. Expiry Date of Insurance | : 17 Jul 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) Named Driver(s) Only. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |
| This Policy does not cover | |
| (a) Use for hire or reward. | |
| (b) Use for racing, pace-making, reliability trial or speed-testing. | |
| (c) Use for the carriage of goods (other than samples) in connection with any trade or business. | |
| (d) Use for any purpose in connection with the Motor Trade. | |

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: TEO BONG HUI
NAMED DRIVER (2)	: LAI PHOOI YEE
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : COMMERCIAL AGENCY PTE LTD (00000614425)
Date of Issue : 18 Jul 2017 10:04 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Authorized Officer



Chief Executive

Countersigned By:





**SINGAPORE
POLICE FORCE**



T/20171226/2035

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

1 of 3

Report No. T/20171226/2035

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/12/2017 10:34		Vide Report No.:	Station Diary No.: 42
Informant's Particulars			
Name of Informant: TEO BONG HUI		Address: C/O 101 UPP CROSS STREET #02-40/41 SINGAPORE 058357	
ID Type / ID No.: FIN NO / G0260176T		Contact No.:	Mobile: 98918228
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 52	Date of Birth: 31/05/1965	Type of Informant: Rider
Race: Chinese		Language:	Institution / School Name:
Occupation: Bus driver		Driving Licence Information: Class: 2B,3,4A	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/12/2017 15:50	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 TUAS SOUTH AVENUE 7 PAN ISLAND EXPRESSWAY After a bus stop				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear		Certified True Copy pursuant to Sec. 78 of the Evidence Act, Cap 97. Yee Hwee Choo CSO Traffic Police Date: 22 FEB 2018		Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FU1852U	Motorcycle	HONDA	TA200	Green	Slightly Damaged	0
JSK7438	Motorcycle				Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
FU1852U	NTUC Income Insurance Co-Operative Limited	5092752241	18/07/2017	17/07/2018



**SINGAPORE
POLICE FORCE**



T/20171226/2035

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20171226/2035

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TEO BONG HUI	ID No.	G0260176T
Related Vehicle	FU1852U (Motorcycle)	Contact No.	98918228
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3,4A Date of Expiry: NIL
Date Treatment	26/12/2017	Date Discharge	26/12/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Rider			
Name	MUHAMMAD RAIZUAN BIN JA AFAR	ID No.	G2990587N
Related Vehicle	JSK7438 (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 25/12/2017 at about 1550hrs, I was riding V1) FU1852U, travelling along Tuas South Ave 7, a three lane road, exiting the premises of Tuas when V2) JSK7438, suddenly banged into V1, causing a hard collision. Subsequently, I fall towards my right side together with V1. V1 landed on the left most lane while V2 landed on the right most lane. I called my friend for help which he later called for the ambulance. Upon interviewing with the rider of AS1) Muhamad Raizuan Bin Ja Afar, he told me that he did saw me in front but he was riding at high speed. My injuries were there were cuts on my right wrist, left elbow, right knee, left upper lip, my right and left palm, and there are blue blacks markings on my left palm. I am not sure of AS1's injuries together with his pillion. V1 damages were the handlebar was slanted, the exhaust pipe and right rear signal light was broken, body of V1 was dented and the wires of the IU unit are spoilt. I am not sure of V2's damages. This is the first time such incident happen to me.

Certified True Copy
pursuant to Sec. 78 of the
Evidence Act, Cap 97.

.....
Yet Hwee Choo
CSO Traffic Police
Date :

22 FEB 2018



**SINGAPORE
POLICE FORCE**



T/20171226/2035

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20171226/2035

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / AHMAD ZAKI ZUHAIRI BIN AYUB
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Contact No.:

Signature Of Informant:
Date/Time: 26/12/2017 10:34
Classification Of Case:

~~Certified True Copy~~
pursuant to Sec. 78 of the
Evidence Act, Cap 97.

Authentication Stamp
NP168

.....
Yet Hwee Choo
CSO Traffic Police
Date :
22 FEB 2018



**SINGAPORE
POLICE FORCE**



T/20171226/2072

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 3

Report No. T/20171226/2072

CONTINUATION OF REPORT

Rider			
Name	MUHAMMAD SAIFUDDIN BIN JAAFAR	ID No.	G6992394T
Related Vehicle	JSK7438 (Motorcycle)	Contact No.	83076875
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Rider			
Name	Unknown Rider	ID No.	NIL
Related Vehicle	NIL	Contact No.	98918228
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 25/12/2017 at about 1600 hours, I was travelling along Tuas South Ave 7 on the middle lane with my pillion, namely
A1) Muhamad Raizuan Bin Jaafar

While I was travelling, there was a bike in front of me travelling slower than I was. I tried to apply brake before going too close to the rider in front of me but I was not able to stop in time. I hit the bike at the back and skidded to the lane on the right with my pillion. My bike is slightly damaged at the front. Ambulance and Police was called, however I was not convey by Ambulance to the hospital. I only able to get the contact number of the other party, HP number: 98918228. I was advised by the Paramedic to seek medical attention from clinic locally but I wish to go to Malaysia and seek medical attention. I am lodging this report for investigation purposes.

Certified True Copy
pursuant to Sec. 78 of the
Evidence Act, Cap 97.

.....
Yet Hwee Choo
CSO Traffic Police
Date : 22 FEB 2018



**SINGAPORE
POLICE FORCE**



T/20171226/2072

3 of 3

Report No. T/20171226/2072

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / SOE PAING ZAW
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT /
Contact No.:

Signature Of Informant:
Date/Time: 26/12/2017 13:51
Classification Of Case: Certified True Copy pursuant to Sec. 78 of the Evidence Act, Cap 97.

Authentication Stamp
NP168

.....
Yei Hwee Choo
CSO Traffic Police
Date: 22 FEB 2018

OH APPRAISAL SERVICES

BLK 34,#02-309,TOA PAYOH,LORONG 5
SINGAPORE (310034)

Mobile : 97982959 Fax : 63975857 email : oh3434@yahoo.com.sg
Business Regn No 53214975X

VEHICLE DAMAGE INSPECTION REPORT

Mr. Teo Bong Hui
101 Upper Cross Street
#02-40/41
Singapore 058357

Our Ref : FU1852U/TP5004
Date : 08 January 2018

REFERENCES

Claim Type	: Third Party	Date of Accident	: 25 December 2017
Vehicle No.	: FU1852U	Date of Assignment	: 03 January 2018
Make	: Honda	Date of Inspection	: 03 January 2018
Model	: TA 200	Date of Re-inspn.	: Nil
Reg. Date	: 27 November 2001	Chassis No	: TA2000005009
Color	: Black	Engine No	: Blocked
Odometer	: 08147 km		

TYRE CONDITION

	Make	Size	Thread Balance
Front	Metzeler	100/80-17	3
Rear	Metzeler	130/90-15	4

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

Front,Lh side and Rear portion

INSPECTION AND ADJUSTMENT

Original Quotation : \$5,211.30 Revised Assessment \$3,350.00 Lump sum

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
(5) days to complete.(Survey at Hua Chin (2000) Trading Motor Service Centre .)

This survey was conducted on a "WITHOUT PREJUDICE" basis.

S/N	Description	Qty	Condition	Original Quotation	Revised Quotation
1	Handle bar	1 pc	Bent	55.00	55.00 ✓
2	Handle balancer	1 set	Grazed	36.00	36.00 ✓
3	Handle grip	1 set	Cut	28.00	28.00 X Svc
4	Brake lever	1 pc	Grazed	18.00	18.00 ✓
5	Mirror	1 pc	Grazed Rh	28.00	28.00 ✓
6	Head lamp assy	1 pc	Grazed	110.00	110.00 ✓
7	Front signal lamp @\$48.00	2 pcs	Grazed Rh	96.00	48.00 ✓
8	Front mudguard	1 pc	Grazed	48.00	48.00 ✓
9	Front fork assy @\$285.00	2 pcs	Align	570.00	S.N.200.00 ✓
10	Front fork emblem (fuel tank emblem)	1 pc	Grazed	48.00	48.00 ✓
11	Steering stem	1 pc	Distorted	185.00	185.00 X Svc
12	Front disc brake	1 pc	Usable	185.00	0.00 ✓
13	Fuel tank	1 pc	Dented	480.00	480.00 ✓
14	Fuel tank emblem @\$28.00	2 pcs	Necessary	56.00	56.00 ✓
15	Front foot rest	1 pc	Bent	45.00	45.00 ✓
16	Front footrest bracket	1 pc	Bent	65.00	65.00 ✓
17	Brake pedal	1 pc	Bent	42.00	42.00 ✓
18	Rear footrest	1 pc	Bent Rh	35.00	35.00 ✓
19	Rear footrest bracket	1 pc	Cracked Rh	68.00	68.00 ✓
20	Rear signal @\$48.00	2 pcs	Grazed Rh	96.00	48.00 ✓
21	Rear fender	1 pc	Grazed	145.00	145.00 X Svc
22	Rear mudguard stay	1 pc	Bent	55.00	55.00 X Svc
23	Tailamp	1 pc	Usable	65.00	0.00 ✓
24	Rear wheel rim	1 pc	Bent	250.00	250.00 X Svc
25	Rear brake disc	1 pc	Usable	185.00	0.00 ✓
26	Rear swing arm	1 pc	Bent	280.00	280.00 X Svc
27	Rear shock absorber @\$360.00	2 pcs	Bent	720.00	720.00 X Svc
28	Exhaust pipe guard	1 pc	Bent	38.00	38.00 ✓
29	Exhaust assy	1 pc	Dented	495.00	495.00 ✓
				4527.00	3426.00 1963
			Less 10% discount	452.70	342.60 -10%
				4074.30	3083.40 1766-70
	<u>Add special nett items</u>				200.00 X Svc
30	Number plate	1 set	Bent/cracked	22.00	22.00 X Svc
31	Steering cone & bearing	1 pc	Necessary	55.00	27.50 ✓
32	Rear box	1 pc	Grazed	300.00	280.00 ✓
33	Rear rack	1 pc	Bent	120.00	100.00 ✓
	Towing fee (Two ways)			60.00	50.00 ✓
	Rim alignment (Front)			100.00	60.00 30/
	Check electrical			80.00	60.00 30/
	Labour charges			400.00	350.00 300/
				5211.30	4232.90
	Lump sum repair adjustment				3350.00 817.50

P-1766-70
 (N+L)-817-50
 2584-20
 LIS-2067-36
 = 2050

4 repair days

OH APPRAISAL SERVICES

Vehicle No: FU1852U

Our Ref : FU1852U/TP5004

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



A handwritten signature in black ink, appearing to be "G. G." or similar, written over a horizontal line.

For Oh Appraisal Services



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: CPW/jc/1904010

Date: 30th Jan 2020

Our Ref: CS1/LAW20001344/Eqd3e2

M/s Wong Thomas & Leong
133 New Bridge Road #10-01
Chinatown Point
Singapore 059413

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FU 1852U
INSURED VEHICLE: JSK 7438
ACCIDENT DATE: 25/12/2017**

We thank you for your instruction on 22/01/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FU 1852U from M/s Oh Appraisal Services.
- b) Final Repair Bill of FU 1852Z from M/s Hua Chin (2000) Trading Motor Service Centre.
- c) Police Report of Vehicle FU 1852U and JSK 7438.
- d) Colour damaged vehicle photographs of FU 1852U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FU 1852U
Make & Model	: Honda TA 200
Chassis Number	: TA2000005009
Year of Registration	: 2001

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 1852U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR	BENT	55.00	55.00
1	SET HANDLE BALANCER	GRAZED	36.00	36.00
1	SET HANDLE GRIP	SERVICEABLE	28.00	-
1	BRAKE LEVER	GRAZED	18.00	18.00
1	MIRROR	O/S GRAZED	28.00	28.00
1	HEAD LAMP ASSY	GRAZED	110.00	110.00
2	FRONT SIGNAL LAMP @\$48.00	O/S GRAZED	96.00	48.00
1	FRONT MUDGUARD	GRAZED	48.00	48.00
1	FRONT FORK EMBLEM	GRAZED	48.00	48.00
1	STEERING STEM	SERVICEABLE	185.00	-
1	FRONT DISC BRAKE	USABLE	185.00	-
1	FUEL TANK	DENTED	480.00	480.00
2	FUEL TANK EMBLEM @\$28.00	NECESSARY	56.00	56.00
1	FRONT FOOT REST	BENT	45.00	45.00
1	FRONT FOOT REST BRACKET	BENT	65.00	65.00
1	BRAKE PEDAL	BENT	42.00	42.00
1	REAR FOOTREST	O/S BENT	35.00	35.00
1	REAR FOOTREST BRACKET	O/S CRACKED	68.00	68.00
2	REAR SIGNAL @\$48.00	O/S GRAZED	96.00	48.00
1	REAR FENDER	SERVICEABLE	145.00	-
1	REAR MUDGUARD STAY	SERVICEABLE	55.00	-
1	TAILLAMP	USABLE	65.00	-
1	REAR WHEEL RIM	SERVICEABLE	250.00	-
1	REAR BRAKE DISC	USABLE	185.00	-
1	REAR SWING ARM	SERVICEABLE	280.00	-
2	REAR SHOCK ABSORBER @\$360.00	SERVICEABLE	720.00	-
1	EXHAUST PIPE GUARD	BENT	38.00	38.00
1	EXHAUST ASSY	DENTED	495.00	495.00
	LESS 10% DISCOUNT		-395.70	-176.30
			3,561.30	1,586.70
2	FRONT FORK ASSY @\$285.00	ALIGN	570.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-57.00	-
			513.00	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	SERVICEABLE	22.00	-
1	STEERING CONE & BEARING (SN)	NECESSARY	55.00	27.50
1	REAR BOX (SN)	GRAZED	300.00	280.00
1	REAR RACK (SN)	BENT	120.00	100.00
			497.00	407.50
	<u>LABOUR</u>			
	TOWING FEE (TWO WAYS).		60.00	50.00
	RIM ALIGNMENT (FRONT).		100.00	30.00
	CHECK ELECTRICAL.		80.00	30.00
	LABOUR CHARGES.		400.00	300.00
			640.00	410.00
	GRAND TOTAL		5,211.30	2,604.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,050.00

Report Ref No. CS1/LAW20001344/Eqd3e2

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.