

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M**AAD2001-161***Not Authorized
1/1 Simp & 5000/3*

Vehicle No.:

Chassis No.:

Vehicle Make:

21 JAN 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 123M

VF1ABL15AUC282689

RENAULT

LATITUDE

18.1.2020

AIG

22-03-16

PART		LIST	
1	BUMPER COVER REAR	\$	<i>Bu</i> 561.70 ✓
1	BUMPER LOWER REAR	\$	<i>Ne</i> 411.90 ✓
1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10 X
1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10 X
1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80 X
1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60 X
1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80 X
1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20 X
1	BUMPER REFLECTOR LH	\$	<i>SL</i> 16.60 X
1	BUMPER BEAM REAR	\$	<i>Bu</i> 547.80 ✓
1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50 X
1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 100.90 X
1	OUTER PANEL REAR (End Panel)	\$	<i>Bu</i> 745.80 ✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>Ne</i> 404.56 ✓
1	TAILLAMP RH	\$	<i>SL</i> 313.10 X
1	TAILLAMP PANEL RH	\$	<i>R</i> 401.40 X
1	TAILLAMP LH	\$	<i>SL</i> 401.40 X
1	TAILLAMP PANEL LH	\$	<i>R</i> 401.40 X
1	BOOT REAR	\$	<i>Bu</i> 1,677.20 ✓
1	BOOT FINISHER	\$	<i>SL</i> 344.70 X
1	BOOT WHEATERSTRIP	\$	<i>SL</i> 178.20 X
1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70 X
1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70 X
1	BOOT BADGE 'RENAULT'	\$	<i>Ne</i> 82.40 ✓
1	BOOT BADGE	\$	<i>Ne</i> 95.80 ✓
1	BOOT STRUT LH	\$	<i>SL</i> 145.10 X
1	BOOT STRUT RH	\$	<i>SL</i> 145.10 X
1	BOOT HINGE LH	\$	<i>R</i> 254.20 X

Trans-cab Auto Services Pte Ltd**AAD2001-161**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M

1	BOOT HINGE RH	\$	R	253.80	}	X
2	BOOT RUBBER PLUG	\$	SL	139.90		
2	LICENCE PLATE LAMP	\$	SL	26.30		
1	BOOT LOCK LINKAGE	\$	SL	20.60		
1	BOOT LOCK LINKAGE HOLDER	\$	SL	99.50		
1	BOOT INNER TRIM BOARD	\$	SL	611.00		
1	BOOT SWITCH	\$	SL	113.00		
1	BOOT LOCK	\$	R	246.60		
1	BOOT LOCK CATCH	\$	R	41.70		
1	EXHAUST CAP REAR	\$	R	125.40		
1	EXHAUST REAR	\$	R	5,263.60		
1	SPARE WHEEL PANEL	\$	R	1,229.40		
1	SPARE TYRE BOARD	\$	SL	680.90		
1	SPARE WHEEL PANEL TRIM	\$	SL	612.21		

TOTAL	\$	17,754.67
10%	\$	1,775.47
	\$	15,979.20

Special Nett

1SET	PARKING AID	\$	Shan	700.00	400.00
1SET	REAR BUMPER CLIP	\$	na	66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	—
1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
1	BOOT STICKER "6555-3333"	\$	na	30.00	—
2	REAR WINDSCREEN SEALANT	\$	na	80.00	X
1	WINDSCREEN MOULDING	\$	na	100.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
1	BOOT INNER TRIM CLIP	\$	na	45.00	X
1SET	BOOT FINISHER CLIP	\$	na	24.20	X

1 TAILLAMP CLIP LH

\$ 5.00

Trans-cab Auto Services Pte Ltd

AAD2001-161

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M

1 TAILLAMP CLIP RH

\$ *nn* 5.00 X

1 Rear Bumper Protector

\$ *nn* 100.00 *405a*

1 EXHAUST MOUNTING REAR

\$ *nn* 16.00 X

1 EXHAUST BRACKET REAR

\$ *n* 24.80 X

1SET Rear licence plate with holder

\$ *src* 80.00 X

TOTAL \$ 1,587.00

TOTAL PARTS \$ 17,566.20

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 170.00 *601*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *601*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 7,500.00 *601*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ *nn* 170.00 X

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*
AAD2001-161

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To repair and realign rear exhaust pipe.

\$ *nn* 170.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *5* 380.00 *X*

Putty and spray painting of the affected portion.

\$ 7,500.00 *6601*

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ *5* 170.00 *X*

To supply and re-do rear luggage floor panel insulation padding.

\$ *5* 380.00 *X*

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.

\$ *5* 170.00 *X*

TOTAL \$ 18,230.00

Over All Total \$ 35,796.20

LUMP SUM (REPAIR DAY)

25 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: