

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD123M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Jan 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002944
Chassis No.:	VF1ABL15AUC282689
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$20,655.00
Total Rebate Amount:	\$35,653.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jan 2020

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M**AAD2001-161***Not Authoised*
1/ Simp \$ 5000/-

Vehicle No.:

Chassis No.:

Vehicle Make:

21 JAN 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 123M

VF1ABL15AUC282689

RENAULT

LATITUDE

18.1.2020

AIG

22-03-16

	PART
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR RH
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER REFLECTOR LH
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	BUMPER BEAM BRACKET RH REAR
1	OUTER PANEL REAR (End Panel)
1	OUTER PANEL REAR (End Panel) TRIM
1	TAILLAMP RH
1	TAILLAMP PANEL RH
1	TAILLAMP LH
1	TAILLAMP PANEL LH
1	BOOT REAR
1	BOOT FINISHER
1	BOOT WHEATERSTRIP
1	BOOT REFLECTOR LAMP LH
1	BOOT REFLECTOR LAMP RH
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	BOOT STRUT LH
1	BOOT STRUT RH
1	BOOT HINGE LH

	LIST
\$	Bu 561.70 ✓
\$	Ne 411.90 ✓
\$	SL 98.10 X
\$	SL 82.10 X
\$	SL 59.80 X
\$	SL 16.60 X
\$	SL 80.80 X
\$	SL 54.20 X
\$	SL 16.60 X
\$	Ne 547.80 ✓
\$	N 114.50 X
\$	N 100.90 X
\$	Ne 745.80 ✓
\$	Ne 404.56 ✓
\$	SL 313.10 X
\$	N 401.40 X
\$	SL 401.40 X
\$	N 401.40 X
\$	Bu 1,677.20 ✓
\$	SL 344.70 X
\$	SL 178.20 X
\$	SL 277.70 X
\$	SL 277.70 X
\$	Ne 82.40 ✓
\$	Ne 95.80 ✓
\$	SL 145.10 X
\$	SL 145.10 X
\$	N 254.20 X

Trans-cab Auto Services Pte Ltd**AAD2001-161**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M

1	BOOT HINGE RH	\$	<i>11</i>	253.80	}	<i>X</i>
2	BOOT RUBBER PLUG	\$	<i>12</i>	139.90		
2	LICENCE PLATE LAMP	\$	<i>12</i>	26.30		
1	BOOT LOCK LINKAGE	\$	<i>12</i>	20.60		
1	BOOT LOCK LINKAGE HOLDER	\$	<i>12</i>	99.50		
1	BOOT INNER TRIM BOARD	\$	<i>12</i>	611.00		
1	BOOT SWITCH	\$	<i>12</i>	113.00		
1	BOOT LOCK	\$	<i>11</i>	246.60		
1	BOOT LOCK CATCH	\$	<i>11</i>	41.70		
1	EXHAUST CAP REAR	\$	<i>11</i>	125.40		
1	EXHAUST REAR	\$	<i>11</i>	5,263.60		
1	SPARE WHEEL PANEL	\$	<i>11</i>	1,229.40		
1	SPARE TYRE BOARD	\$	<i>12</i>	680.90		
1	SPARE WHEEL PANEL TRIM	\$	<i>12</i>	612.21		

TOTAL	\$	17,754.67
10%	\$	1,775.47
	\$	15,979.20

Special Nett

1SET	PARKING AID	\$	<i>Shan</i>	700.00	<i>400.00</i>
1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	<i>X</i>
1SET	BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	<i>X</i>
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	<i>X</i>
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	<i>X</i>
1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	<i>X</i>
1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	—
1	BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	—
1	BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	—
2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	<i>X</i>
1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	<i>X</i>
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	<i>X</i>
1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	<i>X</i>
1SET	BOOT FINISHER CLIP	\$	<i>na</i>	24.20	<i>X</i>

1 TAILLAMP CLIP LH

\$

5.00

Trans-cab Auto Services Pte Ltd

AAD2001-161

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M

1 TAILLAMP CLIP RH

\$

nn 5.00 X

1 Rear Bumper Protector

\$

nn 100.00 *4050*

1 EXHAUST MOUNTING REAR

\$

nn 16.00 X

1 EXHAUST BRACKET REAR

\$

n 24.80 X

1SET Rear licence plate with holder

\$

SW 80.00 X

TOTAL \$ 1,587.00

TOTAL PARTS \$ 17,566.20

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.

\$

170.00 *601*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$

380.00 *601*

To Rust-Proofing Of The Affected Areas.

\$

170.00 *601*

To Check Electrical Lighting Concerned.

\$

170.00 *201*

To transfer of tire, rim and on wheel balancing.

\$

nn 170.00 X

To check steering geometry and computer wheel alignment

\$

nn 220.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$

7,500.00 *6001*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$

nn 170.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$

nn 170.00 X

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*
AAD2001-161

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 123M

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To repair and realign rear exhaust pipe.

\$ *nn* 170.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *4* 380.00 *X*

Putty and spray painting of the affected portion.

\$ 7,500.00 *6601*

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ *4* 170.00 *X*

To supply and re-do rear luggage floor panel insulation padding.

\$ *4* 380.00 *X*

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.

\$ *4* 170.00 *X*

TOTAL \$ 18,230.00

Over All Total \$ 35,796.20

LUMP SUM (REPAIR DAY)

25 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: