

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26897

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0088/2020/NS
Date : 21-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Frederick Benjamin Koh
Address : 8A Grove Road
#17-03
Singapore 258343
Telephone : HP +65 96316627
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No. : **SMG 5453 C**
Model Code : Audi A3 SEDAN 1.0 TFSI 8V
Model / Year : Dec-18
Engine No. : CHZ B22414
Chassis No. : WAUZZZ8V2K1008001
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Jan-20
Place of Accident : PIE After Steven Road ERP Gantry

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 5453 C

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper and lower spoiler. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	500
3	To respray rear bumper, rhs rear fender and lhs rear fender.	\$ 2,800.00	550
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 4,322.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 5453 C

S/N	Parts Description		S/NETT	Damage Parts & Prices		Remarks
1	REAR BUMPER		\$	1,851.00	✓	1480.80
2	REAR BUMPER STICKY PAD	4	\$	22.00	?X	
3	REAR BUMPER FIXING PARTS		\$	182.00	✓	
4	WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$	72.00	✓	
5	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	30.00	X	
6	REAR BUMPER LOCKING MECHANISM	2	\$	55.00	✓	
7	REAR BUMPER SPOILER - LH		\$	223.00	✓	178.40
8	REAR LIGHT REFLECTOR - LH / RH	2	\$	78.00	✓	30.64
9	REAR BUMPER SIDE REINFORCEMENT BEAM		\$	538.00	X	
10	REAR BUMPER BRACKET - LH		\$	26.00	X	
11	REAR BUMPER BRACKET - RH		\$	27.00	X	
12	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	124.00	✓	
13	REAR PARKING AID SENSOR - INNER / OUTER	2	\$	TBC	✓	
14	REAR PARKING AID SEAL RING	4	\$	14.00	✓	
15	SUNDRIES		\$	200.00	?X	

TOTAL SPARE PARTS CHARGES
TOTAL LABOUR CHARGES
GRAND TOTAL

: \$ 3,442.00
: \$ 4,322.00
: \$ 7,764.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Ling
: 22/01/20 J
:
:
:
:
: Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant