Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SM(

S/n	Nature of Jobs		Cha
5	To dismantle and renew front bumper, rhs front fender and rhs headlight. Reorganise crash management components. Reinstall all parts removed.	\$	2,
6	To respray front bumper, rhs front fender and rhs front door.	\$	5
7	To renew rhs front rim and carry out wheel alignment.	S/N \$	
8	To carry out diagnostic check.	\$	
	TOTAL LABOUR CHARGES	: \$	=

7,683.70 360 - + 2,400 .+ 1,250 .+ 1,100 .+ 280 • + 192.+ 5,582.* 0.0 1,515.2+ 4040+ 541.21 20056+ 58 . 84 127.2+ 4,154.4+ 769.6+ 74.32+ 275.6+ 443.6+ 383.2+ 95.2+ 1,752.+ 700+ 96.4+ 64.8+ 142.4+ 228.+ 34.24+ 12.48+ 13.44+ 16.32+ 34.72+ 11.36+ 8.96+ 11,432.88* 0.0 5,582.+ 11,432.88+

Estin

Cha

6,082.+ 13,776.+ 8,142.+ 20130 28.000.*

17,014.88*