

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27024

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0090/2020/KK
Date : 22-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Basavarajaiah Ajay Muddubasappala
Address : 12 Bedok Reservoir
#06-32
Singapore 479237
Telephone : HP +65 91856912
Type of Claim : Own Damage Claims
Policy No. : 1800149214-01
Vehicle No : **SKK 9841 S**
Model Code : Audi Q2 1.4 COD S TR
Model / Year : Dec-18
Engine No : CZE 847441
Chassis No : WAUZZZGA2KA014606
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Jan-20
Place of Accident : North Bridge Road (Intersection With Bain)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 9841 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ ✓
2	To remove and transfer lhs front door and lhs rear door's multi-lock and power window devices.	S/N \$ 560.00 280	✓
3	To dismantle lhs front door panel trim. To renew lhs wing mirror assy.	S/N \$ 400.00	X. ✓
4	To dismantle and renew front bumper, lhs front fender, lhs front door and lhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 4,000.00 1500	✓
SUB TOTAL LABOUR CHARGES		: \$ 5,320.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 9841 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To respray front bumper, lhs front fender, lhs front door, lhs rear door, door handle and lhs wing mirror cover.	\$ 4,900.00	1800 ✓ 3x550 = 1650 mirror 150
6	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00	✓
7	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,692.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 9841 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
1	FRONT BUMPER <i>new</i>	\$	1,763.00	<i>x</i>
2	FRONT BUMPER FIXING PARTS	\$	326.00	<i>x</i>
3	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	\$	159.00	<i>x</i>
4	FRONT BUMPER END CAP - LH/RH	\$	32.00	<i>x</i>
5	FRONT BUMPER SPOILER	\$	282.00	<i>x</i>
6	FRONT BUMPER CLOSING ELEMENT	\$	147.00	<i>x</i>
7	WHEEL SPOILER - LH	\$	32.00	<i>x</i>
8	FRONT BUMPER ADAPTER - LH	\$	34.00	<i>x</i>
9	FRONT BUMPER GUIDE SECTION - LH	\$	34.00	<i>x</i>
10	HEADLIGHT MOUNTING - LH	\$	112.00	<i>x</i>
11	LED HEADLIGHT - LH	\$	4,627.00	<i>x</i>
12	FRONT FENDER - LH <i>Dented</i>	\$	1,079.00	<i>x</i> 863.20
13	FRONT FENDER ATTACHMENT PARTS	\$	38.00	<i>x</i> <i>new</i>
14	FRONT FENDER BRACKET - LH	\$	45.00	<i>x</i>
15	FRONT FENDER BRACKET - LH <i>new</i>	\$	15.00	<i>x</i>
16	FRONT FENDER BRACKET - LH	\$	15.00	<i>x</i>
17	FRONT FENDER BRACE - LH <i>new</i>	\$	35.00	<i>x</i>
18	WHEEL HOUSING LINER - LH <i>new</i>	\$	185.00	<i>x</i>
19	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	54.00	<i>x</i>
20	FRONT WHEEL COVER - LH / RH <i>new</i>	2 \$	606.00	<i>x</i> 484
SUB TOTAL SPARE PARTS		:	<u>\$ 9,620.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 9841 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
21	FRONT DOOR - LH <i>Dented</i>	\$	2,380.00 ✓	1904
22	FRONT DOOR ATTACHMENT PARTS ?	\$	89.00 ?	xnn
23	FRONT DOOR CATCH <i>new</i>	\$	113.00 +	
24	EXTERIOR MIRROR MOUNTING <i>new</i>	\$	964.00 x	
25	MIRROR CAP - LH <i>Ry's</i>	\$	159.00 +	
26	FRONT DOOR COVER - LH <i>cut</i>	\$	242.00 ✓	193-20
27	REAR DOOR - LH <i>Ry's</i>	\$	2,380.00 x	
28	REAR DOOR OUTER SEAL <i>new</i>	NEC \$	127.00 +	
29	BONDING AGENT ?	NEC \$	46.00 ?	xnn
30	CLEANING SOLUTION ?	NEC \$	64.00 ?	xnn
31	REAR DOOR CATCH <i>new</i>	\$	113.00 +	
32	REAR DOOR COVER - LH <i>cut</i>	\$	213.00 ✓	170
33	FRONT DOOR WINDOW GUIDE - LH	\$	389.00 +	
34	FRONT DOOR WINDOW APERTURE SEAL - LH <i>new</i>	\$	127.00 +	
35	CORNER TRIM - LH <i>new</i>	\$	43.00 +	
36	FRONT ALUMINIUM RIM - LH <i>cut</i>	\$	579.00 ✓	462.80
37	SUNDRIES ?	\$ <i>new</i>	300.00 ?	19.84
TOTAL SPARE PARTS CHARGES		:	\$ 17,948.00	
TOTAL LABOUR CHARGES		:	\$ 10,692.00	
GRAND TOTAL		:	\$ 28,640.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *22/01/20*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not Authorised, 06 Days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant