

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile    |  |   |                             |                      |
|--|--|---|-----------------------------|----------------------|
| AXA INSURANCE PTE LTD  |  |   | Ref: CC4/ASM18011753/Kga3s2 |                      |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN: STACEY NG |  | Date: 07-09-2020 Code: ASM                  |                             |                      |
| 1. Policy Particulars :- THIRD PARTY CLAIM                           |  |   |                             |                      |
| 1.   | Insured Veh.   | SGV 3018G                                   | Veh. Inspected              | SKM 2230R            |
|  | Policy No.   | GA220170                                    | Coverage (\$)               | 0.00                 |
|  | Claim No.  | S8M00M0H                                    | Excess (\$)                 | 0.00                 |
|  | Assign From  | STACEY NG                                   | Assign Date                 | 26/06/2018           |
| 2.   | / tooign i iom   |   | culars & Condition          |                      |
|  | Make & Model   | SUBARU FORESTER (A)                         | c.c                         | 1995                 |
|  | Engine No.   | HIDDEN                                      | Year of Reg.                | 2016                 |
|  | Chassis No.  | JF1SJ5KC5GG073571                           | Colour                      | METALLIC PEARL WHITE |
|  | Odometer   | 093729                                      | Steering                    | IN ORDER             |
|  | Brakes   | IN ORDER                                    | Modification                | STANDARD ALLOY RIM   |
|  | General  | GOOD  |                             |                      |
| 3. Conditions of Tyres   |  |   |                             |                      |
|  |  | Size  | Make                        | Balance              |
|  | R/H Front Tyre   | 225/55 R18                                  | BRIDGESTONE                 | 8 mm                 |
|  | L/H Front Tyre   | 225/55 R18                                  | BRIDGESTONE                 | 8 mm                 |
|  | R/H Rear Tyre  | 225/55 R18                                  | BRIDGESTONE                 | 8 mm                 |
|  | L/H Rear Tyre  | 225/55 R18                                  | BRIDGESTONE                 | 8 mm                 |
| 4. Description of Damages  |  |   |                             |                      |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |   |                             |                      |
|  | DAMAGES SEE DETAILS.   |   |                             |                      |
| 5.   | General Information  |   |                             |                      |
|  | Accident Date  | 25/06/2018                                  | Inspection Date             | 21/01/2020           |
|  | Survey held at   | MOTOR IMAGE ENTERPRISES                     | PTE LTD                     |                      |
|  |  | 19 TOA PAYOH LORONG 8 .<br>SINGAPORE 319255 |                             |                      |
| 5a.  | Remarks  |   |                             |                      |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                             |                      |
| 5b.  | . Estimate Days of Repair  |   |                             |                      |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days   |   |                             |                      |