

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9220G**AAD2001-144***Not Authored
Resurvey B4 paint**82360.90*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

21 JAN 2020

SHD 9220G

JTDKB3FU103077229

TOYOTA

PRIUS

16.1.2020

AIG

4/12/2018

PART		LIST	
1	FRONT BUMPER	\$ Bu	516.00 ✓
1	FRONT BUMPER SIDE RETAINER LH	\$ DIT	82.30 ✓
1	REINFORCEMENT, FRONT BUMPER	\$ K	716.60
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$ K	246.10
1	ABSORBER, FRONT BUMPER, LOWER	\$ S _L	132.70
1	ABSORBER, FRONT BUMPER ENERGY	\$ S _L	79.60
1	COVER SUB-ASSY, ENGINE, NO.1	\$ S _L	472.40
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ S _L	241.90
1	COVER, FRONT BUMPER HOLE, LH	\$ S _L	29.30
1	EXTENSION, FRONT BUMPER, LH	\$ S _L	120.10
1	FRONT LED LAMP (LOWER) LH	\$ S _L	951.40
1	FRONT HEADLAMP LH	\$ S _L	2,637.60
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$ S _L	960.50
1	MOTOR, HEADLAMP LEVELING, LH	\$ S _L	487.50
1	FRONT FENDER LH	\$ B	977.80 ✓
1	LINER, FRONT FENDER, LH	\$ CM	202.50 ✓
1	COVER SUB ASSY, FRONT PILLAR, UPPER LH	\$ S _L	100.40 X
1	FRONT FENDER EMBLEM LH	\$ M	54.60 ✓
1	PROTECTOR, FRONT FENDER SIDE PANEL, LH	\$ S _L	93.90
1	FRONT BONNET	\$ K	983.10
1	HINGE ASSY, HOOD, LH	\$ K	58.90
1	LEFT SIDE VIEW MIRROR	\$ S _L	1,339.30
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$ S _L	594.80
1	SHAFT ASSY, FRONT DRIVE, LH	\$ K	1,251.70
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$ S _L	760.10
1	KNUCKLE, STEERING, LH	\$ S _L	663.40
1	FRONT SHOCK ABSORBER	\$ S _L	438.30
1	GRILLE SUB-ASSY, RADIATOR	\$ S _L	346.00
1	GRILLE, RADIATOR, LOWER NO.1	\$ S _L	170.10

Trans-cab Auto Services Pte Ltd

AAD2001-144

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9220G

TOTAL	\$	15,708.90
25%	\$	3,927.23
	\$	11,781.68

Special Nett

1 FRONT WHEEL RIM	\$	Sn	1,879.40	X
1 FRONT WHEEL RIM COVER	\$	Sn	211.50	X
1 FRONT TYRE 195/65/15	\$	Sn	350.00	X
1SET CLIP, FRONT FENDER LINER	\$	na	35.00	✓
1 FRONT NUMBER PLATE WITH MOULDING	\$	Sn	200.00	X
1SET BUMPER CLIP FRT	\$	na	66.00	✓
1SET FRONT BUMPER RETAINER CLIP	\$	na	35.00	X
1SET FRONT FENDER LINER RETAINER	\$	na	35.00	X
TOTAL	\$		2,811.90	

TOTAL PARTS	\$	14,593.58
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *4001*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ na 380.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 170.00 X

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$ 170.00 X

To check ABS and brake efficiency, final checking and testing.

\$ 380.00 X

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$ 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2001-144**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9220G

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	440
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	150
To Rust-Proofing Of The Affected Areas.	\$	170.00	300
TOTAL	\$	14,760.00	
Over All Total	\$	29,353.58	

(PART-BY-PART) Repair Days~~20 days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: