

Section A - Accident Details

Registration Number	SHC4786D
Case Reference Number	TAX/01/20/2070
Registration Date	11/3/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	JEREMY EBENEZER
Type of Accident	Others
Accident Date and Time	16/1/2020 1:45 AM
Accident Reported Date and Time	16/1/2020 11:01 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105343
Special Instruction to ARC, if any	LEFT HAND REAR PORTION
Prepared Date and Time	16/1/2020 7:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$1,494.00	\$730.00
Total Spare Part Cost	\$3,825.86	\$1,663.40
Total Other Cost	\$1,867.20	\$1,187.20
TOTAL COST	\$8,032.06	\$4,080.60
Lump Sum Total	\$8,050.00	\$4,100.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / III
ARC / Surveyor Sign Off Date	21/01/2020 2:58 PM	20/01/2020 4:36 PM
Signature		
Remarks		Lump Sum repair, take after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2002-0168	Invoice Number	
Quotation Date	07.02.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$845.00	\$500.00
Total Labour	\$845.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$80.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,494.00	\$730.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$742.20	\$742.20
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$60.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,867.20	\$1,187.20

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		67004-47080	DOOR RR/LH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	DD
		69080-47080	DOOR LOCK RR/LH	0.00	\$709.30	0.00	\$0.00	Replace	Check	X SVC
		42611-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
		75852-47900	MOULDING BODY, LH	1.00	\$673.60	25.00	\$505.20	Replace	Replace	CRA
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	R
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X SVC



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68552623
Accident Reporting Number : 68552672

Date Generated : 10/02/2020

User ID : PehSuan

			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	/	nec
	61602-47091		FENDER RR/LH	1.00	\$766.80	25.00	\$575.10	Replace	Replace	/	DD
	62720-47031		QUARTER GLASS RR/LH	1.00	\$168.10	25.00	\$126.07	Replace	Replace	/	nec
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	/	nec
	65638-47021		FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X	svc
	65632-47041		SILL MEMBER PLATE RR/LH	0.00	\$57.50	0.00	\$0.00	Replace	Check	X	svc
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	svc
	42450-47040		WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X	svc
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	/	nec
Total					\$6,281.84		\$2,079.25				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2079.25
 - 207
 + 1663.41
 + 500.00
 + 1917.20

 4080.61
 4S \$4100/-