

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5368X**AAD2001-153***Not Withheld
1/10/20 @ 3400*

Vehicle No.:

Chassis No.:

Vehicle Make:

21 JAN 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5368X

VF1ABL15AUC279576

RENAULT

LATITUDE

18.1.2020

III

21-10-14

PART	
1	DOOR PANEL REAR LH
1	DOOR LOCK REAR LH
1	ROCKER PANEL INNER GARNISH LH
1	ROCKER PANEL INNER LH
1	ROCKER PANEL OUTER LH
1	ROCKER PANEL CENTER LH
1	FENDER PANEL REAR LH
1	FENDER PANEL INNER TRIM REAR LH
1	WHEELARCH REAR LH
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER REFLECTOR LH
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	TAILLAMP LH
1	TAILLAMP PANEL LH
1	AIR VENT
1	BOOT REFLECTOR LAMP LH

LIST	
\$	<i>h</i> 758.70 X
\$	<i>h</i> 468.20 X
\$	<i>Sh</i> 466.51 X
\$	<i>h</i> 1,024.79 X
\$	<i>h</i> 1,184.99 X
\$	<i>h</i> 990.25 X
\$	<i>Bu</i> 1,933.20 ✓
\$	<i>Sh</i> 671.45 X
\$	<i>Sh</i> 181.60 X
\$	<i>B</i> 561.70 —
\$	<i>Dil</i> 411.90 ✓
\$	<i>Dil</i> 82.10 X
\$	<i>Dil</i> 54.20 X
\$	<i>Sh</i> 16.60 X
\$	<i>h</i> 547.80 X
\$	<i>h</i> 114.50 X
\$	<i>Sh</i> 401.40 X
\$	<i>h</i> 401.40 X
\$	<i>Bu</i> 59.40 ✓
\$	<i>Sh</i> 277.70 X

TOTAL	\$	10,608.39
10%	\$	1,060.84
	\$	9,547.55

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>na</i> 80.00 X
1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00 X

Trans-cab Auto Services Pte Ltd

AAD2001-153

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5368X

1	TAILLAMP CLIP LH	\$	nn	5.00	X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	405n
1	WINDSCREEN MOULDING	\$	nn	100.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	305n
1	REAR LEFT TYRE	\$	nn	300.00	X
1	REAR LEFT TYRE RIM	\$	nn	380.00	X
1SET	PARKING AID	\$	nn	700.00	X
1SET	REAR BUMPER CLIP	\$	nn	66.00	✓
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	✓
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
TOTAL		\$		1,992.00	

TOTAL PARTS \$ 11,539.55**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 6000

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 1000

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ 170.00 1200

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5368X**AAD2001-153**

To rust-proofing of the affected areas.	\$	170.00	301
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	4 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To reinstall rear bumper parking sensor.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	6,000.00	4401
TOTAL	\$	14,970.00	
Over All Total	\$	26,509.55	

LUMP SUM (REPAIR DAY)~~20 DAYS~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: