

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Vehicle No.(For Motor)

Date of Accident

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5112139826		YIP HON FAI	S7109717Z	GPC	drive CLASSIC	SMN7077E	SMN7077E	26/08/2019	25/08/2020

TP Claims against NTUC Income: Follow-Through Survey

Date : 21/02/2020

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1081086-002	SMRT TAXIS PTE LTD	SHC 4323G	SGD 7075J	21/01/2020	06:50	\$ 5,700.69	\$ 2,279.18
2	MT/1085455-001	COMFORT TRANSPORTATION PTE LTD	SHB 4363X	SIP 8813R	13/02/2020	11:30	\$ 1,933.62	\$ 530.00
3	MT/1080979-002	SMRT TAXIS PTE LTD	SHB 1745Y	SMN 7077E	19/01/2020	16:50	\$ 6,248.29	\$ 2,950.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB1745Y
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR1509922
Chassis No.:	JTDKN36U305758472
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	11 Feb 2015
First Registration Date:	11 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2023
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	10 Feb 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,904.00
COE Rebate Amount:	\$20,178.00
Total Rebate Amount:	\$26,244.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Jan 2020

OK

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Friday, 21 February, 2020 10:42 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHB1745Y

Hi Poh Suan,

Confirm the finalize amount \$2,950. Repair day 3 days under lump sum repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Tuesday, 18 February, 2020 5:05 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB1745Y

Hi Sun Pin,

Attached herewith the repair estimate of SHB 1745Y having Case No: TAX/01/20/2088.

There is no change to the approved amount of \$2,950 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Tuesday, 18 February 2020 4:54 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 12:02
Date Of Accident	19/01/2020 16:50
Exact Location Of Accident	CTE TOWARDS YISHUN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1745Y
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	YEN SOON WENG
NRIC No	SXXXX482A
Date Of Birth	02/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	19/06/1982
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 3 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 4 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name SENGKANG NPC
 Police Station Address ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20200120/2205

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMN7077E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver YIP HON FAI
NRIC/Passport Number SXXXX717Z
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLJ1401A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAI YONG TECK
NRIC/Passport Number SXXXX713E
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name UNKNOWN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLJ1401A
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name YEN SOON WENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHB1745Y
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan Pg. 1



DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GA 20-01-20
Driver's Signature
(If driver is not the policyholder)
Date & Time

20/1/2020
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200120/2205

1 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20200120/2205

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/01/2020 23:47		Vide Report No.:		Station Diary No.: 194	
Informant's Particulars					
Name of Informant: YEN SOON WENG			Address: APT BLK 205B COMPASSVALE LANE #02-03 SINGAPORE 542205		
ID Type / ID No.: NRIC NO / S1484482A			Contact No.: Home/Office: Mobile: 83188576		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 58	Date of Birth: 02/09/1961	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,3,4,5 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/01/2020 16:50	Type of Location: Expressway
Location: Along Road 1 CENTRAL EXPRESSWAY				
CTE towards Yishun, lane 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB1745Y	Car				Slightly Damaged	4
SLJ1401A	Car				Slightly Damaged	4
SMN7077E	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20200120/2205

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of
Report No. T/20200120/2205

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	YEN SOON WENG	ID No.	S1484482A
Related Vehicle	SHB1745Y (Car)	Contact No.	83188576
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3,4,5 Date of Expiry: NIL
Date Treatment	19/01/2020	Date Discharge	19/01/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 19/01/2020 at about 1640hrs, I was driving my taxi bearing registration plate number SHB1745Y with four passengers in the vehicle. I was driving along CTE towards Yishun direction, along Lane 1. While driving along CTE Lane 1, I saw one car stopped in front of me abruptly. I managed to stop in time without hitting onto the vehicle in front of me. However, I felt an impact coming from the rear of my vehicle. Seconds later, another impact came in. I got off my vehicle and established that vehicle SMN7077E was behind me and didn't managed to stop in time after I stopped my vehicle. Subsequently, vehicle SLT1401A didn't managed to stop and hit onto the rear of SMN7077E. That resulted in the 2nd impact onto my vehicle. We got off our vehicles to exchanged particulars. Shortly, one LTA officer arrived and told me to drive off first.

After dropping off my passengers at Yishun area, I drove my vehicle to my company's workshop at woodlands. I left my vehicle there and went over to Khoo Teck Phuat Hospital, A&E Department for further medical assessment as I felt pain at the back of my head. I was given three days MC by the doctor from Khoo Teck Phuat Hospital.

On 20/01/2020 in the morning, I went back to my company to provide information for insurance purposes. I was then told by my company staff that I need to lodge a Traffic Accident Report with the Police. I do not know that I am needed to lodge a Police report on the matter initially. I went back Khoo Teck Phuat Hospital, A&E Department for further check as I still feel pain in my head.

After I was discharged from Khoo Teck Phuat Hospital, I then proceeded to Sengkang Neighbourhood Police Centre to lodge a Police Report on the matter.



**SINGAPORE
POLICE FORCE**



T/20200120/2205

3 of 3

Police Station Of Origin:

Sengkang N.P.C

2 Sengkang Square #01-02 SINGAPORE
545025

Tel No: 1800-343 8999

Report No. T/20200120/2205

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt LOI WEE LONG

Signature Of Informant:

X
Gn

Signature Of Interpreter:

Not applicable

Date/Time:

20/01/2020 23:47

Officer In Charge Of Case:

TP / AEIT /

SSI 2 JUREMAH BINTE AHMAD

Contact No: 65476219

SN 085

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force

Case Details

Case Reference Number :

TAX/01/20/2088

Type of Repair : Accident Repair

Vehicle Registration Number : SHB1745Y

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10217-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 19/01/2020 08:50 AM

Vehicle Age(In Months) : 59

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	• / CR4
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	• / Nec
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	• / Nec
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace	• / BT
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	• / BT
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	• / BT
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	• X SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	• / shu4
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	• X SVC

Total Spare Part Cost 4,074.79

Lump Sum Discount (%) 20.00

Final Spare Part Cost 3,259.83

Surveyor Total 3,184.49

Lump Sum Dis (%) 20

Final Sur Total 1,747.59

SMRT Recommendation

Surveyor Approval

BDM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	65.58	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	314.50	314.50	25.00	235.88	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	✓ DO
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ NA
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ NA
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ Nec.
One Time Key In	Main			SEALANT W/SCREEN	2	37.00	74.00	0.00	74.00	Replace	2	74.00	Replace	✓ NA
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	265.05	265.05	25.00	198.79	Replace	1	198.79	Replace	✓ out
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	0	Svc Old Dam	* X old damage
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	0	Svc Old Dam	* X old damage
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	* X Svc

Total Spare Part Cost 4,074.79

Surveyor Total 2,184.49

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,259.83

Final Sur Total 1,747.59

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	907.00	300	
Total:			907.00 202	300.00 400	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	80	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY REAR SPOILER	180.00	0	
Total:			1,116.00 1296	480.00 580	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	80	
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	Nec
7	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
Total:			896.88	416.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,258.82	1,747.59
Total Labour Cost	507.00	300.00
Total Spray Painting	1,116.00	480.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Other	898.88	416.88
Overall Total	5,778.71 6248.29	2,944.47
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	5,800.00	2,950.00
Surveyor Approved Amount	2785.88	2,950.00
No of Repair Days*	5	3 3 days
Remarks		Lump Sum Repair, Take after paint photo. Please take reinforcement photo.
Surveyor Name		Sun Pin (LKK)
Signature		 30/1/2020
		<input type="button" value="Save"/> <input type="button" value="Clear"/>
Survey Date	21/01/2020	

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Date:

Section A - Accident Details

Registration Number	SHB1745Y
Case Reference Number	TAX/01/20/2088
Registration Date	11/2/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YEN SOON WENG
Type of Accident	Head to Rear
Accident Date and Time	19/1/2020 4:50 PM
Accident Reported Date and Time	20/1/2020 12:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105389
Special Instruction to ARC, if any	DROVE IN / REAR PORTION /TP
Prepared Date and Time	20/1/2020 7:50 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$707.00	\$400.00
Total Spray Cost	\$1,296.00	\$580.00
Total Spare Part Cost	\$4,163.36	\$2,273.09
Total Other Cost	\$696.88	(\$303.09)
TOTAL COST	\$7,063.24 <i>6248.29</i>	\$2,950.00 (L/5)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	22/01/2020 2:18 PM	21/01/2020 4:00 PM
Signature		
Remarks	SUP = 0 day	Lump Sum Repair. Take after paint photo. Please take reinforcement photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2002-0310	Invoice Number	
Quotation Date	15.02.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RR END PANEL	\$200.00	\$100.00
TO REPAIR REAR PORTION	\$507.00	\$300.00
Total Labour	\$707.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$376.00	\$200.00
TO RESPRAY BUMPER BEAM	\$160.00	\$80.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR SPOILER	\$160.00	\$0.00
TO RESPRAY REAR PANEL	\$160.00	\$100.00
Total Spray Painting & Panel Beating	\$1,296.00	\$580.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$296.88	\$296.88
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$719.97)
Total Other Costs	\$896.88	(\$303.09)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace

	52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
	52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X
	52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
	76091-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	✓
	75574-47020	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
	75574-47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
	75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
		SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace	✓
	67681-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	✓
		NUMBER PLATE	1.00	\$15.00	100.00	\$0.00	Replace	Old Damage	X
		NUMBER PLATE FRAME	1.00	\$12.00	100.00	\$0.00	Replace	Old Damage	X
	76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	X
Total				\$5,152.00		\$2,184.51			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace
Total					118.10		88.58		

CRU. A

+
 +
 2273.09 /
 400.00 /
 996.88 /

 3669.97 /
 - 20%

 2935.98 /
 4/5 \$2950/- /
 3 days

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:			
Accident Case Number	Tax/01/20/2058	Date of Collection	1/1
Vehicle No	SHB1745Y	Date of Request	23/1/20
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	10 days

S/N	Part Number	Part Description	Quantity	Unit Price
		Rear Bumper Lip RH	1pc	100
		Labour to Repair Rear End panel		100
		Labour to Spray Rear End panel		100

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20001380/Qsd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 27-02-2020



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMN 7077E	Veh. Inspected	SHB 1745Y
Policy No.	5112139826	Coverage (\$)	0.00
Claim No.	MT/1080979-002	Excess (\$)	0.00
Assign From		Assign Date	21/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDKN36U305758472	Colour	MAROON
Odometer	635641	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/01/2020	Inspection Date	21/01/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1745Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR (DISC 25%)	CRUMPLED	458.60	343.95
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY. RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY. RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	TAILGATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	CUT	353.40	265.05
1	BUMPER LIP COVER RR/RH (DISC 25%)	CRUMPLED	118.10	88.58
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
2	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	74.00	74.00
1	ANTENNA, ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER SEAL, RR LH	SERVICEABLE	88.90	-
1	BUMPER SEAL, RR RH	SERVICEABLE	65.70	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	UNDER COVER SUB-ASSY, RR FLOOR	SERVICEABLE	514.50	-
1	UNDER COVER RR SHIELD	SERVICEABLE	63.90	-
1	SPOILER REAR	SERVICEABLE	953.70	-
1	NUMBER PLATE (SERVICEABLE)	OLD DAMAGED	15.00	-
1	NUMBER PLATE FRAME (SERVICEABLE)	OLD DAMAGED	12.00	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
			5,682.88	2,569.97

Report Ref No. NS/INC20001380/Qsd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No..2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING & BODY WORK.		707.00	400.00
	SPRAY PAINT.		1,296.00	580.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	60.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
			2,603.00	1,100.00
	GRAND TOTAL		8,285.88	3,669.97
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,950.00

Report Ref No. NS/INC20001380/Qsd3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.