

21000000

ASS. REC. BY:

REF: CS3/LR4021584/H+P3-1

and Instruction:

Surveyor:

Hock Ann

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LR

Date/Time:

23/01/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SV 5151E

Insured:

GBE 3106J

at Workshop m/s

Long Wang Motor

Tel:

67482910

of

B1C 3007 Ubi Rd 1 #01-414

Policy No:

Claim No:

19/19/19/VC00022756

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3-12-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

map

H.O.D. Endorsement:

Date/Time:

6-12-19

4-13pm

Person Contacted:

Alice

Vehicle-IN

OUT

Date/Time

Action/Instruction (X) Estimate

SV 5151E - X


GBE 3106J - X

Submit PRS Report

Submit lump sum \$2,700/-

(Red: 1900; 41%)

3 days


3/2/2020

RECEIVED 05 FEB 2020

File No. **H-ANW**

LPC

ASSIGNMENT

PRS

From: **18/12/2019**

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **STV 5151E**

at Workshop nbs: **Long Dang**
of **BLK3007 Ubi Rd #07414**

Insured:

Policy No:

Owner's No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? **Yes or No**

GIA / PR Seen: Consistent? **Yes or No**

Est. Repairs: days: Res: **Yes or No**

Lum Sum: % 3 Val: **Yes or No**

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: **IN / OUT**

Veh No:

Type: **M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or

Make:

T. ALFA

cc **1500**

Colour:

white

ACC:

Insured / Std / NI / NA

Sp Reading:

40266

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/Nr:

MA253REH134351809

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt or**

Brake: **Inorder / Jammed / Leaked / Burnt or**

Modi: **Nil / S/Rim / STD A/Rim or**

Tyre Size:

F:

215/45/R19

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A:

3/12/19

D.O.I:

18/12/19

0600PM

Survey held at

LENG WANG

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**

The **U/C / Chassis frame / Body Structure** affected due to collision

Date / Time	Action / Instruction
	Days 3 days
	* STV 5151E
	LPRS case 12
	MV - 61000
	PV - 45300
	IVU - 15600
	ms: Alice → 9872032

Cons/Time, File Para (s)

11/26/12 Typist

Cons/Time, File Return (s)

It

Report Format:

TP-PRS

Emp/Time/TP/PR/12

Days Of Repair:

Resurvey No. of Trip: **2**

Add Fee:

☐

Site Insp: **15**

☐

Interview: **15**

☐

Tech Insp: **15**

☐

Reclosure: **15**

Survey Fee:

Transportation:

3 x PS: **120**

Phone:

Other:

2019

120

120

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 23 January 2020 8:38 AM
To: Summer Lee (LKK Auto); sur@lkkauto.com; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Your Ref: LCH.lg.UB08-90881.19 Our Ref: 19/19/19/VC00/022756 [External General]
Attachments: 22756 TP SURVEY REPORT.pdf


Lonpac External - General

Dear Nivitha

Attached is the TP survey report.

Please let us have your surveyor's review and report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Summer Lee (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 6 December 2019 4:14 PM
To: ONG LI LI <llong@lonpac.com>; sur@lkkauto.com; assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Your Ref: LCH.lg.UB08-90881.19 Our Ref: 19/19/19/VC00/022756 [External General]

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 6 December, 2019 4:10 PM


To: Summer Lee (LKK Auto) <admin-d@lkkauto.com>; 'Cheonghoh Law' <mail@cheonghoh.sg>; assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Your Ref: LCH.lg.UB08-90881.19 Our Ref: 19/19/19/VC00/022756 [External General]

Lonpac External - General

Dear Summer

Please see attached.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Summer Lee (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, 6 December 2019 4:09 PM
To: ONG LI LI; 'Cheonghoh Law'; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Your Ref: LCH.lg.UB08-90881.19 Our Ref: 19/19/19/VC00/022756 [External General]

Dear Li Li,

Kindly provide the attach thanks.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <long@lonpac.com>
Sent: Friday, 6 December, 2019 4:02 PM
To: Cheonghoh Law <mail@cheonghoh.sg>; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Your Ref: LCH.lg.UB08-90881.19 Our Ref: 19/19/19/VC00/022756 [External General]

Lonpac External - General

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to your fax of 6 December 2019.

We are not agreeable with your list of proposed surveyors and we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey.

Dear Nivitha

Please see attached and arrange survey.

Regards,


Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd


300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/5821/5151/TP/12.19
Date : 08 January 2019

To: Phua Poh Hua
c/o Blk 3007 Ubi Road 1
#01-414
Singapore 408701

VEHICLE APPRAISAL REPORT

Name of Workshop : Leng Wang Motor
Place of Inspection : Blk 3007 Ubi Road 1, #01-414 Singapore 408701
Date of Assignment : 18 December 2019
Date of Accident : 03 December 2019
Date of Inspection : 18 December 2019

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SJV 5151E	Chassis Frame No.	: MR053REH104551807
Make / Model	: Toyota Corolla Altis 1.6 CVT	Engine No. (Logcard)	: 1ZR576103
Year of Manufacture/Reg	: 2016	Odometer Reading	: 40,266 KM
Colour	: White		
Class / Type	: Saloon		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Very Good
Paintwork : Very Good
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE


	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	MICHELIN 215 / 45 R17	8 mm
Front R	MICHELIN 215 / 45 R17	8 mm
Rear L	MICHELIN 215 / 45 R17	8 mm
Rear R	MICHELIN 215 / 45 R17	8 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered Diagonally to the RH Side from rear to front; right to left; portion of the vehicle.



The general area of damages is at the RH Side portion
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs Leng Wang Motor is \$ 7,895.00 .
We have adjusted the cost to \$ 5,770.18 and the repairer has agreed to undertake the repairs at a Contract Lump Sum of \$ 4,600.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of ³/₅ working days.

36 photographs were taken at the time of static inspection.

(This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. 5821 for our services rendered and we thank you for engaging our services.

Conducted By :

Approved By :

TERRENCE HONG

Dip Engineering / DECC (SP)
Certs Automotive Technology (NP)
Cert. Crash Investigation & Reconstruction
Cert SCI (General Insurance)
AMSAAA, AM SAE-A

KELVIN TEO

Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pc	front bumper ✓ (cut)	broken	\$ 544.10	\$ 544.10 ✓ 500
2	1 pc	front bumper l/h side retainer X (300)	necessary	\$ 37.00	\$ 37.00 ✓
3	1 pc	front bumper r/h side retainer ✓ (all) (R/H)	necessary	\$ 37.00	\$ 37.00 ✓
4	1 set	front bumper clips ✓ (all)	necessary	\$ 35.00	\$ 35.00 ✓ 201
5	1 pc	r/h headlamp ✓ (RA)	cracked	\$ 890.40	\$ 890.40 ✓ 790
6	1 pc	r/h side mirror assy ✓ (original) (S/S)	broken	\$ 510.20	\$ 510.20 ✓ 450
7	1 pc	r/h front fender X (CR)	damaged	\$ 543.10	\$ 543.10 repair
8	1 pc	r/h front fender " dual wtl " emblem ✓ (all) (R/H)	necessary	\$ 68.20	\$ 68.20 ✓ 483
9	1 pc	r/h front fender inner shield X (300)	deformed	\$ 120.10	\$ 120.10 ✓
10	1 set	r/h front fender inner shield clips ✓ (all)	necessary	\$ 32.00	\$ 32.00 ✓ 151
11	1 pc	r/h front lower arm X (300)	bent	\$ 246.95	\$ 246.95 ✓
12	1 pc	r/h front shock absorber X (300)	bent	\$ 312.95	\$ 312.95 ✓
13	1 pc	r/h front wheel hub w/ bearing ✓	damaged	\$ 319.40	\$ 319.40 ✓ 220
14	1 pc	r/h front knuckle arm X (300)	distorted	\$ 393.60	\$ 393.60 ✓
Less 25%				\$ 4,090.00	\$ 3,546.90
					\$ 886.73
				\$ 4,090.00	\$ 2,660.18
SPECIAL NETT ITEMS:-					
15	1 pc	r/h front sports rim ✓ (500) (17 inch)	distorted	\$ 650.00	\$ 650.00 ✓ 500
16	1 pc	r/h front tyre @50% depreciation ✓ (500)	scratched	\$ 380.00	\$ 190.00 ✓
				\$ 1,030.00	\$ 840.00
Sub - Total				\$ 5,120.00	\$ 3,500.18



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/5821/5151/TP/12.19
Vehicle Number : SJV 5151E

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 5,120.00	\$ 3,500.18
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts ✓		\$ 1,200.00	\$ 1,000.00
2		To realign headlamp focus ✓		\$ 35.00	\$ 20.00
3		To check wiring and rewire ✓		\$ 60.00	\$ 50.00
4		To carry out wheel balancing ✓ RH only F+ ✓		\$ 20.00	\$ 20.00
5		To perform 4 wheel alignment ✓		\$ 120.00	\$ 100.00
6		To remove and reinstall front undercarriage ✓ (A+)		\$ 240.00	\$ 200.00
7		To apply anti-rust X		\$ 100.00	\$ 80.00
8		To putty and spray-paint of affected areas ✓ L + (side mirror) R/H		\$ 1,000.00	\$ 800.00
				\$ 2,775.00	\$ 2,270.00
		paper sugar ALS repair with 3 day guarantee after paint 12-00pm H-ANW PSS/LRP	parts 2082.50 paint 25% 1561.87 spe dent 690 labor 1105 3356.87 ALS labor 20% 2685.49 Total ALS A+ \$2700R		
		LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
		Acknowledged by Repairer Signature: Date:			
		Sub - Total		\$ 7,895.00	\$ 5,770.18



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/5821/5151/TP/12.19
Date : 08 January 2019

To: Phua Poh Hua
c/o Blk 3007 Ubi Road 1
#01-414
Singapore 408701

VEHICLE APPRAISAL REPORT

Name of Workshop : Leng Wang Motor
Place of Inspection : Blk 3007 Ubi Road 1, #01-414 Singapore 408701
Date of Assignment : 18 December 2019
Date of Accident : 03 December 2019
Date of Inspection : 18 December 2019

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SJV 5151E	Chassis Frame No.	: MR053REH104551807
Make / Model	: Toyota Corolla Altis 1.6 CVT	Engine No. (Logcard)	: 1ZR576103
Year of Manufacture/Reg	: 2016	Odometer Reading	: 40,266 KM
Colour	: White		
Class / Type	: Saloon		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)


General Condition : Very Good
Paintwork : Very Good
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	MICHELIN 215 / 45 R17	8 mm
Front R	MICHELIN 215 / 45 R17	8 mm
Rear L	MICHELIN 215 / 45 R17	8 mm
Rear R	MICHELIN 215 / 45 R17	8 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



: KAAS/TA/5821/5151/TP/12.19
: SJV 5151E



S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	front bumper	broken	\$ 544.10	\$ 544.10
2	1 pc	front bumper l/h side retainer	necessary	\$ 37.00	\$ 37.00
3	1 pc	front bumper r/h side retainer	necessary	\$ 37.00	\$ 37.00
4	1 set	front bumper clips	necessary	\$ 35.00	\$ 35.00
5	1 pc	r/h headlamp	cracked	\$ 890.40	\$ 890.40
6	1 pc	r/h side mirror assy	broken	\$ 510.20	\$ 510.20
7	1 pc	r/h front fender	damaged	\$ 543.10	repair
8	1 pc	r/h front fender " dual vvt-i " emblem	necessary	\$ 68.20	\$ 68.20
9	1 pc	r/h front fender inner shield	deformed	\$ 120.10	\$ 120.10
10	1 set	r/h front fender inner shield clips	necessary	\$ 32.00	\$ 32.00
11	1 pc	r/h front lower arm	bent	\$ 246.95	\$ 246.95
12	1 pc	r/h front shock absorber	bent	\$ 312.95	\$ 312.95
13	1 pc	r/h front wheel hub w/ bearing	damaged	\$ 319.40	\$ 319.40
14	1 pc	r/h front knuckle arm	distorted	\$ 393.60	\$ 393.60
				\$ 4,090.00	\$ 3,546.90
		Less 25%			\$ 866.73
				\$ 4,090.00	\$ 2,680.18
		SPECIAL NETT ITEMS:-			
15	1 pc	r/h front sports rim	distorted	\$ 650.00	\$ 650.00
16	1 pc	r/h front tyre @50% depreciation	scratched	\$ 380.00	\$ 190.00
				\$ 1,030.00	\$ 840.00
			Sub - Total	\$ 5,120.00	\$ 3,500.18

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 5,120.00	\$ 3,500.18
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,200.00	\$ 1,000.00
2		To realign headlamp focus		\$ 35.00	\$ 20.00
3		To check wiring and rewire		\$ 60.00	\$ 50.00
4		To carry out wheel balancing		\$ 20.00	\$ 20.00
5		To perform 4 wheel alignment		\$ 120.00	\$ 100.00
6		To remove and reinstall front undercarriage		\$ 240.00	\$ 200.00
7		To apply anti-rust		\$ 100.00	\$ 80.00
8		To putty and spray-paint of affected areas		\$ 1,000.00	\$ 800.00
				\$ 2,775.00	\$ 2,270.00
Sub - Total				\$ 7,895.00	\$ 5,770.18

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered Diagonally to the RH Side from rear to front; right to left; portion of the vehicle.



The general area of damages is at the RH Side portion
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs Leng Wang Motor is \$ 7,895.00 .
We have adjusted the cost to \$ 5,770.18 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 4,600.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of 5 working days.

36 photographs were taken at the time of static inspection.

This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. 5821 for our services rendered and
we thank you for engaging our services.

Conducted By :

Approved By :

TERRENCE HONG
Dip Engineering / DECC (SP)
Certs Automotive Technology (NP)
Cert. Crash Investigation & Reconstruction
Cert SCI (General Insurance)
AMSAAA, AM SAE-A

KELVIN TEO
Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2019 15:58
Date Of Accident	03/12/2019 15:15
Exact Location Of Accident	ALONG SIN MING DR OPP LTA BLDG OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV5151E
Insured/Policyholder	
Name Of Registered Owner	PHUA POH HUA
NRIC No	S1449147C
Email Address	WILFREDTAN51@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96623690
Alternative Phone No	OFFICE-96623690

Vehicle Particulars

Manufacturer	TOYOTA
Model	ATLIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S119V06645/VPE/R02/E00
Cover Note Number	

Driver

Name of Driver	TAN SWEE KHIM
NRIC No	S1272068H
Date Of Birth	16/01/1957
Occupation	INDOOR
Date Of Driving Pass	10/02/1978
Driving Experience	41 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90070077
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 146 RIVERVALE DRIVE #17-513
Postcode	540146
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	T201912032134
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE3106J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

A: SUV 515E
B: GBE 3106J

Hit & Run

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

COMPONENTS OF ENGINEERING PTE LTD
EXTERNAL BUSINESS OFFICE BRANCH
NAME & ADDRESS: _____
TELEPHONE: _____ FAX: _____
Reporting Officer's Signature _____
Name: _____
NRIC/FIN No.: _____

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CONFIDENTIAL INFORMATION PTE. LTD.

EXTERNAL DISCLOSURE ONLY - NOT FOR

NAME & SIGNATURE: _____

DESIGNATION: _____ DATE: _____

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:



SINGAPORE POLICE FORCE



T/20191203/2134

1 of 3

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. T/20191203/2134

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/12/2019 18:14	Vide Report No.:	Station Diary No.: 63
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: TAN SWEE KHIM		Address: 14 TAI THONG CRESCENT #06-24 SINGAPORE 347848	
ID Type / ID No.: NRIC NO / S1272068H		Contact No.: Home/Office: Mobile: 96623690	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 62	Date of Birth: 16/01/1957	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Retiree		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 03/12/2019 15:30	Type of Location: Car Park
Location: Along Road 1 SIN MING DRIVE				
OPEN PUBLIC CARPARK OF SIN MING DRIVE (OPPOSITE LTA BULIDING)				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBE3106J	Van	NISSAN		Black		0
SJV5151E	Car	TOYOTA	Altis	White	Seriously Damaged	0



Police Station Of Origin:

Serangoon N.P.C

50 Serangoon Avenue 2 #01-02 SINGAPORE

556129

Tel No: 1800-4880999

Report No. T/20191203/2134

CONTINUATION OF REPORT

Brief Details.

On 03/12/2019 at about 1445hrs, I parked my car (White Toyota Altis bearing SJV5151E) at open public carpark located at Sin Ming drive opposite LTA building. Everything was intact and there were no damages.

On the same day at about 1530hrs, while I retrieved my car and was driving out of my carpark a witness "Mr. Yusoff, Hp: 90713108" approached my car informing that my car was involved in a hit and run accident which occurred earlier. He had already snapped a photo which showed a Black Nissan van bearing GBE3106J which had hit my car earlier on while reversing. The driver of the van had drove off after hitting onto my car without leaving any notice. My car has an in-car camera but it will not record when my car is not moving. My car's driver side front portion was seriously damaged. I am lodging this report for traffic police actions and insurance purpose.



**SINGAPORE
POLICE FORCE**



T/20191203/2134

3 of 3

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. T/20191203/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 3 LOGHANATHAN S/O AYYASAMY

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
03/12/2019 18:14

Officer In Charge Of Case:
TP / HRT /

Classification Of Case:

Contact No.:

Authentication Stamp
NP168

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC19021584/Htf3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 05-02-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 3106J	Veh. Inspected	SVJ 5151E	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/19/19/VC00/222756	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	23/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104551807	Colour	WHITE	
Odometer	40266	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	5 mm	
L/H Front Tyre	215/45 R17	MICHELIN	5 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	5 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2019	Inspection Date	18/12/2019	
Survey held at	LENG WANG MOTOR BLK 3007 UBI ROAD #01-414 SINGAPORE 408701			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 5151E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	544.10	500.50
1	FRONT BUMPER L/H SIDE RETAINER	SERVICEABLE	37.00	-
1	FRONT BUMPER R/H SIDE RETAINER	NECESSARY	37.00	37.00
1	SET FRONT BUMPER CLIPS	NECESSARY	35.00	20.00
1	R/H HEADLAMP	CRACKED	890.40	790.50
1	R/H SIDE MIRROR ASSY	CRACKED	510.20	450.80
1	R/H FRONT FENDER	TO REPAIR SEE LABOUR	543.10	-
1	R/H FRONT FENDER "DUAL VVT-I" EMBLEM	NECESSARY	68.20	48.20
1	R/H FRONT FENDER INNER SHIELD	SERVICEABLE	120.10	-
1	SET R/H FRONT FENDER INNER SHIELD CLIPS	NECESSARY	32.00	15.00
1	R/H FRONT LOWER ARM	SERVICEABLE	246.95	-
1	R/H FRONT SHOCK ABSORBER	SERVICEABLE	312.95	-
1	R/H FRONT WHEEL HUB W/BEARING	DAMAGED	319.40	220.50
1	R/H FRONT KNUCKLE ARM	SERVICEABLE	393.60	-
	LESS 25% DISCOUNT		-	-520.63
			4,090.00	1,561.87
SPECIAL NETT ITEMS				
1	R/H FRONT SPORTS RIM (SN)	SCRATCHED	650.00	500.00
1	R/H FRONT TYRE (SN) (50%)	SCRATCHED	380.00	190.00
			1,030.00	690.00
LABOUR				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF R/H FRONT FENDER.		1,200.00	400.00
	TO REALIGN HEADLAMP FOCUS.		35.00	20.00
	TO CHECK WIRING AND REWIRE.		60.00	30.00
	TO CARRY OUT WHEEL BALANCING.		20.00	15.00
	TO PERFORM 4 WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE AND REINSTALL FRONT UNDERCARRIAGE.		240.00	80.00
	TO APPLY ANTI-RUST.	NOT NECESSARY	100.00	-

Report Ref No. CS3/LPC19021584/Htf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		1,000.00	500.00
			2,775.00	1,105.00
GRAND TOTAL			7,895.00	3,356.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS3/LPC19021584/Htf3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.