

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9480Y

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

PART

- 1 FRONT BUMPER
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 COVER SUB-ASSY, ENGINE, NO.1
- 1 COVER SUB-ASSY, ENGINE UNDER, NO.2
- 1 EXTENSION, FRONT BUMPER, RH
- 1 EXTENSION, FRONT BUMPER, LH
- 1 FRONT LED LAMP (LOWER) RH
- 1 FRONT HEADLAMP RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
- 1 MOTOR, HEADLAMP LEVELING, RH
- 1 FRONT FENDER RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL
- 1 PAD, FRONT WHEEL OPENING EXTENSION, RH
- 1 PROTECTOR, FRONT FENDER SIDE PANEL, RH
- 1 SEAL, FENDER APRON MUDGUARD, RH
- 1 COVER SUB ASSY, FRONT PILLAR, UPR RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 FRONT BONNET
- 1 INSULATOR, HOOD

AAD2001-174

Not Notified
Recovery B4 paint

SHD 9480Y

JTDKB3FU703081950

TOYOTA

PRIUS

20.1.2020

TOKIO MARINE

27/6/2019

LIST

\$	72	516.00	✓
\$		103.40	7x } SVL
\$		716.60	7x } SVL
\$		246.10	7x } SVL
\$	72	29.30	✓
\$		132.70	7x SVL
\$	CM	79.60	✓
\$	CM	80.10	✓
\$		472.40	7x SVL
\$	72	241.90	X
\$	72	120.10	X
\$	72	120.10	X
\$	72	951.40	✓
\$	72	2,637.60	✓
\$		960.50	7x SVL
\$		487.50	7x SVL
\$	72	977.80	✓
\$	72	206.70	✓
\$	72	54.60	✓
\$	72	59.60	} X
\$	72	93.90	
\$	72	51.90	
\$	72	100.40	
\$	72	346.00	
\$	72	170.10	
\$	72	90.80	
\$	72	983.10	
\$	72	410.90	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9480Y**AAD2001-174**

1	HINGE ASSY, HOOD, RH	\$	N	58.90	
1	HINGE ASSY, HOOD, LH	\$	N	58.90	
1	LOCK ASSY, HOOD	\$	N	135.00	
1	CABLE ASSY, HOOD LOCK CONTROL	\$	SL	54.90	
1	BRACE, HOOD LOCK SUPPORT	\$	N	78.30	
1	COVER, RADIATOR SUPPORT OPENING	\$	SL	235.30	
1	WIRE, ENGINE ROOM MAIN	\$	SL	7,323.90	
1	WIRE, ENGINE	\$	SL	2,577.20	
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	N	245.10	
1	SUPPORT SUB ASSY, RADIATOR, UPPER	\$	N	377.10	
1	SUPPORT SUB ASSY, RADIATOR, LOWER	\$	B	409.90	
1	SUPPORT, RADIATOR, UPPER RH	\$	B	78.90	
1	LOUVER SUB ASSY, COWL TOP VENTILATOR	\$	SL	686.80	X
1	SHIELD, COWL WATER EXTRACT, RH	\$	SL	19.60	X
1	LOUVER, COWL TOP VENTILATOR, CENTER NO.1	\$	SL	98.60	X
1	TANK, RESERVE SEALED W/O CAP	\$	N	151.40	
1	JAR ASSY, WINDSHIELD WASHER	\$	N	219.10	
1	INLET SUB ASSY, WASHER	\$	SL	67.00	X
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$		292.40	? SVC
1	APRON SUB-ASSY, FRONT FENDER, RH	\$	N	979.40	X
1	APRON ASSY, FRONT FENDER, RH	\$	N	176.80	X
1	MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT RH	\$	N	62.80	X
1	MEMBER, FRONT APRON TO COWL SIDE, UPPER RH	\$	N	110.00	X
1	BRACE SUB-ASSY, FENDER APRON, RH	\$	N	292.50	X
1	MEMBER SUB-ASSY, FRONT SIDE, RH	\$	N B B	2,397.60	X X
1	MEMBER SUB-ASSY, FRONT SIDE, INNER RH	\$	N	794.70	X
1	REINFORCE SUB-ASSY, FRONT BUMPER MOUNTING, RH	\$	N	184.60	X
1	EXTENSION SUB-ASSY, FRONT SIDE MEMBER, RH	\$	N	110.00	X
1	PLATE, FRONT SIDE MEMBER, OUTER RH	\$	N	292.10	X
1	GUIDE, RADIATOR AIR, NO 3	\$	SL	112.70	X
1	GUIDE, RADIATOR AIR, NO. 1 RH	\$	SL	65.30	X
1	SEAL, RADIATOR TO SUPPORT, NO. 2	\$	SL	29.60	X
1	COVER, MOTOR UNDER, REAR RH	\$	SL	80.10	X
1	CONDENSER ASSY, COOLER	\$	SL	1,783.20	
1	SHAFT ASSY, FRONT DRIVE, RH	\$	B	1,379.50	
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$		760.10	? SVC

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9480Y**AAD2001-174**

- 1 JOINT ASSY, LOWER BALL, FRONT RH
- 1 KNUCKLE, STEERING, RH
- 1 LINK ASSY, FRONT STABILIZER, RH
- 1 BAR, STABILIZER, FRONT
- 1 FRONT SHOCK ABSORBER
- 1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH
- 1 GEAR ASSY, STEERING
- 1 CYLINDER ASSY, FRONT DISC BRAKE, RH
- 1 SENSOR, SPEED, FRONT RH
- 1 CROSSMEMBER SUB-ASSY, FRONT SUSPENSION
- 1 REINFORCEMENT SUB-ASSY, SIDE RAIL, REAR RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH
- 1 MOULDING ASSY, BODY ROCKER PANEL, RH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 BRACKET, HEADLAMP, RH
- 1 PANEL SUB ASSY, FRONT DOOR, RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 CHECK ASSY, FRONT DOOR
- 1 RUN, FRONT DOOR GLASS, RH
- 1 WEATHERSTRIP, FRONT DOOR, RH
- 1 TAPE, BLACK OUT, NO.1 RH
- 1 TAPE, BLACK OUT, NO.2 RH
- 1 TAPE, BLACK OUT, NO.3 RH
- 1 WIRE, FRONT DOOR, RH
- 1 MOULDING ASSY, FRONT DOOR BELT, RH

\$	283.40	? SVC
\$	Bz 663.40	✓
\$	237.10	? SVC
\$	Bz 367.30	X
\$	Bz 438.30	✓
\$	236.40	? SVC
\$	1,955.40	? SVC
\$	SL 1,077.90	X
\$	SL 543.90	X
\$	Bz 2,585.50	X
\$	SL 133.30	X
\$	SL 1,436.60	X
\$	CM 594.80	✓
\$	N 59.30	X
\$	34.80	? SVC
\$	N 1,300.70	} X
\$	N 97.50	
\$	N 110.60	
\$	N 183.80	
\$	SL 153.60	
\$	SL 231.30	
\$	NN 13.30	
\$	NN 43.50	
\$	NN 26.30	}
\$	SL 532.80	
\$	SL 92.00	
TOTAL	\$ 47,653.20	
25%	\$ 11,913.30	
	\$ 35,739.90	

Special Nett

- 1 FRONT WHEEL RIM
- 1 FRONT WHEEL RIM COVER
- 1 FRONT TYRE 195/65/15
- 1SET CLIP, FRONT FENDER LINER
- 1 FRONT NUMBER PLATE WITH MOULDING

\$	Nel 1,879.40	✓
\$	Nel 211.50	✓
\$	Pr 350.00	Posn
\$	Nel 35.00	✓
\$	SL 200.00	X

Trans-cab Auto Services Pte Ltd**AAD2001-174**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9480Y

1SET BUMPER CLIP FRT	\$	<i>na</i>	66.00	✓
1SET FRONT BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	
1SET CLIP (FOR RADIATOR SUPPORT OPENING COVER)	\$	<i>na</i>	30.00	
1SET RADIATOR GRILLE CLIP	\$	<i>na</i>	35.00	
1SET FRONT FENDER LINER SCREW	\$	<i>na</i>	30.00	
1 HEADLAMP PROTECTOR RETAINER	\$	<i>na</i>	35.00	
1 FRONT RH DOOR STICKER "Trans-Cab"	\$	<i>na</i>	100.00	
1 WINDSCREEN SEALANT	\$	<i>na</i>	253.80	
1 FRONT WINDSCREEN MOULDING	\$	<i>na</i>	120.00	
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
1 WINDSCREEN MOULDING CLIP	\$	<i>na</i>	30.00	
1SET ROCKER PANEL MOULDING CLIP	\$	<i>na</i>	35.00	✓
1SET FRONT BUMPER RETAINER SCREW	\$	<i>na</i>	35.00	X
1SET DOOR HINGE SCREW	\$	<i>na</i>	10.00	X
1SET DOOR CHECK SCREW	\$	<i>na</i>	10.00	X
TOTAL	\$		3,600.70	
TOTAL PARTS	\$		39,340.60	

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>7000</i>
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>11000</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD2001-174**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9480Y

To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	220.00	601
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	201
To check ABS and brake efficiency, final checking and testing.	\$	380.00	? X
To vacuum, replace, refix and recharge air condenser	\$	380.00	101
To dismantle and refit engine cross-member and engine mounting.	\$	nn 380.00	X
Towing Fees	\$	150.00	501
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To transfer of door fittings, attachments and perform water seepage test.	\$	5 170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	5 380.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	5 380.00	X
TOTAL	\$	19,770.00	

Over All Total \$ 59,110.60 45#

(PART-BY-PART) Repair Days

25 days

6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: