

Not Notwithstanding
Resurvey B4 paint

Date of Registration :

22 JAN 2020

27/6/2019

LIST

PART	LIST	PRICE	QTY	TOTAL	REMARKS
1 FRONT BUMPER		\$ 516.00	✓		
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING		\$ 103.40	?		
1 REINFORCEMENT, FRONT BUMPER		\$ 716.60	?		
1 REINFORCEMENT, FRONT BUMPER, NO.2		\$ 246.10	?		
1 COVER, FRONT BUMPER HOLE, RH		\$ 29.30	✓		
1 ABSORBER, FRONT BUMPER, LOWER		\$ 132.70	?		
1 ABSORBER, FRONT BUMPER ENERGY		\$ 79.60	✓		
1 FRONT BUMPER SIDE RETAINER RH		\$ 80.10	✓		
1 COVER SUB-ASSY, ENGINE, NO.1		\$ 472.40	?		
1 COVER SUB-ASSY, ENGINE UNDER, NO.2		\$ 241.90	X		
1 EXTENSION, FRONT BUMPER, RH		\$ 120.10	X		
1 EXTENSION, FRONT BUMPER, LH		\$ 120.10	X		
1 FRONT LED LAMP (LOWER) RH		\$ 951.40	✓		
1 FRONT HEADLAMP RH		\$ 2,637.60	✓		
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1		\$ 960.50	?		
1 MOTOR, HEADLAMP LEVELING, RH		\$ 487.50	?		
1 FRONT FENDER RH		\$ 977.80	✓		
1 LINER, FRONT FENDER, RH		\$ 206.70	✓		
1 EMBLEM, SIDE PANEL		\$ 54.60	✓		
1 PAD, FRONT WHEEL OPENING EXTENSION, RH		\$ 59.60			
1 PROTECTOR, FRONT FENDER SIDE PANEL, RH		\$ 93.90			
1 SEAL, FENDER APRON MUDGUARD, RH		\$ 51.90			
1 COVER SUB ASSY, FRONT PILLAR, UPR RH		\$ 100.40			
1 GRILLE SUB-ASSY, RADIATOR		\$ 346.00			
1 GRILLE, RADIATOR, LOWER NO.1		\$ 170.10			
1 EMBLEM ASSY, RADIATOR GRILLE		\$ 90.80			
1 FRONT BONNET		\$ 983.10			
1 INSULATOR, HOOD		\$ 410.90			

Auto Services Pte Ltd

100 Mo Kio Street 63 Singapore 569111

Tel : 6287 6666

Fax No. : 6257 1330

U/GST Reg. No. 201019626G

SHD 9480Y

AAD2001-174

- 1 HINGE ASSY, HOOD, RH
- 1 HINGE ASSY, HOOD, LH
- 1 LOCK ASSY, HOOD
- 1 CABLE ASSY, HOOD LOCK CONTROL
- 1 BRACE, HOOD LOCK SUPPORT
- 1 COVER, RADIATOR SUPPORT OPENING
- 1 WIRE, ENGINE ROOM MAIN
- 1 WIRE, ENGINE
- 1 SUPPORT SUB-ASSY, RADIATOR, RH
- 1 SUPPORT SUB ASSY, RADIATOR, UPPER
- 1 SUPPORT SUB ASSY, RADIATOR, LOWER
- 1 SUPPORT, RADIATOR, UPPER RH
- 1 LOUVER SUB ASSY, COWL TOP VENTILATOR
- 1 SHIELD, COWL WATER EXTRACT, RH
- 1 LOUVER, COWL TOP VENTILATOR, CENTER NO.1
- 1 TANK, RESERVE SEALED W/O CAP
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 INLET SUB ASSY, WASHER
- 1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER
- 1 APRON SUB-ASSY, FRONT FENDER, RH
- 1 APRON ASSY, FRONT FENDER, RH
- 1 MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT RH
- 1 MEMBER, FRONT APRON TO COWL SIDE, UPPER RH
- 1 BRACE SUB-ASSY, FENDER APRON, RH
- 1 MEMBER SUB-ASSY, FRONT SIDE, RH
- 1 MEMBER SUB-ASSY, FRONT SIDE, INNER RH
- 1 REINFORCE SUB-ASSY, FRONT BUMPER MOUNTING, RH
- 1 EXTENSION SUB-ASSY, FRONT SIDE MEMBER, RH
- 1 PLATE, FRONT SIDE MEMBER, OUTER RH
- 1 GUIDE, RADIATOR AIR, NO 3
- 1 GUIDE, RADIATOR AIR, NO. 1 RH
- 1 SEAL, RADIATOR TO SUPPORT, NO. 2
- 1 COVER, MOTOR UNDER, REAR RH
- 1 CONDENSER ASSY, COOLER
- 1 SHAFT ASSY, FRONT DRIVE, RH
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH

\$	n	58.90	
\$	n	58.90	
\$	n	135.00	
\$	SL	54.90	
\$	n	78.30	X
\$	SL	235.30	
\$	SL	7,323.90	
\$	SL	2,577.20	
\$	n	245.10	
\$	n	377.10	
\$	Ry	409.90	
\$	Ry	78.90	
\$	SL	686.80	X
\$	SL	19.60	X
\$	SL	98.60	X
\$	NO	151.40	
\$	NO	219.10	
\$	SL	67.00	X
\$		292.40	?
\$	n	979.40	X
\$	n	176.80	X
\$	n	62.80	X
\$	n	110.00	X
\$	n	292.50	X
\$	n Ry Ry	2,397.60	X X
\$	n	794.70	X
\$	n	184.60	X
\$	n	110.00	X
\$	n	292.10	X
\$	SL	112.70	X
\$	SL	65.30	X
\$	SL	29.60	X
\$	SL	80.10	X
\$	SL	1,783.20	
\$	Ry	1,379.50	
\$		760.10	?

- 1 JOINT ASSY, LOWER BALL, FRONT RH
- 1 KNUCKLE, STEERING, RH
- 1 LINK ASSY, FRONT STABILIZER, RH
- 1 BAR, STABILIZER, FRONT
- 1 FRONT SHOCK ABSORBER
- 1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH
- 1 GEAR ASSY, STEERING
- 1 CYLINDER ASSY, FRONT DISC BRAKE, RH
- 1 SENSOR, SPEED, FRONT RH
- 1 CROSSMEMBER SUB-ASSY, FRONT SUSPENSION
- 1 REINFORCEMENT SUB-ASSY, SIDE RAIL, REAR RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH
- 1 MOULDING ASSY, BODY ROCKER PANEL, RH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 BRACKET, HEADLAMP, RH
- 1 PANEL SUB ASSY, FRONT DOOR, RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 CHECK ASSY, FRONT DOOR
- 1 RUN, FRONT DOOR GLASS, RH
- 1 WEATHERSTRIP, FRONT DOOR, RH
- 1 TAPE, BLACK OUT, NO.1 RH
- 1 TAPE, BLACK OUT, NO.2 RH
- 1 TAPE, BLACK OUT, NO.3 RH
- 1 WIRE, FRONT DOOR, RH
- 1 MOULDING ASSY, FRONT DOOR BELT, RH

\$	283.40	?
\$	B 663.40	✓
\$	237.10	?
\$	P 367.30	X
\$	B 438.30	✓
\$	236.40	?
\$	1,955.40	?
\$	P 1,077.90	X
\$	P 543.90	X
\$	B 2,585.50	✓
\$	P 133.30	X
\$	P 1,436.60	X
\$	CM 594.80	✓
\$	N 59.30	X
\$	34.80	?
\$	N 1,300.70	} X
\$	N 97.50	
\$	N 110.60	
\$	N 183.80	
\$	P 153.60	
\$	P 231.30	
\$	N 13.30	
\$	N 43.50	
\$	N 26.30	
\$	P 532.80	
\$	P 92.00	
TOTAL	\$	47,653.20
25%	\$	11,913.30
	\$	35,739.90

Special Nett

- 1 FRONT WHEEL RIM
- 1 FRONT WHEEL RIM COVER
- 1 FRONT TYRE 195/65/15
- 1 SET CLIP, FRONT FENDER LINER
- 1 FRONT NUMBER PLATE WITH MOULDING

\$	N 1,879.40	✓
\$	N 211.50	✓
\$	P 350.00	P 0.50
\$	N 35.00	✓
\$	P 200.00	X

To Rust-Proofing Of The Affected Areas.	\$	170.00	601	
To Check Electrical Lighting Concerned.	\$	170.00	201	
To transfer of tire, rim and on wheel balancing.	\$	170.00	201	
To check steering geometry and computer wheel alignment	\$	220.00	601	
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X	
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	201	
To check ABS and brake efficiency, final checking and testing.	\$	380.00	?	
To vacuum, replace, refix and recharge air condenser	\$	380.00	101	
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	X	
Towing Fees	\$	150.00	501	
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X	
To transfer of door fittings, attachments and perform water seepage test.	\$	170.00	X	
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X	
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X	
TOTAL	\$	19,770.00		