



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2004430
INV Date 22/06/2020
Reference CS/SMO20001396/Atd3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SMG 3321M
Insured Veh. GBH 1736M
Claim No. CMTD2000380/RUC
Policy No.
Accident Date 22/01/2020
Inspection Date 23/01/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20001396/Atd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 22-06-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 1736M	Veh. Inspected	SMG 3321M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000380/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/01/2020

2. Vehicle Particulars & Condition

Make & Model	AUDI Q5	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WAUZZZF2J2129052	Colour	BROWN
Odometer	38658	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R19	MICHELIN	6 mm
L/H Front Tyre	235/55 R19	MICHELIN	6 mm
R/H Rear Tyre	235/55 R19	MICHELIN	6 mm
L/H Rear Tyre	235/55 R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/01/2020	Inspection Date	23/01/2020
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 3321M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TOP BUMPER (SN)	DEFORMED	1,619.00	1,619.00
1	REAR MIDDLE BUMPER (SN)	DEFORMED	1,114.00	1,114.00
1	REAR BUMPER SPOILER (SN)	DEFORMED	780.00	780.00
1	REAR BUMPER TOWING EYE COVER-LH (SN)	NOT NECESSARY	45.00	-
1	REAR BUMPER TOWING EYE COVER-RH (SN)	DEFORMED	27.00	26.60
2	REAR BUMPER CLOSING ELEMENT-LH/RH (SN)	NOT NECESSARY	180.00	-
2	REAR BUMPER CHROME TRIM-LH/RH (SN)	NOT NECESSARY	442.00	-
2	TAIL LIGHT-LH/RH (SN)	CRACKED	1,296.00	1,296.00
1	BOOT LID CONTROL UNIT (SN)	NOT NECESSARY	396.00	-
1	REAR BUMPER CARRIER (SN)	BENT	857.00	857.00
1	REAR BUMPER HOLDING STRAP (SN)	DAMAGED	156.00	156.00
2	REAR BUMPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	156.00	-
2	REAR BUMPER FOAM FILLER PIECE-LH/RH (SN)	NOT NECESSARY	116.00	-
4	REAR PARKING AID SENSOR (NPA)(SN)	NOT NECESSARY	-	-
4	REAR PARKING AID SEAL RING (SN)	NOT NECESSARY	14.00	-
1	REAR BUMPER WIRING SET (SN)	NOT NECESSARY	462.00	-
1	REAR LID (SN)	DENTED	3,972.00	3,972.00
2	REAR LID HINGE-LH/RH (SN)	NOT NECESSARY	432.00	-
1	REAR LID ATTACHMENT PARTS (SN)	NOT NECESSARY	114.00	-
2	REAR LID DRIVE UNIT (SN)	N/S DAMAGED	3,414.00	1,707.00
1	REAR LID FLAP GASKET (SN)	NOT NECESSARY	365.00	-
1	REAR LID LOCK STICKER (SN)	NOT NECESSARY	81.00	-
1	REAR LID LOCK (SN)	NOT NECESSARY	209.00	-
1	REAR LID SERVOMOTOR (SN)	NOT NECESSARY	277.00	-
1	REAR LID BOWDEN CABLE (SN)	NOT NECESSARY	36.00	-
1	BONNET ANTI THEFT GUARD (SN)	NOT NECESSARY	14.00	-
1	LID LOCK PUSH BUTTON (SN)	NOT NECESSARY	1,308.00	-
1	PACKING ADHESIVE (SN)	NECESSARY	18.00	17.80
1	AUDI EMBLEM (SN)	NECESSARY	117.00	116.50
1	Q5 INSCRIPTION (SN)	NECESSARY	90.00	89.70
1	TFSI INSCRIPTION (SN)	NECESSARY	90.00	89.70

Report Ref No. CS/SMO20001396/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	QUATTRO INSCRIPTION (SN)	NECESSARY	90.00	89.70
2	REAR SPOILER-LH/RH (SN)	NECESSARY	436.00	435.00
1	REAR WINDSCREEN (SN)	NECESSARY	1,066.00	1,066.00
1	PRIMER (SN)	NECESSARY	19.00	18.60
2	LED TAIL LIGHT-LH/RH (SN)	O/S CUT	3,108.00	1,554.00
2	LED LICENCE PLATE LIGHT (SN)	NOT NECESSARY	95.00	-
1	SPOILER FIXING PARTS (SN)	NECESSARY	19.00	18.60
1	LOCK CARRIER REINFORCEMENT (SN)	NOT NECESSARY	159.00	-
1	REAR CROSS PANEL (SN)	TO REPAIR SEE LABOUR	532.00	-
1	REAR LID TRIM PANEL-LOWER (SN)	NOT NECESSARY	699.00	-
1	REAR CROSS PANEL TRIM (SN)	NOT NECESSARY	431.00	-
2	REAR WHEEL COVER-LH/RH (SN)	NECESSARY	1,004.00	1,004.00
1	REAR SILENCER (SN)	NOT NECESSARY	1,281.00	-
1	REAR SILENCER DUAL CLIP (SN)	NOT NECESSARY	49.00	-
2	REAR SILENCER BRACKET (SN)	NOT NECESSARY	107.00	-
1	REAR SILENCER HEAT SHIELD (SN)	NOT NECESSARY	135.00	-
1	FRONT NO PLATE (SN)	DENTED	40.00	40.00
1	REAR NO PLATE (SN)	DENTED	40.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	200.00	200.00
1	ACRYLIC SEALANT (SN)	NOT NECESSARY	180.00	-
1	CAVITY WAX (SN)	NOT NECESSARY	140.00	-
1	STONE CHIP (SN)	NOT NECESSARY	180.00	-
1	SUNDRIES (SN)	NECESSARY	500.00	63.20
			28,707.00	16,370.40
	<u>LABOUR</u>			
	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.		360.00	360.00
	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM,WIRE HARNESS FOR TAIL LIGHT AND REAR WIPER ASSY.		480.00	480.00
	TO RENEW REAR WINDSCREEN TO FACILITATE REAR LID RENEWAL.		480.00	480.00
	TO INSTALL REAR WINDSCREEN SOLAR FILM.		400.00	400.00

Report Ref No. CS/SMO20001396/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.	NOT NECESSARY	480.00	-
	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.TO CUT OUT AND REWELD REAR END PANELLING OUTER AND INNER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF REAR CROSS PANEL.		4,800.00	1,600.00
	TO RESPRAY REAR BUMPER,HINGES,REAR LID,END PANELLING AND SPARE WHEEL HOUSING.		4,500.00	1,600.00
	TO RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION.	NOT NECESSARY	480.00	-
	TO CARRY OUT DIAGNOSTIC CHECKS.		192.00	192.00
	TO RESPRAY BOTH REAR WHEEL ARCH TRIMS (ADDITIONLA).		1,000.00	600.00
	TO REPAIR END PANNELING (ADDITIONLA).		800.00	400.00
	TO RESPRAY END PANNELING (ADDITIONLA).		1,000.00	800.00
			14,972.00	6,912.00
GRAND TOTAL			43,679.00	23,282.40

RECOMMENDED COST OF REPAIRS			23,282.40
------------------------------------	--	--	------------------

Report Ref No. CS/SMO20001396/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3321M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3321M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3321M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3321M

RE-INSPECTION

