

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27327

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0099/2020/NS
Date : 23-Jan-20

Denise 23/1/20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : GBH 1736 M

SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

Attn: Motor Claims Dept

Tel: 6461 6555 Fax 6221 3147

Owner's Name : Mr Chia Fee Hween Peter
Address : 23 Mimosa Walk
Singapore 807870
Telephone : HP +65 97394801
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SMG 3321 M**
Model Code : Q5 Sport 2.0 TFSI QU
Model / Year : Oct-18
Engine No : DAX 031594
Chassis No : WAUZZZF2J2129052
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Jan-20
Place of Accident : Upper Changi Road East

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 3321 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	✓
2	To remove and transfer rear lid's convenience lock system, wire harness for tail light and rear wiper assy.	S/N \$ 480.00 ✓	✓
3	To renew rear windscreen to facilitate rear lid renewal.	S/N \$ 480.00 ✓	✓
4	To install rear windscreen solar film.	S/N \$ 400.00 ✓	✓
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 480.00 X	X
SUB TOTAL LABOUR CHARGES		: \$ 2,200.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 3321 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dismantle and renew rear bumper and rear lid. To cut out and reweld rear end panelling outer and inner. Re-organise crash management components. Reinstall all parts removed.	S 4,800.00	1600 ✓
7	To respray rear bumper, hinges, rear lid, end panelling and spare wheel housing.	S 4,500.00	1600 ✓
8	To renew rear exhaust silencer and align to position.	S/N S 480.00 X	X
9	To carry out diagnostic checks	S/N S 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 12,172.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3321 M

Damaged Parts & Prices

S/N	Parts Description	S/Nett	Remarks
1	REAR TOP BUMPER <i>Re-lid</i>	\$ 1,619.00	✓✓
2	REAR MIDDLE BUMPER <i>Re-lid</i>	\$ 1,114.00	✓✓
3	REAR BUMPER SPOILER <i>Re-lid</i>	\$ 780.00	✓✓
4	REAR BUMPER TOWING EYE COVER - LH <i>new</i>	\$ 45.00	✗✗
5	REAR BUMPER TOWING EYE COVER - RH <i>Re-lid</i>	\$ 27.00	✓✓ 26.60
6	REAR BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	\$ 180.00	? ✗
7	REAR BUMPER CHROME TRIM - LH / RH <i>new</i>	\$ 442.00	? ✗
8	TAIL LIGHT - LH / RH <i>could</i>	\$ 1,296.00	✓ 1296
9	BOOT LID CONTROL UNIT <i>new</i>	\$ 396.00	✗
10	REAR BUMPER CARRIER <i>Best</i>	\$ 857.00	? ✓ 857
11	REAR BUMPER HOLDING STRAP <i>Re-lid</i>	\$ 156.00	? ✓ 156
12	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$ 156.00	✗
13	REAR BUMPER FOAM FILLER PIECE - LH / RH <i>new</i>	\$ 116.00	? ✗
14	REAR PARKING AID SENSOR <i>new</i>	4	TBC ✗
15	REAR PARKING AID SEAL RING <i>new</i>	4 \$ 14.00	✗
16	REAR BUMPER WIRING SET	\$ 462.00	✗
17	REAR LID <i>Dented</i>	\$ 3,972.00	✓✓
18	REAR LID HINGE - LH / RH <i>new</i>	2 \$ 432.00	✗ ✗
19	REAR LID ATTACHMENT PARTS <i>new</i>	\$ 114.00	? ✗
20	REAR LID DRIVE UNIT <i>LH Damaged</i>	2 \$ 3,414.00	✗ 1707
SUB TOTAL SPARE PARTS CHARGES		: \$ 15,592.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3321 M

Damaged Parts & Prices

S/N	Parts Description	S/Nett	Remarks
21	REAR LID FLAP GASKET	\$ 365.00	X
22	REAR LID LOCK STRIKER	\$ 81.00	X
23	REAR LID LOCK	\$ 209.00	X
24	REAR LID SERVOMOTOR	\$ 277.00	X
25	REAR LID BOWDEN CABLE	\$ 36.00	X
26	BONNET ANTI THEFT GUARD	\$ 14.00	X
27	LID LOCK PUSH BUTTON	\$ 1,308.00	X
28	PACKING ADHESIVE	\$ 18.00	✓ 17.80
29	AUDI EMBLEM	\$ 117.00	✓ 116.50
30	Q5 INSCRIPTION	\$ 90.00	✓ 89.70
31	TFSI INSCRIPTION	\$ 90.00	✓ 89.70
32	QUATTRO INSCRIPTION	\$ 90.00	✓ 89.70
33	REAR SPOILER - LH / RH	2 \$ 436.00	? 435
34	REAR WINDSCREEN	\$ 1,066.00	✓
35	PRIMER	\$ 19.00	✓ 18.60
36	LED TAIL LIGHT - LH / RH	2 \$ 3,108.00	✓ 1554. ✓
37	LED LICENCE PLATE LIGHT	2 \$ 95.00	X
38	SPOILER FIXING PARTS	\$ 19.00	✓ 18.60
39	LOCK CARRIER REINFORCEMENT	\$ 159.00	X
40	REAR CROSS PANEL	\$ 532.00	X
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,129.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3321 M

		<u>Damaged Parts & Prices</u>		<u>Remarks</u>
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>	
41	REAR LID TRIM PANEL - LOWER <i>new</i>	\$	699.00 +	
42	REAR CROSS PANEL TRIM <i>new</i>	\$	431.00 +	
43	REAR WHEEL COVER - LH / RH <i>new</i>	2 \$	1,004.00 ✓	1004 ✓
44	REAR SILENCER	\$	1,281.00 +	
45	REAR SILENCER DUAL CLIP	\$	49.00 +	
46	REAR SILENCER BRACKET	2 \$	107.00 +	
47	REAR SILENCER HEAT SHIELD	\$	135.00 +	
48	FRONT NO PLATE <i>dentid</i>	S/N \$	40.00 — ✓	
49	REAR NO PLATE <i>dentid</i>	S/N \$	40.00 — ✓	
50	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$	200.00 — ✓	
51	ACRYLIC SEALANT	S/N \$	180.00 +	
52	CAVITY WAX	S/N \$	140.00 +	
53	STONE CHIP	S/N \$	180.00 +	
54	SUNDRIES <i>Nec.</i>	\$	500.00 ? 63.20	
TOTAL SPARE PARTS CHARGES		:	\$ 28,707.00	
TOTAL LABOUR CHARGES		:	\$ 12,172.00	
GRAND TOTAL		:	\$ 40,879.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 22/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 09 days. R/S.
06 days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Sompo Insurance Singapore Pte Ltd 05-01/06 Land Tower, Raffles Place, Singapore Land Tower, Singapore 048623 Attn: Motor Claims Dept Tel: 64616555		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0100/2020/NS 29-Jan-20 Glory Tan 1 of 1 SMG 3321 M Q5 Sport 2.0 TFSI QU	
Quantity	Description	Unit Price	Amount	
Labours				
1	To respray both rear wheel arch trims. @ 300/ EACH	\$ 1,000.00	\$	600.00 ✓
2	To repair end panelling.	\$ 800.00	\$	400.00 ✓
3	To respray end panelling.	\$ 1,000.00	\$	800.00 ✓
		\$ 2,800.00	\$	1,800.00
TOTAL		\$ 2,800.00	\$	1,800.00

For Premium Automobiles Pte Ltd

Adrian King
[Signature]

Authorized Signature