

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27270

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0097/2020/NS
Date : 22-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Qian Ting Winnie (Lin Qianting)
Address : 478 Pasir Ris Drive 4
#08-421
Singapore 510478
Telephone : HP +65 91702671
Type of Claim : Own Damage Claims
Policy No. : 1800006550-01
Vehicle No : **SLV 9259 D**
Model Code : Audi A3 SEDAN 1.0 TFSI 8V
Model / Year : Jan-18
Engine No : CHZ 628994
Chassis No : WAUZZZ8V3J1038980
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Jan-20
Place of Accident : Yishun Central Multistory Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 9259 D

<u>S/N Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1 To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	✓ ✓
2 To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	✓ ✓
3 To install rear windscreen solar film.	S/N \$	400.00	✓ ✓
4 To remove and transfer lhs rear door's multi-lock and power window devices.	S/N \$	280.00	X
5 To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	✓ ✓
SUB TOTAL LABOUR CHARGES	:	<u>\$ 2,960.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 9259 D

<u>S/N Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
6 To remove and reinstall rea seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbaa etc.	S/N \$ 1,400.00	✓ ✓
7 To dismantle rear bumper, rear lid and lhs rear door. To renew rear bumper and lhs rear door. Cut out and weld lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00	3000 ✓
8 To respray rear bumper, lhs rear door, lhs rear fender, lhs sill panel door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,600.00	2750 5 x 550 = 2750 ✓
9 To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓ ✓
10 to carry out diagnostic check	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES	: <u>\$ 16,732.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 9259 D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER <i>Rep</i>	\$	1,851.00	+
2	REAR BUMPER FIXING PARTS	\$	182.00	+
3	WHEEL HOUSING LINER ADAPTER - LH	\$	36.00	+
4	REAR BUMPER GUIDE SECTION - LH / RH	2 \$	30.00	+
5	REAR BUMPER LOCKING MECHANISM	2 \$	55.00	+
6	REAR LIGHT REFLECTOR - LH / RH	\$	39.00	+
7	REAR BUMPER GUIDE SECTION - LH	\$	62.00	+
8	SIDE PANEL - LH <i>Dented</i>	\$	2,195.00	- 1756
9	REAR WINDSCREEN <i>new</i>	\$	766.00	- 612.80
10	PRIMER <i>new</i>	\$	19.00	- 14.80
11	SIDE WINDOW - LH <i>new</i>	\$	537.00	- 429.00
12	WHEEL HOUSING LINER <i>new</i>	\$	226.00	+
13	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	84.00	+
14	REAR DOOR - LH <i>Rep</i>	\$	2,375.00	+
15	REAR DOOR OUTER SEAL - LH <i>new</i>	NEC \$	151.00	+
16	BONDING AGENT	NEC \$	46.00	+
17	CLEANING SOLUTION <i>new</i>	NEC \$	64.00	+
18	REAR DOOR CATCH	\$	89.00	+
19	REAR ALUMINIUM RIM - LH <i>cut</i>	\$	666.00	- 532.40
20	ACRYLIC SEALANT <i>new</i>	S/N \$	180.00	- 180
SUB TOTAL SPARE PARTS CHARGES		:	\$ 9,653.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 9259 D

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	CAVITY WAX	S/N \$ 140.00	140
22	STONE CHIP	S/N \$ 180.00	180
23	METAL FILLER POWDER	S/N \$ 280.00	280
24	REAR WINDSCREEN SEALANT	S/N \$ 200.00	200
25	1/4 GLASS SEALANT	S/N \$ 100.00	100
26	SUNDRIES <i>Nec.</i>	\$ 400.00	? 27.92

TOTAL SPARE PARTS CHARGES : **\$ 10,953.00**
TOTAL LABOUR CHARGES : **\$ 16,732.00**
GRAND TOTAL : **\$ 27,685.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian
Surveyed Date : 23/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 12 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9823 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant