

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27083

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0094/2020/NS
Date : 22-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
5 days repair ok - Carrine

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lim Tsen Yong
Address : 89 Pasir Ris Drive
#09-24
Singapore 518214
Telephone : HP +65 90061410
Type of Claim : Own Damage Claims
Policy No. : 2100329576-06
Vehicle No : **SKH 9813 P**
Model Code : Audi A4 1.8T FSI MU 8K203
Model / Year : Jan-13
Engine No : CJE 017590
Chassis No : WAUZZZ8K6DA057923
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Jan-20
Place of Accident : Along Upper Changi Rd East

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 9813 P

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ -
2	To dismantle and renew front bumper, rhs front fender, bonnet, and rhs headlight. To cut out and reweld rhs fender top support. Re-organise crash management components. Reinstall all parts removed.	\$	5,250.00	\$ 750.00
3	To respray front bumper, rhs front fender, bonnet and rhs fender top support.	\$	4,000.00	\$ 1,100.00
4	To renew rhs front rim and carry out wheel alignment.	S/N \$	280.00	\$ -
5	To carry out diagnostic check.	S/N \$	192.00	\$ -
TOTAL LABOUR CHARGES		:	\$ 10,082.00	\$ 1,850.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 2,110.00	
2	FRONT BUMPER FIXING PARTS	\$ 244.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 215.00	
4	FRONT BUMPER VENT GRILLE - RH	\$ 127.00	
5	FRONT WHEEL SPOILER - RH	\$ 48.00	
6	FRONT BUMPER GUIDE SECTION - RH	\$ 34.00	
7	FRONT FENDER - RH	\$ 932.00	\$ 745.20
8	FRONT FENDER ATTACHMENT PARTS	\$ 54.00	
9	FRONT FENDER BRACKET - RH	\$ 50.00	
10	FRONT FENDER DEFORMATION ELEMENT BRACKET	\$ 46.00	
11	FRONT FENDER BRACE - RH LOWER	\$ 112.00	\$ 89.20
12	WHEEL HOUSING LINER	\$ 226.00	
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 42.00	
14	STONE CHIP GUARD	\$ 69.00	\$ 54.64
15	ADHESIVE TAPE	\$ 52.00	
16	BONNET	\$ 2,629.00	
17	BONNET PROTECTIVE FILM - FRONT	\$ 43.00	
18	BONNET ATTACHMENT PARTS	\$ 159.00	
19	BONNET EDGE PROTECTION - FRONT	\$ 26.00	
20	HEADLIGHT MOUNTING - RH	\$ 112.00	\$ 89.20
SUB TOTAL SPARE PARTS		: \$ 7,330.00	\$ 978.24

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	Remarks
		b/f		978.24
21	MOUNTING PLATE		\$ 100.00	\$ 79.28
22	HEADLIGHT COUPLING ELEMENT		\$ 30.00	
23	HALOGEN HEADLIGHT - RH		\$ 1,027.00	\$ 821.60
24	HALOGEN FOG LAMP - RH		\$ 247.00	
25	FENDER TOP SUPPORT CONNECTING PLATE - RH UPPER		\$ 489.00	
26	FRONT ALUMINIUM RIM - RH		\$ 710.00	
27	ACRYLIC SEALANT	S/N	\$ 180.00	
28	CAVITY WAX	S/N	\$ 140.00	
29	STONE CHIP	S/N	\$ 180.00	
30	SUNDRIES		\$ 400.00	\$ 10.24
TOTAL SPARE PARTS CHARGES		:	\$ 10,833.00	\$ 1,889.36
TOTAL LABOUR CHARGES		:	\$ 10,082.00	\$ 1,850.00
GRAND TOTAL		:	\$ 20,915.00	\$ 3,739.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.