

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 9813 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ X overlapped +
2	To dismantle and renew front bumper, rhs front fender, bonnet, and rhs headlight. To cut out and reweld rhs fender top support. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00	750 1250 overlapped -500
3	To respray front bumper, rhs front fender, bonnet and rhs fender top support. ✓ ✓ ✓	\$ 4,000.00	1100 bumper 1650 overlapped -550
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	X
5	To carry out diagnostic check.	S/N \$ 192.00	X
TOTAL LABOUR CHARGES		: \$ 10,082.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>Repr</i>	\$ 2,110.00	X
2	FRONT BUMPER FIXING PARTS	\$ 244.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>2</i>	\$ 215.00	+
4	FRONT BUMPER VENT GRILLE - RH <i>new</i>	\$ 127.00	+
5	FRONT WHEEL SPOILER - RH	\$ 48.00	+
6	FRONT BUMPER GUIDE SECTION - RH <i>2 new</i>	\$ 34.00	+
7	FRONT FENDER - RH <i>Distorted</i>	\$ 932.00	✓ 745.20.
8	FRONT FENDER ATTACHMENT PARTS <i>Re new</i>	\$ 54.00	X
9	FRONT FENDER BRACKET - RH <i>Re new</i>	\$ 50.00	X
10	FRONT FENDER DEFORMATION ELEMENT BRACKET <i>Re new</i>	\$ 46.00	X
11	FRONT FENDER BRACE - RH LOWER <i>Best</i>	\$ 112.00	✓ 89.20.
12	WHEEL HOUSING LINER <i>new</i>	\$ 226.00	+
13	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 42.00	+
14	STONE CHIP GUARD <i>new</i>	\$ 69.00	✓ 54.64
15	ADHESIVE TAPE <i>Re new.</i>	\$ 52.00	X
16	BONNET <i>Repr</i>	\$ 2,629.00	+
17	BONNET PROTECTIVE FILM - FRONT <i>2</i>	\$ 43.00	+
18	BONNET ATTACHMENT PARTS	\$ 159.00	+
19	BONNET EDGE PROTECTION - FRONT <i>2</i>	\$ 26.00	+
20	HEADLIGHT MOUNTING - RH <i>2 new</i>	\$ 112.00	✓ 89.20.
SUB TOTAL SPARE PARTS		: \$ 7,330.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9813 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	MOUNTING PLATE <i>new</i>	\$ 100.00	✓ 79.28
22	HEADLIGHT COUPLING ELEMENT <i>new</i>	\$ 30.00	+
23	HALOGEN HEADLIGHT - RH <i>new cut</i>	\$ 1,027.00	✓ 821.60
24	HALOGEN FOG LAMP - RH <i>new</i>	\$ 247.00	+
25	FENDER TOP SUPPORT CONNECTING PLATE - RH UPPER <i>new</i>	\$ 489.00	+
26	FRONT ALUMINIUM RIM - RH <i>new</i>	\$ 710.00	+
27	ACRYLIC SEALANT <i>2</i>	S/N \$ 180.00	+
28	CAVITY WAX <i>NP</i>	S/N \$ 140.00	+
29	STONE CHIP <i>new</i>	S/N \$ 180.00	+
30	SUNDRIES <i>new</i>	\$ 400.00	✓ 10.24
TOTAL SPARE PARTS CHARGES		: \$ 10,833.00	
TOTAL LABOUR CHARGES		: \$ 10,082.00	
GRAND TOTAL		: \$ 20,915.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 23/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant