

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date : 19/10/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLL9585P

CHASSIS NO : GM41105168

MAKE / MODEL : HONDA GRACE HYBRID

DATE OF ACCIDENT : 19 JAN 2020

YOUR INSURED VEHICLE NUMBER : SLW8718Y

PARTS DISCRIPTION

		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear boot ✓ <i>nn</i>	1PC	\$0.00	\$1,500.00 <i>725.40</i>
2	Rear boot weatherstrip ✓ <i>CR4</i>	1PC	\$0.00	\$160.00 ✓
3	Rear boot lock ✓ <i>Janed</i>	1PC	\$0.00	\$160.00 ✓
4	Rear boot lock catch ? <i>XSVC</i>	1PC	\$0.00	\$30.00 <i>x</i>
5	Rear boot Hybrid emblem ✓ <i>Nec</i>	1PC	\$0.00	\$78.00 ✓
6	Rear boot Honda logo ✓ <i>Nec</i>	1PC	\$0.00	\$50.00 ✓
7	Rear boot GRACE emblem ✓ <i>Nec</i>	1PC	\$0.00	\$60.00 ✓
8	Rear boot chrome moulding ? <i>XSVC</i>	1PC	\$0.00	\$360.00 <i>x</i>
9	Rear bumper ✓ <i>CR4</i>	1PC	\$0.00	\$980.00 ✓
10	Rear bumper retainer LH ✓ <i>BN</i>	1PC	\$0.00	\$42.00 ✓
11	Rear bumper retainer RH <i>XSVC</i>	1PC	\$0.00	\$42.00 <i>x</i>
12	Rear RH taillamp ? <i>XSVC</i>	1PC	\$0.00	\$690.00 <i>x</i>
13	Rear LH taillamp ✓ <i>CR4</i>	1PC	\$0.00	\$690.00 <i>381.70</i>
14	Rear boot RH reflector lamp ? <i>SCR</i>	1PC	\$0.00	\$510.00 <i>386</i>
15	Rear boot LH reflector lamp ? <i>SCR</i>	1PC	\$0.00	\$510.00 <i>380</i>
16	Rear end panel ✓ <i>nn</i>	1PC	\$0.00	\$400.00 ✓
17	Rear end panel top garnish ✓ <i>CR4</i>	1PC	\$0.00	\$170.00 ✓
18	Rear nn taillamp panel ✓ <i>nn</i>	1PC	\$0.00	\$180.00 ✓

LH

4147.1
LIST TOTAL S\$: \$6,612.00
20.00% DISCOUNT S\$: \$1,322.40
\$5,289.60 *3,317.68*

SPECIAL NETT

1	Rear bumper clips ✓ <i>Nec</i>	1 SET	\$80.00 <i>30</i>
2	Reverse sensor ✓ <i>short</i>	1 SET	\$260.00 <i>200</i>
3		1PC	
Special Nett Total S\$: \$340.00			<i>230</i>

LABOUR CHARGES

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.	\$1,500.00	1000
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER) ^{Fender}	\$1,400.00	\$1000
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	\$180.00	40.
4	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED	\$280.00	30.
5	TO CARRY OUT DIAGNOSTIC TEST	\$300.00	X 500
LABOUR TOTAL S\$:		\$3,660.00	2,070
TOTAL S\$:		\$9,289.60	
7% GST		\$650.27	
GRAND TOTAL S\$:		<u>\$9,939.87</u>	

Repair dy - 6 dys.
Lump Sum Repair
After paint photo

Sum Pin Click?
23/01/2020.
TP without prejudice.

45
\$4,500
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

$$\begin{array}{r} P = 3,317.68 \\ N = 230 \\ L = 2,070 \\ \hline 5,617.68 \\ - 20\% \\ \hline 4,494.14 \end{array}$$