

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date : 19/10/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLL9585P

CHASSIS NO : GM41105168

MAKE / MODEL : HONDA GRACE HYBRID

DATE OF ACCIDENT : 19 JAN 2020

YOUR INSURED VEHICLE NUMBER : SLW8718Y

PARTS DISCRIPTION

		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear boot ✓ <i>nn</i>	1PC	\$0.00	\$1,500.00
2	Rear boot weatherstrip ✓ <i>CHY</i>	1PC	\$0.00	\$160.00
3	Rear boot lock ✓ <i>Janed</i>	1PC	\$0.00	\$160.00
4	Rear boot lock catch ?	1PC	\$0.00	\$30.00
5	Rear boot Hybrid emblem ✓ <i>Nec</i>	1PC	\$0.00	\$78.00
6	Rear boot Honda logo ✓ <i>Nec</i>	1PC	\$0.00	\$50.00
7	Rear boot GRACE emblem ✓ <i>Nec</i>	1PC	\$0.00	\$60.00
8	Rear boot chrome moulding ?	1PC	\$0.00	\$360.00
9	Rear bumper ✓ <i>CHY</i>	1PC	\$0.00	\$980.00
10	Rear bumper retainer LH ✓ <i>BN</i>	1PC	\$0.00	\$42.00
11	Rear bumper retainer RH ✓ <i>Xsve</i>	1PC	\$0.00	\$42.00
12	Rear RH taillamp ?	1PC	\$0.00	\$690.00
13	Rear LH taillamp ✓ <i>CHY</i>	1PC	\$0.00	\$690.00
14	Rear boot RH reflector lamp ?	1PC	\$0.00	\$510.00
15	Rear boot LH reflector lamp ?	1PC	\$0.00	\$510.00
photo. 16	Rear end panel ✓ <i>nn</i>	1PC	\$0.00	\$400.00
17	Rear end panel top garnish ✓ <i>CHY</i>	1PC	\$0.00	\$170.00
18	Rear RH taillamp panel ✓ <i>nn</i>	1PC	\$0.00	\$180.00

LIST TOTAL S\$: \$6,612.00
20.00% DISCOUNT S\$: \$1,322.40
\$5,289.60

SPECIAL NETT

1	Rear bumper clips ✓ <i>Nec</i>	1 SET	\$80.00 30
2	Reverse sensor ✓ <i>short</i>	1 SET	\$260.00 200
3		1PC	
Special Nett Total S\$:			\$340.00

LABOUR CHARGES

- | | | | |
|---|---|------------|-------|
| 1 | TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN. | \$1,500.00 | 1000 |
| 2 | TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER) <i>Fender</i> | \$1,400.00 | 800 |
| 3 | TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS. | \$180.00 | 40 |
| 4 | TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED | \$280.00 | 30 |
| 5 | TO CARRY OUT DIAGNOSTIC TEST | \$300.00 | X 500 |

LABOUR TOTAL S\$:	\$3,660.00
TOTAL S\$:	\$9,289.60
7% GST	\$650.27
GRAND TOTAL S\$:	<u>\$9,939.87</u>

Repair day - 6 days.
Lump Sum Repair
After paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sum Pin CLKK?
23/01/2020.
TP without prejudice.