



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Tang Hon Chong Gabriel ADDRESS: 614b Edgefield Plains #12-311 Singapore 822614 TEL: 98550398		WIP: 43222 EXCESS: DATE: 22-Jan-20	
VEH NO:	SLR8884B	DATE IN:		CONTACT PERSON:	Eva 63310683
CHASSIS NO:	JM6GL1071H0124180	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA6	DATE REG.:	11-Sep-17	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER <i>da/</i>	1	MGJS1-50-221ABB		\$ 1,266.60
2	BRACKET CENTER <i>xm</i>	1	MKD53-50-251		\$ 5.40
3	TOWING COVER RHS <i>x sm</i>	1	MG4YL-50-EK1 64		\$ 24.90
4	RETAINER CENTER, SENSOR <i>x sm</i>	1	MKD45-67-UC5A64		\$ 18.20
5	SENSOR CENTER, ULTRASONIC <i>x sm</i>	2	MGMK6-67-UC1 64		\$ 361.80
6	TAPE PROTECTOR, SENSOR <i>re /</i>	4	MGS1D-50-EM1A		\$ 34.40
7	GROMMET, REAR BUMPER <i>re /</i>	4	MH260-50-841		\$ 12.00
8	GROMMET, REAR BUMPER <i>re /</i>	2	M9991-00-501		\$ 6.00
9	CLIP, REAR BUMPER <i>re /</i>	4	MC274-50-133		\$ 14.80
10	FASTENER, REAR BUMPER <i>re /</i>	6	MB45A-56-146A		\$ 18.00
11	REAR REINFORCEMENT <i>? xm</i>	1	MGHK1-50-260		\$ 538.30
12	GASKET LHS, TAILLAMP <i>re /</i>	1	MGJA1-51-163		\$ 27.70
13	GASKET RHS, TAILLAMP <i>re /</i>	1	MGJA1-51-153		\$ 27.70
TOTAL PARTS					\$ 2,355.80
TOTAL PARTS COST					\$ 2,355.80
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT		<i>660</i>	\$ 1,980.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL.		<i>630</i>	\$ 1,890.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		NETT	\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		<i>re x</i>	\$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 20 100.00
			TOTAL LABOUR	\$ - \$ 5,150.00
			TOTAL PARTS	\$ - \$ 2,355.80
			TOTAL	\$ - \$ 7,505.80
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorized Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Paul
Hp 90010068
3 days
03/07/2020 1110
Resy before print



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX :		NAME : Mr Tang Hon Chong Gabriel ADDRESS : 614b Edgefield Plains #12-311 Singapore 822614 TEL : 98550398		WIP : 43222 EXCESS : DATE: 22-Jan-20	
VEH NO :	SLR8884B	DATE IN :		CONTACT PERSON :	Eva 63310683
CHASSIS NO :	JM6GL1071H0124180	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	11-Sep-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MGJS1-50-221ABB	\$ 1,266.60	\$ 1,266.60
2	1	MKD53-50-251		\$ 5.40
3	1	MG4YL-50-EK1 64		\$ 24.90
4	1	MKD45-67-UC5A64		\$ 18.20
5	2	MGMK6-67-UC1 64		\$ 361.80
6	4	MGS1D-50-EM1A	\$ 34.40	\$ 34.40
7	4	MH260-50-841	\$ 12.00	\$ 12.00
8	2	M9991-00-501	\$ 6.00	\$ 6.00
9	4	MC274-50-133	\$ 14.80	\$ 14.80
10	6	MB45A-56-146A	\$ 18.00	\$ 18.00
11	1	MGHK1-50-260		\$ 538.30
12	1	MGJA1-51-163	\$ 27.70	\$ 27.70
13	1	MGJA1-51-153	\$ 27.70	\$ 27.70
TOTAL PARTS			\$ 1,407.20	\$ 2,355.80
TOTAL PARTS COST			\$ 1,407.20	\$ 2,355.80

Labour Description

1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,980.00
2		TO RESPRAY REAR BUMPER.	\$ 630.00	\$ 1,890.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 1,970.00	\$ 5,150.00
TOTAL PARTS			\$ 1,407.20	\$ 2,355.80
TOTAL			\$ 3,377.20	\$ 7,505.80
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,377.20	
GST 7%			\$ 236.40	\$ -
GRAND TOTAL			\$ 3,613.60	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)