

## TRANS EUROKARS PTE LTD



## **ESTIMATE COST OF REPAIRS**

INDIA INTERNATIONAL INSURANCE P/L NAME: Mr Tang Hon Chong Gabriel WIP: 43222

64 CECIL STREET ADDRESS : 614b Edgefield Plains **EXCESS:** 

#04-#05 IOB BUILDING #12-311 DATE: 22-Jan-20

SINGAPORE 049711 Singapore 822614

ATTN.: MOTOR CLAIMS TEL: 98550398

FAX:

SLR8884B DATE IN: VEH NO: CONTACT PERSON : Eva 63310683 **CHASSIS NO:** JM6GL1071H0124180 MILEAGE: THIRD PARTY CLAIM TYPE OF CLAIM: MODEL: DATE REG.: POLICY NO. : MAZDA6 11-Sep-17

		•	NATURE OF WOR	<u>ks</u>			
Parts Description							
NO		QTY			REVISED	PRICES	
1	REAR BUMPER		1	MGJS1-50-221ABB		\$	1,266.60
2	BRACKET CENTER	R	1	MKD53-50-251		\$	5.40
3	TOWING COVER	RHS	1	MG4YL-50-EK1 64		\$	24.90
4	RETAINER CENTE	R, SENSOR	1	MKD45-67-UC5A64		\$	18.20
5	SENSOR CENTER, ULTRASONIC		2	MGMK6-67-UC1 64		\$	361.80
6	TAPE PROTECTO	R, SENSOR	4	MGS1D-50-EM1A		\$	34.40
7	GROMMET, REAR BUMPER 4 M		MH260-50-841		\$	12.00	
8	GROMMET, REAF	R BUMPER	2	M9991-00-501		\$	6.00
9	CLIP, REAR BUM	PER	4	MC274-50-133		\$	14.80
10	FASTENER, REAR	BUMPER	6	MB45A-56-146A		\$	18.00
11	REAR REINFORCE	MENT	1	MGHK1-50-260		\$	538.30
12	GASKET LHS, TAII	LAMP	1	MGJA1-51-163		\$	27.70
13	GASKET RHS, TAI	LLAMP	1	MGJA1-51-153		\$	27.70
	TOTAL PARTS					\$	2,355.80
	TOTAL PARTS COST					\$	2,355.80
	1		<u>Labour Descripti</u>	<u>on</u>		1	
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			EL	\$	1,980.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL.				\$	1,890.00
3	MZ-BR-REVSEN	Z-BR-REVSEN TO TRANSFER REVERSE SENSORS.			NETT	\$	330.00
4	MZ-BR-CAVITY	Z-BR-CAVITY TO CARRY-OUT BODY CAVITY PRESERVATION.				\$	250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.		NETT		\$ 100.00
			TOTAL LABOUR	\$	-	\$ 5,150.00
			TOTAL PARTS	\$	-	\$ 2,355.80
			TOTAL	\$	-	\$ 7,505.80
			LESS EXCESS	\$	-	\$ -
			TOTAL AFTER EXCESS	\$	-	
			GST 7%	\$	-	\$ -
			GRAND TOTAL	\$	-	\$ -

## REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANG	i Fili	ROKARS	DTF	I TD
111/7/14	,	1011/11/15	,,,,	

**Authorised Signature**