

ASS. REC. BY

RET:

CS/MSG20001420/KV d3

72

Special Instruction:

Assigner: KEMAH

ASSIGNMENT (Office)

From (Person): Ong Zi Hui

of

MSG

Date/Time: 23/01/2020 @ 4:02pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMP 8369X

Insured:

SLX 9178T

at Workshop m/s

cheng Hoe Motor

Tel:

6481 2001

of

10 Amk Ind. Park 2A # 01-04

Policy No:

29079316ARW

Claim No:

618341

Sum Insured:

Excess:

Make of Velt:

(Client's Record)

D.O.A.

21/01/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:07pm @ 23/1/2020

Person Contacted:

Donylyn

Vehicle IN/OUT

Date/Time	Action/Instruction
	Followup ✓
	SMP 8369X - X
	SLX 9178T - X
13/1/20	Send preli revised via merimen

ASS. REC. BY:

REF: INSG/

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Smp 8389X

Yr Regn: _____

10, 19Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

1 tonner van

c.c

1496

Colour: _____

M-Black

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

4910

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

RUI1320470Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

215/60R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. _____

9 mm

L/Bal. _____

9 mm

D.O.A. _____

21/1/20

Rear

R/Bal. _____

9 mm

L/Bal. _____

9 mm

D.O.I. _____

12/2/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/32874.40Cabinn(Red 906, 2390)

RECEIVED 10 MAY 2020

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

Days Of Repair: _____

5

Resurvey No. of Trip: _____

1

Survey Fee: _____

Transportation: _____

S - RS - SI

F. n. s.

Others

TOTAL

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: _____

Mr. men

Lump Sum / I.B.I: (\$

2974.40150111619/3 - typot

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Monica Chung Pei Zhen	Date:	13 Feb 2020
<u>Preliminary Advice</u>			

Insured Vehicle No	: SLX9178T	Accident Date	: 21/01/2020
TP Vehicle No	: SMP8369X	Assignment Date	: 24/01/2020
Make	: HONDA VEZEL	Est. Duration of Repair	: 5.00
Date of Inspection	: 12/02/2020		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,880.40
Revised Amount	:S\$	2,974.40
Check Items (Estimated)	:S\$	126.48
Total	:S\$	3,100.88
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

()	The vehicle is economical/not economical for repair.
(X)	The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2020		24 Jan 2020 10:57 Edit Adj Rpt		Last:IA 13 Feb 2020 12:02		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Tan Choon Lay, ID: S7012542J		
Main Claimant:	TENG JIA XING JEREMY, ID: S8903123J		
Vehicle Reg. No.:	SMP8369X	Date of Loss:	21/01/2020 00:00 - :59 [3 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 618341	Policy/Cover Note No.:	29079316AVW Coverage: 17/04/2019 - 16/04/2020
Vehicle Reg. No. (Insured):	SLX9178T	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/02/2020]		
Adj Asg. Remarks:	on WP, Manual assigned to LKK via email on 23/01/2020. (Manual Assign). Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Dorlyn Li @ 6481 2001.		

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Thursday, 23 January, 2020 4:02 PM
To: assignments; Admin-D (LKKAuto)
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned
Attachments: SMP8369 GIA.pdf

Repair Survey (Single Joint Expert) /ENQUIRY OF LIABILITY - SMP8369X (DOA: 21/01/2020) SLX9178T (MSIG)

Manual Assigned

Dear LKK,

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Thursday, 23 January 2020 3:15 PM
To: Cheng Hoe Motor Pte Ltd (AMK) <chmamk@singnet.com.sg>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: Repair Survey (Single Joint Expert) /ENQUIRY OF LIABILITY - SMP8369X (DOA: 21/01/2020) SLX9178T (MSIG)

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Cheng Hoe Motor Pte Ltd (AMK) <chmamk@singnet.com.sg>

Sent: Thursday, 23 January 2020 12:04 PM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>

Subject: RE: Repair Survey (Single Joint Expert) /ENQUIRY OF LIABILITY - SMP8369X (DOA: 21/01/2020) SLX9178T (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi,

Our Selection as follow :

1) LKK auto Consultants Pte Ltd

** Would appreciate your assistance to advise on officer-in-charge for this case please.

Thank you.

Rgds

Dorlyn Li

Cheng Hoe Motor Pte LTd (AMK)

Tel : 64812001

On Wed Jan 22 2020 16:33:40 GMT+0800 (Singapore Standard Time) Helene Phua <helene_phua@sg.msig-asia.com> wrote:

----- Original Message -----

Hi,

We refer to your email dated 22/01/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd (closed from 23 Jan to 29 Jan)
- 6) AutoProbe Consultants
- 7) MSIG In-House Surveyors (Appointment is unavailable on 23 Jan & 24 Jan)

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1. Xing Guo Qiang	6) Chow Bo Xiong
2. Kenneth Kong	7) Siew Meng Hui
3. Marcus Chua	8) Daniel Chan
4. Ng You Han	9) Victor Png
5. Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- a. *Fast lane settlement is not applicable for cases that liability is in dispute*
- b. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!


Helene Phua
Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G |

msig.com.sg



From:

Cheng Hoe Motor Pte Ltd (AMK) <chmamk@singnet.com.sg>

Sent: Wednesday, 22 January 2020 3:55 PM

To: Claims <claims@sg.msig-asia.com>; Cheng Hoe <chmotor@singnet.com.sg>

Subject: Repair Survey (Single Joint Expert) /ENQUIRY OF LIABILITY - SMP8369X
(DOA: 21/01/2020)

EXTERNAL EMAIL:

Be careful when you click any links or open any attachment(s).

Dear Sir,

OUR CLIENT : SMP8369X

DOA : 21/01/20 @ 0650HR

YR INSURED : SLX9178T (TAN CHOON LAY)

(A) Kindly provide us your surveyor listing for the selection on the survey.

(B) Also, please advise on liability and are you agree on DIRECT SETTLEMENT?

Thank you.

Regards

Dorlyn

Cheng Hoe Motor Pte Ltd
Tel :64812001

Fax : 64821296

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	123J

Vehicle Details

Vehicle No.:	SMP8369X
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	L15B5570507
Chassis No.:	RU11320470
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$23,727.00
Original Registration Date:	17 Oct 2019
First Registration Date:	17 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$15,218.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2029
PARF Rebate Amount:	\$11,413.00

Intended COE Rebate Details

COE Expiry Date:	16 Oct 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,999.00
COE Rebate Amount:	\$26,267.00
Total Rebate Amount:	\$37,680.00

The information contained herein is correct as at 23 Jan 2020

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 21/01/2020

TP Veh Reg No: SLX9178T

Estimate No: ES2090132/AMK

Date: 12 Feb 2020

Policy No: 5113304265 DC

Veh Reg No: SMP8369X

Make/Model: HONDA VEZEL 1.5X
 CVT A

Chassis No: RU11320470

Engine No: L15B5570507

Reg. Date: 17/10/2019

Estimate Repair Cost to Vehicle No :SMP8369X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	508.50	1 PC	508.50	✓
2 REAR BUMPER CLIP	3.90	6 PC	23.40	✓
3 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓
4 TAILGATE INNER RUBBER	96.80	1 PC	96.80	✓
5 TAILGATE INNER LOCK	158.10	1 PC	158.10	✓
6 TAILGATE EMBLEM 'VEZEL'	43.00	1 PC	43.00	✓
7 TAILGATE WINDSCREEN GLASS MOULDING	153.10	1 PC	153.10	✓
8 REAR END PANEL	411.90	1 PC	411.90	✓
9 REAR END PANEL INNER TOP GARNISH	92.30	1 PC	92.30	✓
			2,588.00	
		Less 20%	517.60	2,070.40
Special Net				
10 REVERSE SENSOR	200.00	1 SET	200.00	✓
11 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
12 REAR END PANEL SEALANT	40.00	1 PC	40.00	✓
			280.00	280.00
Labour				
13 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
14 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILGATE, SPOILER & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	700.00	1 LA	700.00	500
15 PUTTY & RESPRAY REAR SIDE BUMPERS, TAILGATE, REVERSE SENSORS, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	600.00	1 LA	600.00	420
16 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
17 RUSTPROOFING	60.00	1 LA	60.00	30
			1,530.00	1,530.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 21/01/2020
TP Veh Reg No: SLX9178T

Estimate No: ES2090132/AMK
Date: 12 Feb 2020
Policy No: 5113304265 DC
Veh Reg No: SMP8369X
Make/Model: HONDA VEZEL 1.5X
CVT A
Chassis No: RU11320470
Engine No: L15B5570507
Reg. Date: 17/10/2019

Estimate Repair Cost to Vehicle No :SMP8369X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 3,880.40
			Add GST @ 7%	271.63
			Total Amount Payable	SS 4,152.03

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20001420/KVD3N2
Date: 11/03/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29079316AVW
Claimant Vehicle No :	SMP8369X	Insured Vehicle No :	SLX9178T
Date of Loss:	21/01/2020	Nature of Claim:	TP
		Claim No:	618341

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8369X	Engine No:	L15B5570507
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11320470
Reg. Date:	17/10/2019 (Man. Year: 2019)	Odometer:	4910 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,350.40	1,854.40	496.00	21.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,120.00	410.00	26.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,880.40	2,974.40	906.00	23.35
+ GST 7.00/7.00% (S\$)	271.63	208.21	63.42	23.35
Nett Amount (S\$)	4,152.03	3,182.61	969.42	23.35

INSPECTION

Date of Assignment:	24/01/2020	Cheng Hoe Motor Pte Ltd (AMK)
Date Inspected:	12/02/2020 Inspected At:	10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT
Estimated Period of Repair:	5.0 days	Singapore 568047

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP8369X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	508.50 FL	*508.50 FL
2	6		*REAR BUMPER CLIP	Necessary	23.40 FL	*23.40 FL
3	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
4	1		*TAILGATE INNER RUBBER	Cut	96.80 FL	*96.80 FL
5	1		*TAILGATE INNER LOCK	Repair	158.10 FL	*- FL
6	1		*TAILGATE EMBLEM VEZEL	Necessary	43.00 FL	*43.00 FL
7	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	153.10 FL	*153.10 FL
8	1		*REAR END PANEL	Repair	411.90 FL	*- FL
9	1		*REAR END PANEL INNER TOP GARNISH	Mtg Cracked	92.30 FL	*92.30 FL
10	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
11	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
12	1		*REAR END PANEL SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,868.00	2,258.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	517.60	403.60
Total Parts (\$\$)	2,350.40	1,854.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILGATE, SPOILER & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	New	700.00	500.00
3	PUTTY & RESPRAY REAR SIDE BUMPERS, TAILGATE, REVERSE SENSORS, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	New	600.00	420.00
4	REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	New	50.00	50.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,530.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >