



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

20/01/2020

Blk C 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China.

Asher.

JN1TAAE12Z0972471

Accident date: 20/01/2020

Estimated repair cost for vehicle no: SLG8254C NISSAN NOTE 1.2 A '16

CHASSIS: JN1TAAE12Z0972471

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$847.80 <i>X</i>
2	2	Front Bonnet Hinge <i>Not New</i>	\$35.00	\$70.00 <i>X</i>
3	2	Front Headlamp <i>crushed</i>	\$1,614.60	\$3,229.20 <i>✓</i>
4	2	Front Headlamp Lower Bracket <i>Not New</i>	\$28.10	\$56.20 <i>X</i>
5	1	Front Grille <i>crushed</i>		\$276.70 <i>✓</i>
6	1	Front Grille Emblem Logo <i>New</i>		\$29.10 <i>✓</i>
7	1	Front Grille Top Cover <i>crushed</i>		\$194.40 <i>✓</i>
8	1	Front Bumper <i>deformed</i>		\$394.30 <i>✓</i>
9	2	Front Bumper Side Retainer <i>New</i>	\$35.20	\$70.40 <i>✓</i>
10	2	Front Bumper Fog Lamp Cover <i>2 New</i>	\$130.20	\$260.40 <i>X</i>
11	1	Front Bumper Towing Cover <i>New</i>		\$29.20 <i>X</i>
12	1	Front Bumper Inner Foam <i>crushed</i>		\$219.00 <i>✓</i>
13	1	Front Bumper Reinforcement <i>Bent</i>		\$495.00 <i>341.60</i>
14	2	Front Bumper Reinforcement Bracket <i>Not New</i>	\$94.80	\$189.60 <i>X</i>
15	1	Front Support Panel <i>Not New</i>		\$315.80 <i>X</i>
16	1	Front Support Panel Top Cover <i>Not New</i>		\$276.70 <i>X</i>
17	1	Rear Boot Lid <i>Distorted</i>		\$1,294.50 <i>1126.10</i>
18	2	Rear Boot Lid Hinge <i>Not New</i>	\$84.90	\$169.80 <i>X</i>
19	2	Rear Boot Lid Shock Absorber <i>Not New</i>	\$218.20	\$436.40 <i>X</i>
20	1	Rear Boot Lid Emblem Logo <i>2 New</i>		\$64.90 <i>✓</i>
21	1	Rear Boot Lid Note Logo <i>New</i>		\$94.90 <i>✓</i>
22	2	Rear Boot Lid Number Plate Lamp <i>New</i>	\$97.10	\$194.20 <i>X</i>
23	1	Rear Boot Lid Center Moulding <i>crushed</i>		\$255.60 <i>✓</i>
24	1	Rear Boot Lid Lock <i>Damaged</i>		\$198.10 <i>✓</i>
25	1	Rear Boot Lid Weatherstrip <i>cut</i>		\$86.20 <i>✓</i>
26	1	Rear Boot Lid Inner Trim Board <i>crushed</i>		\$198.00 <i>✓</i>
27	1	Rear Boot Lid Windscreen Moulding <i>New</i>		\$76.50 <i>✓</i>

28	2	Rear Taillamp <i>lit</i>	\$435.80	\$871.60 ✓
29	2	Rear Taillamp Panel <i>Regr</i>	\$186.20	\$372.40 ✗
30	1	Rear Bumper <i>Distorted</i>		\$460.00 ✓
31	2	Rear Bumper Side Retainer <i>new</i>	\$55.10	\$110.20 ✓
32	2	Rear Bumper Side Reflector <i>not new</i>	\$66.60	\$133.20 ✗
33	2	Rear Bumper Bracket <i>Dented</i>	\$96.90	\$193.80 ✓
34	1	Rear Bumper Inner Foam <i>cracked</i>		\$125.30 ✓
35	1	Rear End Panel <i>Distorted</i>		\$552.80 ✓
36	1	Rear End Panel Top Garnish <i>deformed</i>		\$85.00 ✓
37	2	Rear Fender <i>Regr</i>	\$909.00	\$909.00 ✗
38	2	Rear Fender Cowling <i>not new</i>		\$55.10 ✗
39	2	Rear Fender Inner Trim Board <i>cracked</i>		\$378.40 ✓
40	1	Rear Spare Tyre Panel <i>Buckled</i>		\$891.00 ✓
41	1	Rear Spare Tyre Panel Top Cover <i>to/r</i>		\$197.20 ✓
42	1	Rear Spare Tyre Panel Inner Foam <i>deformed</i>		\$433.70 ✗
43	2	Rear Exhaust Mounting <i>new</i>	\$37.10	\$74.20 ✗
44	1	Rear Boot Lid Wiper Motor <i>Damaged</i>	565	
			Subtotal :-	\$15,585.80

11573.30
10415.97

S/n	Qty	Items / Special Nett	U/price	Amount
44	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 -20
45	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
46	1	Front Bumper Number Plate <i>Bent</i>		\$50.00 ✓
47	1	Front Air-Con Condenser <i>?</i>		\$655.00 ✗
48	1	Front Radiator <i>not new</i>		\$689.60 ✗
49	1	Front Radiator Fan Motor Assy <i>?</i>		\$891.40 ✗
50	1	Rear Boot Lid Number Plate <i>Bent</i>		\$50.00 ✓
51	1	Rear Boot Lid Wiper Arm <i>not new</i>		\$92.00 ✗
52	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 -30
53	1	Rear Boot Lid Reverse Camera <i>new</i>		\$850.00 ✗
54	4	Rear Taillamp Clip <i>new</i>	\$8.00	\$32.00 ✓
55	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
56	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 200
57	1	Rear Antenna <i>cracked</i>		\$238.80 85
58	1	Rear Buzzer Sensor <i>not new</i>		\$91.70 ✗
59	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 -60
60	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00 -150
61	1	Rear Exhaust <i>Bent</i>		\$552.00 ✓
62	1	Rear Center Exhaust <i>not new</i>		\$440.80 ✗

1289

Subtotal :- \$5,801.30

Labour charges

To remove & refit cushion & trim board	\$380.00 100
To remove & refit reverse camera	\$180.00 50
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 80
To remove & refit rear windscreen	\$150.00 120
Gum	\$60.00 ✓
To remove & refit rear L/H & R/H fender glass	\$240.00 X
Gum	\$120.00 X
Towing fee	\$150.00 X
Tuff kote	\$150.00 80
To check wiring	4000 \$100.00 60
Panel beating	\$2,400.00 2000
Spray painting	\$2,200.00 1400

Subtotal :- \$6,610.00

Total:- \$27,997.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 15704.97

4/s: 12.51c

13 Days.

12.51c