

ASS. REC. BY:

REF:

CS/CTI20001451/CTD302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Irene Tay

of

CTI

Date/Time: 24/01/2020 @ 9:16am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF3361M

Insured:

SLC 1596H

At Workshop m/s

Kah Motor

Tel:

82886309

of

No. 255 Alexandra Road

Policy No: DMPEST30963619022

Claim No:

SNM200200475C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/01/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:30am @ 24/1/2020

Person Contacted:

jack

Vehicle IN/OUT

Date/Time

Action/Instruction

Johnnie

SJF3361M-X

SLC 1596H- NA/CTI20001415/13

D.O.A: 23/01/2020

REF: STP

REF: C11

ASSIGNMENT

Form: _____ Date: 28/01/2020

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJF 3361M

at Workshop with: Kah Motor

of: No. 255 Alexandra Road

Insured: _____

Policy No.: _____

Claims No.: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Jack @ 8288 6309

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJF 3361 M Yr Regn: 27/5/08

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1595

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 142653 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM F045708 S201422

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / STD A/Rim or

Tyre Size: F: 205/55R16 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/1/20 D.O.I. 28/1/20

Survey held at Kah Motor

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV - 25,000</u>
	<u>PV - 12,761</u>
	<u>INV - 12,240</u>
<u>11/2/20</u>	<u>Final \$10,559.72, 9 days (Jack)</u>
	<u>Red: 4662.36 30°N</u>
	<u>RECEIVED 12 FEB 2020</u>

Date/Time, File Pass to? _____

23/1 Typist ☐ : Prel. Report ☒ : Final Report

Date/Time, File Return to? _____

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

Site Insp: ☐ \$ _____

Interview: ☐ \$ _____

Tech. Insp: ☐ \$ _____

Met. Insp: ☐ \$ _____

Report Format: TP

Lump Sum / H.R. : 10,559.72

Survey Fee: 220

Transportation: _____

Site Insp: _____

Interview: _____

Tech. Insp: _____

Met. Insp: _____

Report Format: _____

Lump Sum / H.R. : _____

Survey Fee: 220

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Friday, 24 January 2020 9:16 AM
To: jackng@honda.com.sg
Cc: Admin A; assignments
Subject: FW: ACCIDENT BETWEEN SJF 3361 M AND YOUR INSURED SLC 1596 H
Attachments: SAS2739846.PDF

Importance: High

Dear Jack,

Liability is down on our insured.

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with Jack from Honda to conduct survey.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jack Ng [mailto:jackng@honda.com.sg]
Sent: Thursday, January 23, 2020 3:58 PM
To: DL-CLAIMS <claims@sg.cntaiping.com>
Subject: ACCIDENT BETWEEN SJF 3361 M AND YOUR INSURED SLC 1596 H
Importance: High

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report.

Thank you and have a great days ahead

Cheers !!!

Best Regards,
Jack Ng

Tel: 8288 6309

Email: jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2020 15:51
Date Of Accident	23/01/2020 12:25
Exact Location Of Accident	ALONG AYE TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF3361M
Insured/Policyholder	
Name Of Registered Owner	LIM GEOK HONG
NRIC No	SXXXX115B
Email Address	CURATEDRECORDS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94380980
Alternative Phone No	OFFICE-94380980

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LIM XUXIANG
NRIC No	SXXXX865G
Date Of Birth	01/02/1984
Occupation	INDOOR
Date Of Driving Pass	28/07/2004
Driving Experience	15 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98439287
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 423 FAJAR ROAD
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC1596H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMJ5537D
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SHD4454G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 115B

Vehicle Details

Vehicle No.: SJF3361M

Vehicle to be Exported: No

Intended Deregistration Date: 23 Jan 2020

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6L VTi SMT

Primary Colour: White

Manufacturing Year: 2008

Engine No.: R16A13004025

Chassis No.: JHMFD45208S201422

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$19,268.00

Original Registration Date: 27 May 2008

First Registration Date: 27 May 2008

Transfer Count: 0

Actual ARF Paid: \$21,195.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 May 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$19,096.00

COE Rebate Amount: \$12,761.00

Total Rebate Amount: \$12,761.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Jan 2020

OK



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SJF3361M

Chassis No : JHMF45208S201422

Model : CIVIC 1.6L MT

Owner's Name : LIM GEOK HONG

Ins Policy No. :

Date of Accident : 23/1/2020

Document No. : SQT20000401

Date : 24. Jan 2020

Customer No. : WZC008

Svc Advisor : JACK NG

Engine No : R16A13004025

Date | Time : 24. Jan 2020 9:29:39 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIM GEOK HONG OWNER INSURER: TOKIO MARINE ACC DATE: 23/01/2020 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SJF 3361 M						
04715-SNB-000ZZ	FACEREAR BUMPER / <i>OK</i>	1	771.50	5	732.92 <i>715.5</i>	51.30	784.22
71193-SNB-003	SPACERR FR BUMPER SIDE / <i>OK</i>	1	13.80 <i>16.50</i>	5	13.11 <i>15.67</i>	0.92	14.03
71198-SNB-003	SPACERL FR BUMPER SIDE / <i>OK X MN</i>	1	13.80	5	13.11	0.92	14.03
91503-SZ3-003	CLIP ABUMPER / <i>OK</i>	2	3.90	5	7.41	0.52	7.93
91505-S9A-003	CLIP ABUMPER / <i>OK</i>	8	3.90	5	29.64	2.07	31.71
75722-SNB-J01	EMBLEMRR (CIVIC) / <i>OK</i>	1	32.90	5	31.25	2.19	33.44
75725-SNA-K01	EMBLEMRR (I-VTEC) / <i>OK</i>	1	37.30	5	35.43	2.48	37.91
75701-SNB-003	EMBLEMRR (H) / <i>OK</i>	1	30.20	5	28.69	2.01	30.70
91512-SR3-004	CLIP TUBULAR / <i>OK X MN</i>	2	2.40	5	4.56	0.32	4.88
68500-SNB-G00ZZ	LIDTRUNK / <i>OK</i>	1	610.70	5	580.16	40.61	620.77
74865-SNA-003	W/STRIPTRUNK LID / <i>OK X MN</i>	1	90.40	5	85.88	6.01	91.89
66100-SNA-U02ZZ	PANELREAR / <i>OK</i>	1	329.20	5	312.74	21.89	334.63
Sum Item					<u>1874.90</u>	<u>131.24</u>	<u>2,006.14</u>
BOSUN	SUNDRIES	1	100.00		<i>50</i> 100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	150.00		<i>120</i> 150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR END PANEL <i>OK</i>	1	150.00		<i>120</i> ? 150.00	10.50	160.50
BOBC	BODY UNDERSIDE COATING (N)	1	350.00		<i>350</i> ? 350.00	24.50	374.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00		<i>380</i> 380.00	26.60	406.60

Printed on 24/1/2020 9:42:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SJF3361M

Chassis No : JHMF45208S201422

Model : CIVIC 1.6L MT

Owner's Name : LIM GEOK HONG

Ins Policy No. :

Date of Accident : 23/1/2020

Document No. : SQT20000401 **Page** 2

Date : 24. Jan 2020

Customer No. : WZC008

Svc Advisor : JACK NG

Engine No : R16A13004025

Date | Time : 24. Jan 2020 9:29:39 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00		380.00	26.60	406.60
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	800.00	560	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	560	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS (W/ P1 - 180(S 42))	1	5000.00	1800 1680	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 450 x J	1	3000.00	1750	3000.00	210.00	3210.00
Sum Labor					11110.00	777.70	11,887.70

Survey By : STEVE (LKK)

Date & Time : 28/1/20, 1.30pm

Excess : R 0.00

Status : 9 days

Signature : P/P

Total Amount 12,984.90 908.94 13,893.84

Total (Inclusive of GST) 13,893.84

15222.06 ✓
15224.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 24/1/2020 9:42:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0016022 / CHINA TAIPING
Chassis No: JHMFD45208S201422
License No: SJF3361M
Mileage: 242700
Engine No: R16A13004025

Document No: SVO20006537
Printed By: JACKNG
Order Date: 29. January 2020
Order Time: 12:48:59 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIM GEOK HONG OWNER INSURER: TOKIO MARINE ACC DATE: 23/01/2020 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SJF 3361 M SUPPLEMENTARY PART						
04715-SNB-010ZZ	FACE REAR BUMPER	1	749.00	5	711.55	49.81	761.36
71593-SNA-A01	SPACER RR BUMPER SIDE	1	16.50	5	15.67	1.10	16.77
91503-SZ3-003	CLIP ABUMPER	2	3.90	5	7.41	0.52	7.93
91505-S9A-003	CLIP ABUMPER	8	3.90	5	29.64	2.07	31.71
75722-SNB-J01	EMBLEM RR (CIVIC)	1	32.90	5	31.25	2.19	33.44
75725-SNA-K01	EMBLEM RR (I-VTEC)	1	37.30	5	35.43	2.48	37.91
75701-SNB-003	EMBLEM RR (H)	1	30.20	5	28.69	2.01	30.70
68500-SNB-G00ZZ	LID TRUNK	1	610.70	5	580.16	40.81	620.77
66100-SNA-U02ZZ	PANEL REAR	1	329.20	5	312.74	21.89	334.63
74851-SNA-G22	LOCK TRUNK (SM) BT	1	219.50	5	208.52	14.60	223.12
74852-SDA-A21	SNAP (SM) NEC	1	2.70	5	2.56	0.18	2.74
74853-SDA-A21	WASHER (SM) NEC	1	2.10	5	1.99	0.14	2.13
74855-SNA-A01	SILENCER (SM) NEC	1	1.70	5	1.61	0.11	1.72
33551-SNB-003	LAMP UNIT L (SM) BR	1	255.20	5	242.44	16.97	259.41
34156-SNB-023	LAMP UNIT L (SM) BR	1	164.60	5	156.37	10.95	167.32
33501-SNB-003	LAMP UNIT R (SM) BR	1	255.20	5	242.44	16.97	259.41
34151-SNB-023	LAMP UNIT R (SM) CRT	1	164.60	5	156.37	10.95	167.32
RS-2P	BUMPER SENSOR 2PCS (SM) Short	1	150.00		150.00	10.50	160.50
74854-SNA-A01	WASHER (SM) NEC	1	1.70	5	1.61	0.11	1.72
84640-SNA-A01ZA	LINING RR PANEL (SM) CRU	1	66.60	5	63.27	4.43	67.70
	SUM PARTS:				2,979.72	208.59	3,188.31
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	120.00		120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	120.00		120.00	8.40	128.40
BOBC	BODY UNDERSIDE COATING (N)	1	350.00		350.00	24.50	374.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST (N)	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00		380.00	26.60	406.60
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID. ADJUST & ALIGN.	1	560.00		560.00	39.20	599.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0018022 / CHINA TAIPIING
Chassis No: JHMFD45208S201422
License No: SJF3361M
Mileage: 242700
Engine No: R16A13004025

Document No: SVO20006537
Printed By: JACKNG
Order Date: 29. January 2020
Order Time: 12:48:59 PM
Service Advisor: JACK NG

BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00	560.00 /	39.20	599.20
BKRP02M	1466 CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	2,800.00	2,800.00 /	196.00	2,996.00
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,350.00	1,350.00 /	94.50	1,444.50
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	560.00	560.00 /	39.20	599.20
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	450.00	450.00 /	31.50	481.50

SUM LABOUR: 7,580.00 530.60 8,110.60**TOTAL SGD** 10,559.72 739.19 11,298.91**Total Payable (SGD)** 11,298.91

GST Amount is calculated from individual line(s).

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651 Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937 Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Supplementary

Customer: CU0016022 / LIM GEOK HONG
 Chassis No: JHMFD45208S201422
 License No: SJF3361M
 Mileage: 242700
 Engine No: R16A13004025

Document No: SVO20006537
 Printed By: JACKNG
 Order Date: 29. January 2020
 Order Time: 12:48:59 PM
 Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
74851-SNA-G22	LOCK TRUNK	1	219.50	25	164.62	11.52	176.14
74852-SDA-A21	SNAP	1	2.70	25	2.02	0.14	2.16
74853-SDA-A21	WASHER	1	2.10	25	1.57	0.11	1.68
74855-SNA-A01	SILENCER	1	1.70	25	1.27	0.09	1.36
33551-SNB-003	LAMP UNIT L	1	255.20	25	191.40	13.40	204.80
34156-SNB-023	LAMP UNIT L	1	164.60	25	123.45	8.64	132.09
33501-SNB-003	LAMP UNIT R	1	255.20	25	191.40	13.40	204.80
34151-SNB-023	LAMP UNIT R	1	164.60	25	123.45	8.64	132.09
R5-2P	BUMPER SENSOR 2PCS	1	150.00	25	112.50	7.88	120.38
74854-SNA-A01	WASHER	1	1.70	25	1.27	0.09	1.36
84640-SNA-A01ZA	LININGRR.PANEL	1	66.60	25	49.95	3.50	53.45
	SUM PARTS:				1,000.40	70.03	1,070.43
BKRP02M	CUT OFF & RENEW RR PANEL RENEW ALL DAMAGE PARTS FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	580.00		580.00	39.20	599.20
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	450.00		450.00	31.50	481.50
	SUM LABOUR:				1,010.00	70.70	1,080.70
	TOTAL SGD				2,010.40	140.73	2,151.13

Total Payable (SGD)

2,151.13

GST Amount is calculated from individual line(s)

2237.18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2020		11 Feb 2020 16:54 Edit Adj Rpt	S\$10,559.72 Edit Estimates	S\$10,559.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	LIM GEOK HONG , ID: S01741158								
Vehicle Reg. No.:	SJF3361M	Date of Loss:	23/01/2020 12:00 - :59 [139 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200475C02	Policy/Cover Note No.:	DMPCSN30963619022						
Vehicle Reg. No. (Insured):	SLC1596H	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (alexandra) (HQ) 255 Alexandra Road, 159937 Alexandra - Tel: 6514 5481								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 20/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJF3361M (SNM20D200475C02)

[SLC1596H]

TP

LIM GEOK HONG

Jan 23 2020 12:00PM

[-]

Kah Motor Co Sdn Bhd (alexandra)

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail	Print	
1	23/01/20 15:55	Accident Statement						Load HTM		
Photos/Images							3 per page		☒	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail	Print	
1	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
2	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
3	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
4	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
5	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
6	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
7	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
8	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
9	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
10	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
11	23/01/20 15:55	Accident Photo [Linked Accident Report Documents]						Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	11/02/20 17:06	General View						Load JPG	☒	
2	11/02/20 17:06	General View						Load JPG	☒	
3	11/02/20 17:06	General View						Load JPG	☒	
4	11/02/20 17:06	General View						Load JPG	☒	
5	11/02/20 17:06	General View						Load JPG	☒	
6	11/02/20 17:06	General View						Load JPG	☒	
7	11/02/20 17:06	General View						Load JPG	☒	
8	11/02/20 17:06	General View						Load JPG	☒	
9	11/02/20 17:06	General View						Load JPG	☒	
10	11/02/20 17:06	General View						Load JPG	☒	
11	11/02/20 17:06	General View						Load JPG	☒	
12	11/02/20 17:06	General View						Load JPG	☒	
13	11/02/20 17:06	General View						Load JPG	☒	
14	11/02/20 17:06	General View						Load JPG	☒	
15	11/02/20 17:06	General View						Load JPG	☒	
16	11/02/20 17:06	General View						Load JPG	☒	
17	11/02/20 17:06	General View						Load JPG	☒	
18	11/02/20 17:06	General View						Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
19	11/02/20 17:06	General View		☒
20	11/02/20 17:06	General View		☒
21	11/02/20 17:06	General View		☒
22	11/02/20 17:06	General View		☒
23	11/02/20 17:06	General View		☒
24	11/02/20 17:06	General View		☒
25	11/02/20 17:06	General View		☒
26	11/02/20 17:06	General View		☒
27	11/02/20 17:06	General View		☒
28	11/02/20 17:06	General View		☒
29	11/02/20 17:06	General View		☒
30	11/02/20 17:06	General View		☒
31	11/02/20 17:06	General View		☒
32	11/02/20 17:06	General View		☒
33	11/02/20 17:06	General View		☒
34	11/02/20 17:07	Reinspection Photo		☒
35	11/02/20 17:07	Reinspection Photo		☒
36	11/02/20 17:07	Reinspection Photo		☒
37	11/02/20 17:07	Reinspection Photo		☒
38	11/02/20 17:07	Reinspection Photo		☒
39	11/02/20 17:07	Reinspection Photo		☒
40	11/02/20 17:07	Reinspection Photo		☒
41	11/02/20 17:07	Reinspection Photo		☒
42	11/02/20 17:07	Reinspection Photo		☒
43	11/02/20 17:07	Reinspection Photo		☒
44	11/02/20 17:07	Reinspection Photo		☒
45	11/02/20 17:07	Reinspection Photo		☒
46	11/02/20 17:07	Reinspection Photo		☒
47	11/02/20 17:07	Reinspection Photo		☒
48	11/02/20 17:07	Reinspection Photo		☒
49	11/02/20 17:07	Reinspection Photo		☒
50	11/02/20 17:07	Reinspection Photo		☒
51	11/02/20 17:07	Reinspection Photo		☒
52	11/02/20 17:07	Photo Before Spray		☒
53	11/02/20 17:07	Photo Before Spray		☒
54	11/02/20 17:07	Photo Before Spray		☒
55	11/02/20 17:07	Photo Before Spray		☒
56	11/02/20 17:07	Photo Before Spray		☒
Documentation			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	23/01/20 15:55	Sketch Plan [Linked Accident Report Documents]		☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/20 16:41	Supplementary		☐

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	23/01/20 15:55	Accident Statement	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	23/01/20 15:55	Accident Photo	 Load JPG	☒
2	23/01/20 15:55	Accident Photo	 Load JPG	☒
3	23/01/20 15:55	Accident Photo	 Load JPG	☒
4	23/01/20 15:55	Accident Photo	 Load JPG	☒
5	23/01/20 15:55	Accident Photo	 Load JPG	☒
6	23/01/20 15:55	Accident Photo	 Load JPG	☒
7	23/01/20 15:55	Accident Photo	 Load JPG	☒
8	23/01/20 15:55	Accident Photo	 Load JPG	☒
9	23/01/20 15:55	Accident Photo	 Load JPG	☒
10	23/01/20 15:55	Accident Photo	 Load JPG	☒
11	23/01/20 15:55	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	23/01/20 15:55	Sketch Plan	 Load TIF	☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120001451/ETD3E2

Date: 12/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30963619022
Claimant Vehicle No: SJF3361M Insured Vehicle No: SLC1596H
Date of Loss: 23/01/2020 Nature of Claim: TP Claim No: SNM20D200475C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJF3361M
Make & Model: HONDA CIVIC, 1.6 (A) Engine No: R16A13004025
Reg. Date: 27/05/2008 (Man. Year: 2008) Chassis No: JHMFD45208S201422
Colour: White Odometer: 242653 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,204.64	3,029.72	174.92	5.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,020.00	7,530.00	4,490.00	37.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,224.64	10,559.72	4,664.92	30.64
+ GST 7.00/7.00% (S\$)	1,065.72	739.18	326.54	30.64
Nett Amount (S\$)	16,290.36	11,298.90	4,991.46	30.64

INSPECTION

Date of Assignment: 11/02/2020
Date Inspected: 28/01/2020 Inspected At: Kah Motor Co Sdn Bhd (alexandra) (HQ)
255 Alexandra Road
Singapore 159937
Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2020)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF3361M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACEREAR BUMPER	Dented	732.92 FS	*711.55 FS
2	1		*SPACERR RR BUMPER SIDE	Broken	15.67 FS	*15.67 FS
3	1		*SPACERL FR BUMPER SIDE	Not Necessary	13.11 FS	*. FS
4	1		*CLIP, ABUMPER (2PCS)	Necessary	7.41 FS	*7.41 FS
5	1		*CLIP ABUMPER (8PCS)	Necessary	29.64 FS	*29.64 FS
6	1		*EMBLEMRR (CIVIC)	Necessary	31.25 FS	*31.25 FS
7	1		*EMBLEMRR (I-VTEC)	Necessary	35.43 FS	*35.43 FS
8	1		*EMBLEMRR (H)	Necessary	28.69 FS	*28.69 FS
9	2		*CLIP TUBULAR	Not Necessary	4.56 FS	*. FS
10	1		*LIDTRUNK	Dented	580.16 FS	*580.16 FS
11	1		*W/STRIPTRUNK LID	Not Necessary	85.88 FS	*. FS
12	1		*PANELREAR	Dented	312.74 FS	*312.74 FS
13	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
14	1		*LOCK TRUNK	Bent	208.52 FS	*208.52 FS
15	1		*SNAP	Necessary	2.56 FS	*2.56 FS
16	1		*WASHER	Necessary	1.99 FS	*1.99 FS
17	1		*SILENCER	Necessary	1.61 FS	*1.61 FS
18	1		*LAMP UNIT L	Broken	242.44 FS	*242.44 FS
19	1		*LAMP UNITL.	Broken	156.37 FS	*156.37 FS
20	1		*LAMP UNIT R	Broken	242.44 FS	*242.44 FS
21	1		*LAMP UNITR.	Cut	156.37 FS	*156.37 FS
22	2		*BUMPER SENSOR	Shorted	150.00 FS	*150.00 FS
23	1		*WASHER	Necessary	1.61 FS	*1.61 FS
24	1		*LININGRR.PANEL	Crushed	63.27 FS	*63.27 FS
Total Parts (\$\$)					3,204.64	3,029.72

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY JOINT SEALANT FOR TAILGATE	New	150.00	120.00
2	BODY JOINT SEALANT FOR END PANEL	New	150.00	120.00
3	BODY UNDERSIDE COATING	New	350.00	350.00
4	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	380.00	280.00
5	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	380.00	380.00
6	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	800.00	560.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	800.00	560.00
8	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS	New	5,000.00	2,800.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	1,350.00
10	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS. FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	New	560.00	560.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	New	450.00	450.00
Gross Labour Cost (\$\$)			12,020.00	7,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >