

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

3 Days.

Supplementary Estimate 1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534
Attn: Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Estimate No. PA/TP/0101/2020/NS
Date 6-Mar-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SLG 1983 C
Model No Honda Civic

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Acrylic sealant	\$	180.00
2	Cavity wax	\$	140.00
3	Stone chip	\$	180.00

Labours

1	To carry out first measurement test on car-o-liner.	S/N \$	800.00	200 - photo
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	480.00	40
3	To cut out and weld rear end panelling. To repair spare wheel housing and lhs chassis member.	350 \$	3,500.00	1050
4	To respray rear end panelling, spare wheel housing and lhs chassis member. To carry out stone chip treatment and joint sealant works.	350 \$	2,800.00	700
5	To place vehicle on car-o-liner.	S/N \$	2,400.00	X
6	To carry out wheel alignment.	S/N \$	240.00	X
TOTAL		\$	10,720.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 1983 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	40
2	To renew rear windscreen to facilitate rear lid renewal.	S/N \$ 400.00	X
3	To install rear windscreen solar film.	S/N \$ 400.00	X
4	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	100
5	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender and lhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1000 700
6	To respray rear bumper, rear lid, lhs rear fender and lhs tail lamp panel.	\$ 3,900.00	1000 700
7	To carry out diagnostic check.	S/N \$ 192.00	X
TOTAL LABOUR CHARGES		: \$ 8,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER ✓	\$	750.00
2	REAR BUMPER SPOILER ✓	\$	105.00
3	REAR BUMPER REFLECTOR-LH X	\$	45.00
4	REAR BUMPER VENT GRILLE-LH ✓	\$	36.00
5	REAR BUMPER REINFORCEMENT BAR ✓	\$	375.00
6	REAR BUMPER GUIDE-LH/RH ✓ R/X	2 \$	33.00
7	REAR BUMPER BRACKET-LH/RH ?	2 \$	15.00
8	REAR BUMPER WIRING ?	\$	105.00
9	REAR BUMPER SPONGE ?	\$	20.00
10	REAR BUMPER TOW COVER ✓	\$	20.00
11	REAR LID ✓	\$	960.00
12	REAR LID WEATHER STRIP ?	\$	90.00
13	REAR LID LOGO ✓	\$	60.00
14	REAR LID " HONDA CIVIC " EMBLEM ✓	\$	60.00
15	REAR LID " I-VTEC " EMBLEM ✓	\$	60.00
16	REAR LID HINGE LH/RH X	\$	120.00
17	TAILLIGHT INNER LH/RH ?	\$	510.00
18	TAILLIGHT OUTER LH/RH ?	\$	960.00
19	REAR END PANEL ✓	\$	540.00
20	REAR END PANEL TOP GARNISH ?	\$	60.00
SUB-TOTAL SPARE PARTS		\$	2,310.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved; Remarks (X) = Not approved.

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Guo Qiny - 82880282
Surveyed Date : 21/01/2020
Authorised Date :
Excess Cost : before paint photos.
Liability :
Remarks : 7 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27372

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0101/2020/NS
Date : 23-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SBT 3335 K

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Siah Yu Jun Ivan
Address : 178 Cranberra Drive
#05-17
Singapore 767951
Telephone : HP +65 96217285
Type of Claim : Third Party Claim
Policy No. : 5108031442
Vehicle No : **SLG 1983 C**
Model Code : Honda Civic
Model / Year : Sep-16
Engine No : R16B21600446
Chassis No : MRHFC5650GT000319
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jan-20
Place of Accident : Canberra Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 1983 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$	280.00	280 40
2	To renew rear windscreen to facilitate rear lid renewal.	S/N \$	400.00	X
3	To install rear windscreen solar film.	S/N \$	400.00	X
4	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	280 100.
5	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender and lhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.	350 \$	2,800.00	1000 700
6	To respray rear bumper, rear lid, lhs rear fender and lhs tail lamp panel.	350 \$	3,900.00	1000 700
7	To carry out diagnostic check.	S/N \$	192.00	X
TOTAL LABOUR CHARGES		:	\$ 8,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER / RE.		
2	REAR BUMPER SPOILER / RE.		
3	REAR BUMPER REFLECTOR-LH X		
4	REAR BUMPER VENT GRILLE-LH / SOR.		
5	REAR BUMPER REINFORCEMENT BAR ?		
6	REAR BUMPER GUIDE-LH/RH LHL - RE RH X NN		
7	REAR BUMPER BRACKET-LH/RH ?		
8	REAR BUMPER WIRING ?		
9	REAR BUMPER SPONGE ?		
10	REAR BUMPER TOW COVER / ANT		
11	REAR LID / BT.		
12	REAR LID WEATHER STRIP ?		
13	REAR LID LOGO /		
14	REAR LID " HONDA CIVIC " EMBLEM / LMC		
15	REAR LID " I-VTEC " EMBLEM /		
16	REAR LID HINGE LH/RH X NN		
17	TAILLIGHT INNER LH/RH ?		
18	TAILLIGHT OUTER LH/RH ?		
19	REAR END PANEL ?		
20	REAR END PANEL TOP GARNISH ?		

SUB-TOTAL SPARE PARTS

: \$ -

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	REAR PARKING AID SENSOR <i>ipc</i> / <i>mis</i>			
22	REAR PARKING AID SENSOR SEAL RING <i>acc</i>			
23	REAR WINDSCREEN <i>X</i>			
24	REAR WINDSCREEN MOULDING <i>X</i> <i>nn</i>			
25	REAR WINDSCREEN SEALANT <i>X</i>	S/N	\$	200.00
26	REAR WINDSCREEN PRIMER <i>X</i>	S/N	\$	19.00
27	PACKING ADHESIVE FOR CAR PLATE NO. HOLDER <i>acc</i>	S/N	\$	20.00
28	SUNDRIES <i>?</i>		\$	400.00
TOTAL SPARE PARTS		:	\$	400.00
TOTAL LABOUR CHARGES		:	\$	2,980.00
GRAND TOTAL		:	\$	3,380.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Guo Qiang - 82880282
21/01/2020
before paint photos.
4 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after **spray painting**
- To display damaged part(s) **during** resurvey
- Parts prices are subject to **confirmation**
- Third party survey is on a **"Without Prejudice"** basis
- No illegal modification(s) is **allowed**
- Supplementary item(s) **must be** resurveyed and
is subject to final approval **from Insurance Company**

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant