

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27372

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0101/2020/NS
Date	:	23-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SBT 3335 K

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Mr Siah Yu Jun Ivan
Address	:	178 Cranberra Drive #05-17 Singapore 767951
Telephone	:	HP +65 96217285
Type of Claim	:	Third Party Claim
Policy No.	:	5108031442
Vehicle No	:	SLG 1983 C
Model Code	:	Honda Civic
Model / Year	:	Sep-16
Engine No	:	R16B21600446
Chassis No	:	MRHFC5650GT000319
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	21-Jan-20
Place of Accident	:	Canberra Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 1983 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$	280.00	✓
2	To renew rear windscreen to facilitate rear lid renewal.	S/N \$	400.00	X
3	To install rear windscreen solar film.	S/N \$	400.00	X
4	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	✓
5	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender and lhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	1000 ?
6	To respray rear bumper, rear lid, lhs rear fender and lhs tail lamp panel.	\$	3,900.00	1000 ?
7	To carry out diagnostic check.	S/N \$	192.00	X
TOTAL LABOUR CHARGES		:	\$ 8,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER / <i>RE.</i>		
2	REAR BUMPER SPOILER / <i>RE.</i>		
3	REAR BUMPER REFLECTOR-LH X		
4	REAR BUMPER VENT GRILLE-LH / <i>sd.</i>		
5	REAR BUMPER REINFORCEMENT BAR ?		
6	REAR BUMPER GUIDE-LH/RH <i>LH - RH X</i>		
7	REAR BUMPER BRACKET-LH/RH ?		
8	REAR BUMPER WIRING ?		
9	REAR BUMPER SPONGE ?		
10	REAR BUMPER TOW COVER /		
11	REAR LID / <i>BT.</i>		
12	REAR LID WEATHER STRIP ?		
13	REAR LID LOGO /		
14	REAR LID " HONDA CIVIC " EMBLEM /		
15	REAR LID " I-VTEC " EMBLEM /		
16	REAR LID HINGE LH/RH X		
17	TAILLIGHT INNER LH/RH ?		
18	TAILLIGHT OUTER LH/RH ?		
19	REAR END PANEL ?		
20	REAR END PANEL TOP GARNISH ?		

SUB-TOTAL SPARE PARTS

: \$ -

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	REAR PARKING AID SENSOR 1pc /		
22	REAR PARKING AID SENSOR SEAL RING /		
23	REAR WINDSCREEN X		
24	REAR WINDSCREEN MOULDING X		
25	REAR WINDSCREEN SEALANT X		
26	REAR WINDSCREEN PRIMER X	S/N \$	200.00
27	PACKING ADHESIVE FOR CAR PLATE NO. HOLDER /	S/N \$	19.00
28	SUNDRIES ?	S/N \$	20.00
		\$	400.00
	TOTAL SPARE PARTS	: \$	400.00
	TOTAL LABOUR CHARGES	: \$	2,980.00
	GRAND TOTAL	: \$	3,380.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Guo Qiny - 82880282
Surveyed Date : 21/01/2020
Authorised Date :
Excess Cost :
Liability : before paint photos.
Remarks : 4 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER ✓	\$	750.00	
2	REAR BUMPER SPOILER ✓	\$	105.00	
3	REAR BUMPER REFLECTOR-LH X	\$	45.00	
4	REAR BUMPER VENT GRILLE-LH ✓	\$	36.00	
5	REAR BUMPER REINFORCEMENT BAR ?	\$	375.00	
6	REAR BUMPER GUIDE-LH/RH ✓ R4 X	2 \$	33.00	
7	REAR BUMPER BRACKET-LH/RH ?	2 \$	15.00	
8	REAR BUMPER WIRING ?	\$	105.00	
9	REAR BUMPER SPONGE ?	\$	20.00	
10	REAR BUMPER TOW COVER ✓	\$	20.00	
11	REAR LID ✓	\$	960.00	
12	REAR LID WEATHER STRIP ?	\$	90.00	
13	REAR LID LOGO ✓	\$	60.00	
14	REAR LID " HONDA CIVIC " EMBLEM ✓	\$	60.00	
15	REAR LID " I-VTEC " EMBLEM ✓	\$	60.00	
16	REAR LID HINGE LH/RH X	\$	120.00	
17	TAILLIGHT INNER LH/RH ?	\$	510.00	
18	TAILLIGHT OUTER LH/RH ?	\$	960.00	
19	REAR END PANEL ?	\$	540.00	
20	REAR END PANEL TOP GARNISH ?	\$	60.00	
SUB-TOTAL SPARE PARTS		:	\$ 2,310.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	REAR PARKING AID SENSOR 1 PL ✓	\$	264.00
23	REAR WINDSCREEN ✗	\$	2,250.00
24	REAR WINDSCREEN MOULDING ✗	\$	260.00
25	REAR WINDSCREEN SEALANT ✗	S/N \$	200.00
26	REAR WINDSCREEN PRIMER ✗	S/N \$	19.00
27	PACKING ADHESIVE FOR CAR PLATE NO. HOLDER ✓	S/N \$	20.00
28	SUNDRIES ?	\$	400.00
TOTAL SPARE PARTS		:	\$ 400.00
TOTAL LABOUR CHARGES		:	\$ 2,980.00
GRAND TOTAL		:	\$ 3,380.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.