

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27372

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0101/2020/NS
Date : 23-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.
Your Insured Veh No : SBT 3335 K

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Siah Yu Jun Ivan
Address : 178 Cranberra Drive
#05-17
Singapore 767951
Telephone : HP +65 96217285
Type of Claim : Third Party Claim
Policy No. : 5108031442
Vehicle No : **SLG 1983 C**
Model Code : Honda Civic
Model / Year : Sep-16
Engine No : R16B21600446
Chassis No : MRHFC5650GT000319
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jan-20
Place of Accident : Canberra Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 1983 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	400 180
2	To renew rear windscreen to facilitate rear lid renewal.	S/N \$ 400.00	X Jan
3	To install rear windscreen solar film.	S/N \$ 400.00	X
4	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	1000 180
5	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender and lhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1000 700 800
6	To respray rear bumper, rear lid, lhs rear fender and lhs tail lamp panel.	\$ 3,900.00	1000 700 800
7	To carry out diagnostic check.	S/N \$ 192.00	100 120
TOTAL LABOUR CHARGES		: \$ 8,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER ✓ DE	\$	750.00 ✓
2	REAR BUMPER SPOILER ✓ DE	\$	105.00 ✓
3	REAR BUMPER REFLECTOR-LH X NN	\$	45.00 X
4	REAR BUMPER VENT GRILLE-LH ✓ SCR	\$	36.00 ✓
5	REAR BUMPER REINFORCEMENT BAR R ✓ BT	\$	246.2 375.00 ✓ 246.20
6	REAR BUMPER GUIDE-LH/RH LH ✓ RH X NN LH-DE	2 \$	16.5 33.00 ✓ 16.50
7	REAR BUMPER BRACKET-LH/RH X NN	2 \$	15.00 X
8	REAR BUMPER WIRING X NN	\$	105.00 X
9	REAR BUMPER SPONGE X NN	\$	20.00 X
10	REAR BUMPER TOW COVER ✓ CUT	\$	20.00 ✓ 15.00 15.00
11	REAR LID ✓ BT	\$	960.00 ✓ 720
12	REAR LID WEATHER STRIP X NN	\$	90.00 X
13	REAR LID LOGO ✓ NEC	\$	28.4 60.00 ✓ 28.40
14	REAR LID "HONDA CIVIC" EMBLEM ✓ NEC	\$	28.3 60.00 ✓ 28.30
15	REAR LID "I-VTEC" EMBLEM ✓ NEC	\$	31.2 60.00 ✓ 31.20
16	REAR LID HINGE LH/RH X NN	\$	120.00 X
17	TAILLIGHT INNER LH/RH X NN	\$	510.00 X
18	TAILLIGHT OUTER LH/RH X NN	\$	960.00 X
19	REAR END PANEL R ✓ BUC	\$	540.00 ✓
20	REAR END PANEL TOP GARNISH X NN	\$	60.00 X
SUB-TOTAL SPARE PARTS		\$	2,310.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved; Remarks (X) = Not approved.
Spare parts are Special Net.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	REAR PARKING AID SENSOR 1 PC ✓ MR	\$	148.3 264.00	✓
23	REAR WINDSCREEN X NN	\$	2,250.00	X
24	REAR WINDSCREEN MOULDING X NN	\$	260.00	X
25	REAR WINDSCREEN SEALANT X NN	S/N \$	200.00	✓
26	REAR WINDSCREEN PRIMER X NN	S/N \$	19.00	X
27	PACKING ADHESIVE FOR CAR PLATE NO. HOLDER / NEC	S/N \$	20.00	X nn
28	SUNDRIES ✓ NEC	\$	30(SN) 400.00	✓
TOTAL SPARE PARTS		:	\$ 400.00	
TOTAL LABOUR CHARGES		:	\$ 2,980.00	
GRAND TOTAL		:	\$ 3,380.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

65 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

3 Days.

Supplementary Estimate 1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534
Attn: Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Estimate No. PA/TP/0101/2020/NS
Date 6-Mar-20
Service Advisor Glory Tan
Pages 1 of 1
Regn. No SLG 1983 C
Model No Honda Civic

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Acrylic sealant	\$ 180.00	100
2	Cavity wax	\$ 140.00	100
3	Stone chip	\$ 180.00	100

Labours

1	To carry out first measurement test on car-o-liner.	S/N \$ 800.00	200 photo X NA
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 480.00	40 180.00
3	To cut out and weld rear end panelling. To repair spare wheel housing and lhs chassis member.	350 \$ 3,500.00	1050 1200.00
4	To respray rear end panelling, spare wheel housing and lhs chassis member. To carry out stone chip treatment and joint sealant works.	250 \$ 2,800.00	700 800.00
5	To place vehicle on car-o-liner.	S/N \$ 2,400.00	400 1200.00
6	To carry out wheel alignment.	S/N \$ 240.00	X MV

TOTAL \$ 10,720.00

For Premium Automobiles Pte Ltd

Authorised Signature