

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 27372**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0101/2020/NS  
**Date** : 23-Jan-20

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your Insured Veh No : SBT 3335 K**

## China Taiping Insurance (SG) Pte Ltd

105 Cecil Street  
#19-00 The Octagon  
Singapore 069534

*Hi Guo Qiang*

*8 days exclude 1 Sunday*

*jb 16 Dec 20*

**Attn: Ms Angie - Motor Claims Dept/Windscreen**

**Tel: 6389 6541 - Fax: 6224 7175**

**Owner's Name** : Mr Siah Yu Jun Ivan  
**Address** : 178 Cranberra Drive  
#05-17  
Singapore 767951  
**Telephone** : HP +65 96217285  
**Type of Claim** : Third Party Claim  
**Policy No.** : 5108031442  
**Vehicle No** : **SLG 1983 C**  
**Model Code** : Honda Civic  
**Model / Year** : Sep-16  
**Engine No** : R16B21600446  
**Chassis No** : MRHFC5650GT000319  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 21-Jan-20  
**Place of Accident** : Canberra Link

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLG 1983 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$	280.00	\$ 180.00
2	To renew rear windscreen to facilitate rear lid renewal.	S/N \$	400.00	
3	To install rear windscreen solar film.	S/N \$	400.00	
4	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	\$ 180.00
5	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender and lhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	\$ 800.00
6	To respray rear bumper, rear lid, lhs rear fender and lhs tail lamp panel.	\$	3,900.00	\$ 800.00
6a	Added labour charges - see attached	\$	10,220.00	\$ 3,380.00
7	To carry out diagnostic check.	S/N \$	192.00	\$ 120.00
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 18,472.00</b>	<b>\$ 5,460.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	<u>Damage Parts &amp; Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER	\$ 750.00	\$ 750.00
2	REAR BUMPER SPOILER	\$ 105.00	\$ 105.00
3	REAR BUMPER REFLECTOR-LH	\$ 45.00	
4	REAR BUMPER VENT GRILLE-LH	\$ 36.00	\$ 36.00
5	REAR BUMPER REINFORCEMENT BAR	\$ 375.00	\$ 375.00
6	REAR BUMPER GUIDE-LH/RH	2 \$ 33.00	\$ 33.00
7	REAR BUMPER BRACKET-LH/RH	2 \$ 15.00	
8	REAR BUMPER WIRING	\$ 105.00	
9	REAR BUMPER SPONGE	\$ 20.00	
10	REAR BUMPER TOW COVER	\$ 20.00	\$ 15.00
11	REAR LID	\$ 960.00	\$ 960.00
12	REAR LID WEATHER STRIP	\$ 90.00	
13	REAR LID LOGO	\$ 60.00	\$ 60.00
14	REAR LID " HONDA CIVIC " EMBLEM	\$ 60.00	\$ 60.00
15	REAR LID " I-VTEC " EMBLEM	\$ 60.00	\$ 60.00
16	REAR LID HINGE LH/RH	\$ 120.00	
17	TAILLIGHT INNER LH/RH	\$ 510.00	
18	TAILLIGHT OUTER LH/RH	\$ 960.00	
19	REAR END PANEL	\$ 540.00	\$ 540.00
20	REAR END PANEL TOP GARNISH	\$ 60.00	
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 2,310.00</b>	<b>\$ 2,994.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>	\$ 2,310.00	\$ 2,994.00
21	REAR PARKING AID SENSOR		\$ 264.00	\$ 264.00
23	REAR WINDSCREEN		\$ 2,250.00	
24	REAR WINDSCREEN MOULDING		\$ 260.00	
25	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
26	REAR WINDSCREEN PRIMER	S/N	\$ 19.00	
27	PACKING ADHESIVE FOR CAR PLATE NO. HOLDER	S/N	\$ 20.00	
27a	ADDED PARTS - SEE ATTACHED	S/N	\$ 500.00	\$ 500.00
28	SUNDRIES		\$ 400.00	\$ 72.00
<b>TOTAL SPARE PARTS</b>			<b>: \$ 6,223.00</b>	<b>\$ 3,830.00</b>
<b>TOTAL LABOUR CHARGES</b>			<b>: \$ 2,980.00</b>	<b>\$ 5,460.00</b>
<b>GRAND TOTAL</b>			<b>: \$ 9,203.00</b>	<b>\$ 9,290.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

<b>China Taiping Insurance (SG) Pte Ltd</b> 105 Cecil Street #19-00 The Octagon Singapore 069534 Attn: Motor Claims Dept <b>Tel: 6389 6541 - Fax: 6224 7175</b>		<b>Estimate No.</b> <b>Date</b> <b>Service Advisor</b> <b>Pages</b> <b>Regn No</b> <b>Model No</b>	PA/TP/0101/2020/NS 6-Mar-20 Glory Tan 1 of 1 SLG 1983 C Honda Civic
Quantity	Description	Unit Price	Amount
<b><u>Parts</u></b>			
1	Acrylic sealant	\$ 180.00	\$ 180.00
2	Cavity wax	\$ 140.00	\$ 140.00
3	Stone chip	\$ 180.00	\$ 180.00
		\$ 500.00	\$ 500.00
<b><u>Labours</u></b>			
1	To carry out first measurement test on car-o-liner.	S/N \$ 800.00	
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 480.00	\$ 180.00 #
3	To cut out and weld rear end panelling. To repair spare wheel housing and lhs chassis member.	\$ 3,500.00	\$ 1,200.00 #
4	To respray rear end panelling, spare wheel housing and lhs chassis member. To carry out stone chip treatment and joint sealant works.	\$ 2,800.00	\$ 800.00 #
5	To place vehicle on car-o-liner.	S/N \$ 2,400.00	\$ 1,200.00 #
6	To carry out wheel alignment.	S/N \$ 240.00	
		LABOUR	\$ 10,220.00 \$ 3,380.00 #
		MATERIALS	\$ 500.00 \$ 500.00
		<b>TOTAL</b>	<b>\$ 10,720.00 \$ 3,880.00 #</b>

For Premium Automobiles Pte Ltd

Authorised Signature

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant