

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27372

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0101/2020/NS
Date : 23-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SBT 3335 K

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Guo Qiang
8 days exclude 1 Sunday
jb 16 Dec 20

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Siah Yu Jun Ivan
Address : 178 Cranberra Drive
#05-17
Singapore 767951
Telephone : HP +65 96217285
Type of Claim : Third Party Claim
Policy No. : 5108031442
Vehicle No : **SLG 1983 C**
Model Code : Honda Civic
Model / Year : Sep-16
Engine No : R16B21600446
Chassis No : MRHFC5650GT000319
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jan-20
Place of Accident : Canberra Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 1983 C

S/n	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	\$	180.00
2	To renew rear windscreen to facilitate rear lid renewal.	S/N	\$ 400.00		
3	To install rear windscreen solar film.	S/N	\$ 400.00		
4	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00	\$	180.00
5	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender and lhs tail lamp panel. Re-organise crash management components. Reinstall all parts removed.		\$ 2,800.00	\$	800.00
6	To respray rear bumper, rear lid, lhs rear fender and lhs tail lamp panel.		\$ 3,900.00	\$	800.00
6a	Added labour charges - see attached		\$ 10,220.00	\$	3,380.00
7	To carry out diagnostic check.	S/N	\$ 192.00	\$	120.00
TOTAL LABOUR CHARGES		:	\$ 18,472.00	\$	5,460.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices			
		S/Nett	Remarks		
1	REAR BUMPER	\$ 750.00	\$ 750.00	\$ 600.00	
2	REAR BUMPER SPOILER	\$ 105.00	\$ 105.00	\$ 84.00	
3	REAR BUMPER REFLECTOR-LH	\$ 45.00			
4	REAR BUMPER VENT GRILLE-LH	\$ 36.00	\$ 36.00	\$ 28.80	
5	REAR BUMPER REINFORCEMENT BAR	\$ 375.00	\$ 246.20	\$ 196.96	
6	REAR BUMPER GUIDE-LH/RH	2 \$ 33.00	\$ 16.50	\$ 13.20	
7	REAR BUMPER BRACKET-LH/RH	2 \$ 15.00			
8	REAR BUMPER WIRING	\$ 105.00			
9	REAR BUMPER SPONGE	\$ 20.00			
10	REAR BUMPER TOW COVER	\$ 20.00	\$ 15.00	\$ 12.00	
11	REAR LID	\$ 960.00	\$ 720.00	\$ 576.00	
12	REAR LID WEATHER STRIP	\$ 90.00			
13	REAR LID LOGO	\$ 60.00	\$ 28.40	\$ 22.72	
14	REAR LID " HONDA CIVIC " EMBLEM	\$ 60.00	\$ 28.30	\$ 22.64	
15	REAR LID " I-VTEC " EMBLEM	\$ 60.00	\$ 31.20	\$ 24.96	
16	REAR LID HINGE LH/RH	\$ 120.00			
17	TAILLIGHT INNER LH/RH	\$ 510.00			
18	TAILLIGHT OUTER LH/RH	\$ 960.00			
19	REAR END PANEL	\$ 540.00	\$ 540.00	\$ 432.00	
20	REAR END PANEL TOP GARNISH	\$ 60.00			
SUB-TOTAL SPARE PARTS		\$ 2,310.00	\$ 2,516.60	\$ 2,013.28	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 1983 C

S/N	Parts Description	Damage Parts & Prices			
			S/Nett	Remarks	
		c/f	\$ 2,310.00	\$ 2,516.60	\$ 2,013.28
21	REAR PARKING AID SENSOR		\$ 264.00	\$ 148.30	\$ 118.64
23	REAR WINDSCREEN		\$ 2,250.00		
24	REAR WINDSCREEN MOULDING		\$ 260.00		
25	REAR WINDSCREEN SEALANT	S/N	\$ 200.00		
26	REAR WINDSCREEN PRIMER	S/N	\$ 19.00		
27	PACKING ADHESIVE FOR CAR PLATE NO. HOLDER	S/N	\$ 20.00		
27a	ADDED PARTS - SEE ATTACHED	S/N	\$ 500.00	\$ 50.00	\$ 300.00
28	SUNDRIES		\$ 400.00	\$ 30.00	\$ 30.00
	TOTAL SPARE PARTS	:	\$ 6,223.00	\$ 2,744.90	\$ 2,461.92
	TOTAL LABOUR CHARGES	:	\$ 2,980.00	\$ 5,460.00	\$ 5,460.00
	GRAND TOTAL	:	\$ 9,203.00	\$ 8,204.90	\$ 7,921.92

All charges are not inclusive of GST

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Netf.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd 105 Cecil Street #19-00 The Octagon Singapore 069534 Attn: Motor Claims Dept Tel: 6389 6541 - Fax: 6224 7175		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0101/2020/NS 6-Mar-20 Glory Tan 1 of 1 SLG 1983 C Honda Civic
Quantity	Description	Unit Price	Amount
Parts			
1	Acrylic sealant	\$ 180.00	\$ 100.00
2	Cavity wax	\$ 140.00	\$ 100.00
3	Stone chip	\$ 180.00	\$ 100.00
		\$ 500.00	\$ 300.00
Labours			
1	To carry out first measurement test on car-o-liner.	S/N \$ 800.00	
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 480.00	\$ 180.00
3	To cut out and weld rear end panelling. To repair spare wheel housing and lhs chassis member.	\$ 3,500.00	\$ 1,200.00
4	To respray rear end panelling, spare wheel housing and lhs chassis member. To carry out stone chip treatment and joint sealant works.	\$ 2,800.00	\$ 800.00
5	To place vehicle on car-o-liner.	S/N \$ 2,400.00	\$ 1,200.00
6	To carry out wheel alignment.	S/N \$ 240.00	
LABOUR		\$ 10,220.00	\$ 3,380.00
MATERIALS		\$ 500.00	\$ 500.00
TOTAL		\$ 10,720.00	\$ 3,880.00

For Premium Automobiles Pte Ltd

Authorised Signature