

kk

Not Notthain  
Penny Bepain

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMR 5626M**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SMR 5626M**

KMHC851CVLU201291

HYUNDAI

IONIQ

20.1.2020

**AIG**

14/1/2020

**PART**

**LIST**

- 1 MOULDING ASSY-W/LINE RR DOOR
- 2 MOULDING ASSY-W/LINE FRT DOOR
- 3 PANEL ASSY-PILLAR OUTER, RH
- 4 MIRROR ASSY - OUTSIDE RR VIEW RH
- 5 PANEL FENDER, RH
- 6 GRIP - FRONT DORR OUTSIDE, RH
- 7 PANEL ASSY - FRONT DOOR, RH
- 8 PANEL ASSY - QUARTER OUTER, RH

\$	me	77.10	—
\$	me	110.10	—
\$	R	3,764.90	X
\$	Bz	911.60	✓
\$	R	588.80	X
\$	SL	108.40	X
\$	R	1,797.20	X
\$	R	1,768.30	X

<b>TOTAL</b>	\$	<b>9,126.40</b>
<b>10%</b>	\$	<b>912.64</b>
	\$	<b>8,213.76</b>

**Special Nett**

- 2 FRONT WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 FRONT WINDSCREEN INNER SPONGE SEAL
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP
- 1SET FRONT BUMPER RETAINER CLIP

\$	nn	253.80	} X
\$	nn	120.00	
\$	nn	100.00	
\$	nn	35.00	
\$	nn	66.00	
\$	nn	35.00	

<b>TOTAL</b>	\$	<b>609.80</b>
--------------	----	---------------

<b>TOTAL PARTS</b>	\$	<b>8,823.56</b>
--------------------	----	-----------------

**LABOUR**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMR 5626M**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,500.00	500/
Putty And Spray Painting Of The Affected Portion.	\$	3,500.00	1100/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	Nm 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	↪ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪ 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	↪ 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	↪ 170.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of rear door fittings, attachment and perform water seepage test.	\$	↪ 170.00	X
To transfer of front windscreen glass to facilitate bodywork repair.	\$	↪ 170.00	X
To transfer of rear fender fittings, attachment to facilitate bodywork repair.	\$	↪ 170.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMR 5626M**

To transfer of front fender fittings, attachment to facilitate  
bodywork repair.

\$ *na* 170.00 X**TOTAL** \$ 9,340.00**Over All Total** \$ 18,163.56**(PART-BY-PART) Repair Days**~~10 days~~*4 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: