



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005694
INV Date 19/08/2020
Reference CC4/FCI20001470/R1da3n2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLT 6308B
Insured Veh. SHA 5759L
Claim No. D20000587MFSH/1
Policy No. D-20094922MFSH
Accident Date 22/01/2020
Inspection Date 03/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20001470/R1da3n2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 19-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 5759L	Veh. Inspected	SLT 6308B
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20000587MFSH/1	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	24/01/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200 AVG	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2130422A257093	Colour	BLACK
Odometer	57736	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	PIRELLI	6 mm
L/H Front Tyre	245/45 R18	PIRELLI	6 mm
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/01/2020	Inspection Date	03/02/2020
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 6308B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (SN)	DEFORMED	2,021.87	2,021.87
1	REAR BOTTOM PANEL (SN)	CUT	281.03	281.03
1	REAR BOTTOM PANEL GARNISH (SN)	CUT	316.65	316.65
4	CT/R PARKING SENSOR (SN)	SERVICEABLE	715.00	-
4	CT/R PARKING SENSOR SEAL (SN)	NOT NECESSARY	25.40	-
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	SERVICEABLE	112.12	-
1	LH/R BASIC MOUNTING FOR BUMPER (SN)	SERVICEABLE	69.11	-
1	RH/R BASIC MOUNTING FOR BUMPER (SN)	SERVICEABLE	67.79	-
1	REAR CROSS MEMBER (SN)	SERVICEABLE	823.80	-
1	E200 EMBLEM (SN)	NECESSARY	91.70	91.70
1	REAR STAR EMBLEM (SN)	NECESSARY	51.96	51.96
3	GROMMET (SN)	NECESSARY	7.83	7.83
1	REAR BOOT LID GARNISH (SN)	SERVICEABLE	143.31	-
			4,727.57	2,771.04
<u>LABOUR</u>				
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.			380.00	380.00
REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.			1,920.00	960.00
RESPRAY REAR BUMPER & REAR BOOT LID .			1,500.00	1,200.00
			3,800.00	2,540.00
GRAND TOTAL			8,527.57	5,311.04
RECOMMENDED COST OF REPAIRS				5,311.04

Report Ref No. CC4/FCI20001470/R1da3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 6308B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

