



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SLT6308B

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Rasul

Vehicle & Document Information

WIP No 40939
Reg No/Reg Date SLT6308B / 24/11/2017
Date In/Mileage 03/02/2020 / 57738
Chassis No WDD2130422A267093
Engine No 27492031034525
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim 021 197 Obsidian Bl/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	22/02/2020/ 23:11	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M. BPNSUN POLICY NO: ACC DATE : A3002018520MY // 22-01-2020 DRIVE IN: 22-01-2020 // TP GAR NO: SHAS/59L (FIRST CAPITAL INS) DATE IN/DATE SURVEY: 03-02-2020 // LKK RASUL BY/AUTHORIZED ON : JASON TEA // 03-02-2020				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960.00
A BPIRES RESPRAY REAR BUMPER & REAR BOOT LID				1200.00
X REAR BUMPER	1.00	2021.87	00.00	2021.87
X REAR BOTTOM PANEL	1.00	281.03	00.00	281.03
X REAR BOTTOM PANEL GARNISH	1.00	316.65	00.00	316.65
X E200 EMBLEM	1.00	91.70	00.00	91.70
X REAR STAR EMBLEM	1.00	51.96	00.00	51.96
X GROMMET	3.00	2.61	00.00	7.83

THIS IS NOT AN OFFICIAL TAX INVOICE
4D
ESTIMATES

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 5,311.04
7% GST on 5311.04 371.77
Total Payable 5,682.81

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of resealing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany