

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20001484/KVD3E2

**Date:** 08/04/2020

### REFERENCE

|                   |            |                  |                  |                        |
|-------------------|------------|------------------|------------------|------------------------|
| Insured/Claimant: | -          | Policy No:       | DMCVSN1935991900 |                        |
| Date of Loss:     | 23/10/2019 | Nature of Claim: | OD               | Claim No: SNM20D200053 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBG7169R</b>                   |             |                   |
| Make & Model:               | NISSAN NV350, 2.5 (A)             | Engine No:  | YD25420081A       |
| Reg. Date:                  | 13/10/2017 (Man. Year: 2017)      | Chassis No: | JN1MC2E26Z0008313 |
| Colour:                     | Metallic Grey                     | Odometer:   | 0 km              |
| Engine Capacity:            | 2488 cc                           |             |                   |
| Market Value/New Car Price: | S\$51,000.00                      |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 195 R15X8   | Rear Tyre Size:  | 195 R15X8   |
| Front Left Side:  | Dunlop 4 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 4 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 89,963.30         | 40,466.50         | 49,496.80         | 55.02         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 13,390.00         | 7,980.00          | 5,410.00          | 40.40         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>103,353.30</b> | <b>48,446.50</b>  | <b>54,906.80</b>  | <b>53.13</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>20,000.00</b>  |                   |               |
| <b>- Excess (\$\$)</b>                    | 350.00            | 350.00            | 0.00              | 0.00          |
| <b>(\$\$)</b>                             | 103,003.30        | 19,650.00         | 83,353.30         | 80.92         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 7,210.23          | 1,375.50          | 5,834.73          | 80.92         |
| <b>Nett Amount (\$\$)</b>                 | <b>110,213.53</b> | <b>21,025.50</b>  | <b>89,188.03</b>  | <b>80.92</b>  |

### INSPECTION

Date of Assignment: 23/01/2020  
Date Inspected: 29/01/2020 Inspected At:

S Three Automotive & Recovery Pte Ltd -  
Sin Ming (HQ)  
BLK 8 SIN MING IND EST #01-64/66  
Singapore 575643

Estimated Period of Repair: 35.0 days

---

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

|                      |                                                                                                                                                                              |                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| <b>Reference</b>     |                                                                                                                                                                              |                                                        |
| <b>Part Source:</b>  | (Last Synchronised: 08 Apr 2020)                                                                                                                                             |                                                        |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | NISSAN NV350 2.5 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBG7169R)                                                                                                                                    |                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

## Recommended Parts

| No. | Qty | Part No. | Particulars                                                | Condition        | Repairer's | Amount    |
|-----|-----|----------|------------------------------------------------------------|------------------|------------|-----------|
| 1   | 1   |          | <b>*FRONT BUMPER FOG LAMP RH</b><br>(WCP)                  | Missing          | 280.00 F   | *280.00 F |
| 2   | 1   |          | <b>*FRONT BUMPER FOG LAMP LH</b><br>(WCP)                  | Missing          | 280.00 F   | *280.00 F |
| 3   | 1   |          | <b>*FRONT BUMPER TOP BEAN</b><br>(WCP)                     | Missing          | 185.00 F   | *185.00 F |
| 4   | 1   |          | <b>*FRONT GRILLE</b><br>(WCP)                              | Missing          | 250.00 F   | *250.00 F |
| 5   | 1   |          | <b>*FRONT GRILLE LOGO</b><br>(WCP)                         | Missing          | 50.00 F    | *50.00 F  |
| 6   | 1   |          | <b>*FRONT BUMPER</b><br>(WCP)                              | Missing          | 320.00 F   | *320.00 F |
| 7   | 1   |          | <b>*FRONT BUMPER SIDE RETAINER TOP BRACKET LH</b><br>(WCP) | Cracked          | 50.00 F    | *50.00 F  |
| 8   | 1   |          | <b>*FRONT BUMPER SIDE RETAINER TOP BRACKET RH</b><br>(WCP) | Missing          | 50.00 F    | *50.00 F  |
| 9   | 1   |          | <b>*FRONT BUMPER BRACKET LH</b><br>(WCP)                   | Repair           | 80.00 F    | *- F      |
| 10  | 1   |          | <b>*FRONT BUMPER BRACKET RH</b><br>(WCP)                   | Bent             | 80.00 F    | *80.00 F  |
| 11  | 1   |          | <b>*FRONT BUMPER REINFORCEMENT</b><br>(WCP)                | Bent / Distorted | 280.00 F   | *280.00 F |
| 12  | 1   |          | <b>*FRONT BUMPER INNER GRILLE</b><br>(WCP)                 | Missing          | 120.00 F   | *120.00 F |
| 13  | 1   |          | <b>*FRONT BUMPER SIDE RETAINER LH</b><br>(WCP)             | Cracked          | 30.00 F    | *30.00 F  |
| 14  | 1   |          | <b>*FRONT BUMPER SIDE RETAINER RH</b><br>(WCP)             | Missing          | 60.00 F    | *60.00 F  |
| 15  | 1   |          | <b>*FRONT BUMPER SIDE BRACE BRACKET</b><br>(WCP)           | Bent             | 60.00 F    | *60.00 F  |
| 16  | 1   |          | <b>*FRONT BUMPER LOWER GRILLE</b><br>(WCP)                 | Missing          | 105.00 F   | *105.00 F |
| 17  | 1   |          | <b>*FRONT BUMPER FOG LAMP COVER LH</b><br>(WCP)            | Missing          | 80.00 F    | *80.00 F  |
| 18  | 1   |          | <b>*FRONT BUMPER FOG LAMP COVER RH</b><br>(WCP)            | Missing          | 80.00 F    | *80.00 F  |
| 19  | 1   |          | <b>*FRONT BUMPER SPONGE</b><br>(WCP)                       | No such part     | 80.00 F    | *- F      |
| 20  | 1   |          | <b>*FRONT BUMPER LOWER COVER</b><br>(WCP)                  | Cracked          | 120.00 F   | *120.00 F |
| 21  | 1   |          | <b>*FRONT PANEL</b><br>(WCP)                               | Bent             | 600.00 F   | *600.00 F |
| 22  | 1   |          | <b>*FRONT PANEL INSULATOR</b><br>(WCP)                     | Torn             | 280.00 F   | *280.00 F |
| 23  | 1   |          | <b>*FRONT PANEL INNER RUBBER</b><br>(WCP)                  | Bent             | 80.00 F    | *80.00 F  |
| 24  | 1   |          |                                                            | Bent             | 150.00 F   | *150.00 F |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                                | Condition   | Repairer's | Amount    |
|-----|-----|----------|------------------------------------------------------------|-------------|------------|-----------|
|     |     |          | <b>*FRONT LOWER PANEL</b><br>(WCP)                         |             |            |           |
| 25  | 1   |          | <b>*FRONT HEADLAMP LH</b><br>(WCP)                         | Mtg Cracked | 300.00 F   | *300.00 F |
| 26  | 1   |          | <b>*FRONT HEADLAMP RH</b><br>(WCP)                         | Broken      | 300.00 F   | *300.00 F |
| 27  | 1   |          | <b>*FRONT HEADLAMP BRACKET LH</b><br>(WCP)                 | Bent        | 50.00 F    | *50.00 F  |
| 28  | 1   |          | <b>*FRONT HEADLAMP BRACKET RH</b><br>(WCP)                 | Distorted   | 50.00 F    | *50.00 F  |
| 29  | 1   |          | <b>*RADIATOR SPARE TANK</b><br>(WCP)                       | Serviceable | 120.00 F   | *- F      |
| 30  | 1   |          | <b>*RADIATOR</b><br>(WCP)                                  | Serviceable | 600.00 F   | *- F      |
| 31  | 1   |          | <b>*RADIATOR FAN BLADE</b><br>(WCP)                        | Serviceable | 180.00 F   | *- F      |
| 32  | 1   |          | <b>*RADIATOR FAN MOTOR W/COWLING</b><br>(WCP)              | Serviceable | 220.00 F   | *- F      |
| 33  | 1   |          | <b>*RADIATOR SIDE GARNISH LH</b><br>(WCP)                  | Serviceable | 110.00 F   | *- F      |
| 34  | 1   |          | <b>*FRONT SIDE PANEL RH</b><br>(WCP)                       | Bent        | 200.00 F   | *200.00 F |
| 35  | 1   |          | <b>*FRONT SIDE PANEL LH</b><br>(WCP)                       | Bent        | 200.00 F   | *200.00 F |
| 36  | 1   |          | <b>*AIR CON FAN ASSY</b><br>(WCP)                          | Serviceable | 250.00 F   | *- F      |
| 37  | 1   |          | <b>*RADIATOR SIDE GARNISH RH</b><br>(WCP)                  | Serviceable | 110.00 F   | *- F      |
| 38  | 1   |          | <b>*INTER COOLER</b><br>(WCP)                              | Bent        | 900.00 F   | *900.00 F |
| 39  | 1   |          | <b>*AIR CON CONDENSOR</b><br>(WCP)                         | Serviceable | 360.00 F   | *- F      |
| 40  | 1   |          | <b>*AIR CON FAN W/COWLING</b><br>(WCP)                     | Serviceable | 180.00 F   | *- F      |
| 41  | 1   |          | <b>*AIR CON PIPE - CONDENSOR TO COOLING COIL</b><br>(WCP)  | Serviceable | 350.00 F   | *- F      |
| 42  | 1   |          | <b>*AIR CON PIPE - CONDENSOR TO COMPRESSOR</b><br>(WCP)    | Serviceable | 310.00 F   | *- F      |
| 43  | 1   |          | <b>*AIR CON PIPE - COMPRESSOR TO COOLING COIL</b><br>(WCP) | Serviceable | 180.00 F   | *- F      |
| 44  | 1   |          | <b>*INTAKE COOLER HOSE TO INTAKE MANIFOLD</b><br>(WCP)     | Serviceable | 180.00 F   | *- F      |
| 45  | 1   |          | <b>*INTAKE COOLER HOSE TO TURBO</b><br>(WCP)               | Serviceable | 160.00 F   | *- F      |
| 46  | 1   |          | <b>*INTAKE COOLER HOSE PIPE</b><br>(WCP)                   | Serviceable | 300.00 F   | *- F      |
| 47  | 1   |          | <b>*AUTOLATOR</b><br>(WCP)                                 | Serviceable | 1,150.00 F | *- F      |
| 48  | 1   |          | <b>*AIR CON COMPRESSOR</b><br>(WCP)                        | Serviceable | 850.00 F   | *- F      |
| 49  | 1   |          | <b>*BELTING</b><br>(WCP)                                   | Serviceable | 60.00 F    | *- F      |
| 50  | 1   |          | <b>*AIR DUCT</b><br>(WCP)                                  | Serviceable | 130.00 F   | *- F      |
| 51  | 1   |          | <b>*RADIATOR SPARE TANK</b><br>(WCP)                       | Serviceable | 80.00 F    | *- F      |
| 52  | 1   |          | <b>*SET ENGINE MOUNTING</b><br>(WCP)                       | Serviceable | 360.00 F   | *- F      |
| 53  | 1   |          | <b>*ENGINE MOUNTING BRACKET RH</b><br>(WCP)                | Serviceable | 200.00 F   | *- F      |
| 54  | 1   |          | <b>*SET TRIM BELT SYSTEM</b><br>(WCP)                      | Serviceable | 600.00 F   | *- F      |
| 55  | 1   |          | <b>*WASHER TANK</b><br>(WCP)                               | Serviceable | 130.00 F   | *- F      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                 | Condition   | Repairer's | Amount      |
|-----|-----|----------|---------------------------------------------|-------------|------------|-------------|
| 56  | 1   |          | <b>*WASHER TANK MOTOR</b><br>(WCP)          | Serviceable | 85.00 F    | *- F        |
| 57  | 1   |          | <b>*FRONT WHEEL RIM RH</b><br>(WCP)         | Serviceable | 280.00 F   | *- F        |
| 58  | 1   |          | <b>*OIL FILTER HOISING</b><br>(WCP)         | Serviceable | 28.00 F    | *- F        |
| 59  | 1   |          | <b>*INTAKE OIL COOLER ASSEMBLY</b><br>(WCP) | Serviceable | 380.00 F   | *- F        |
| 60  | 1   |          | <b>*INTAKE COOLER HOSE</b><br>(WCP)         | Serviceable | 280.00 F   | *- F        |
| 61  | 1   |          | <b>*FRONT CHASSIS CROSSMEMBER</b><br>(WCP)  | Serviceable | 1,250.00 F | *- F        |
| 62  | 1   |          | <b>*AIR CON DRIVE</b><br>(WCP)              | Serviceable | 180.00 F   | *- F        |
| 63  | 1   |          | <b>*AIR CON SWITCH</b><br>(WCP)             | Serviceable | 150.00 F   | *- F        |
| 64  | 1   |          | <b>*AIR DUCT</b><br>(WCP)                   | Cracked     | 95.00 F    | *95.00 F    |
| 65  | 1   |          | <b>*AIR VENT</b><br>(WCP)                   | Cracked     | 90.00 F    | *90.00 F    |
| 66  | 1   |          | <b>*AIR VENT HOSE</b><br>(WCP)              | Cracked     | 75.00 F    | *75.00 F    |
| 67  | 1   |          | <b>*OIL COOLER RETURN PIPE</b><br>(WCP)     | Dented      | 265.00 F   | *265.00 F   |
| 68  | 1   |          | <b>*FRONT WIRE HARNESS ASSY</b><br>(WCP)    | Serviceable | 1,800.00 F | *- F        |
| 69  | 1   |          | <b>*STEERING WHEEL</b><br>(WCP)             | Serviceable | 780.00 F   | *- F        |
| 70  | 1   |          | <b>*STEERING BOX ASSY</b><br>(WCP)          | Bent        | 1,950.00 F | *1,950.00 F |
| 71  | 1   |          | <b>*STEERING SHAFT JOINT</b><br>(WCP)       | Bent        | 290.00 F   | *290.00 F   |
| 72  | 1   |          | <b>*STEERING SHAFT</b><br>(WCP)             | Bent        | 950.00 F   | *950.00 F   |
| 73  | 1   |          | <b>*STEERING COLUMN</b><br>(WCP)            | Distorted   | 1,250.00 F | *1,250.00 F |
| 74  | 1   |          | <b>*STEERING RACK AND PINION</b><br>(WCP)   | Serviceable | 1,850.00 F | *- F        |
| 75  | 1   |          | <b>*STEERING COVER</b><br>(WCP)             | Cracked     | 180.00 F   | *180.00 F   |
| 76  | 1   |          | <b>*STEERING COVER PANEL</b><br>(WCP)       | Cracked     | 320.00 F   | *320.00 F   |
| 77  | 1   |          | <b>*SET BREAK AIR PIPE ONE</b><br>(WCP)     | Serviceable | 380.00 F   | *- F        |
| 78  | 1   |          | <b>*BREAK AIR HOSE</b><br>(WCP)             | Serviceable | 165.00 F   | *- F        |
| 79  | 1   |          | <b>*BREAK BOOSTER</b><br>(WCP)              | Bent        | 680.00 F   | *680.00 F   |
| 80  | 1   |          | <b>*BRAKE MASTER PUMP</b><br>(WCP)          | Bent        | 690.00 F   | *690.00 F   |
| 81  | 10  |          | <b>*BREAK PIPE ASSY</b><br>(WCP)            | Serviceable | 980.00 F   | *- F        |
| 82  | 1   |          | <b>*BREAK REVERSER</b><br>(WCP)             | Serviceable | 185.00 F   | *- F        |
| 83  | 1   |          | <b>*BREAK PEDAL</b><br>(WCP)                | Bent        | 490.00 F   | *490.00 F   |
| 84  | 1   |          | <b>*CLUTCH PEDAL</b><br>(WCP)               | Bent        | 490.00 F   | *490.00 F   |
| 85  | 1   |          | <b>*CLUTCH PUMP TOP</b><br>(WCP)            | Serviceable | 270.00 F   | *- F        |
| 86  | 1   |          | <b>*CLUTCH PUMP LOWER</b><br>(WCP)          | Serviceable | 275.00 F   | *- F        |
| 87  | 1   |          | <b>*CLUTCH CABLE</b><br>(WCP)               | Serviceable | 275.00 F   | *- F        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                            | Condition   | Repairer's | Amount    |
|-----|-----|----------|--------------------------------------------------------|-------------|------------|-----------|
| 88  | 3   |          | <b>*INTAKE COOLER BRACKET</b><br>(WCP)                 | Serviceable | 240.00 F   | *- F      |
| 89  | 1   |          | <b>*FRONT CHASSIS RH</b><br>(WCP)                      | Repair      | 1,600.00 F | *- F      |
| 90  | 1   |          | <b>*FRONT CHASSIS SIDE MEMBER RH</b><br>(WCP)          | Serviceable | 600.00 F   | *- F      |
| 91  | 1   |          | <b>*FRONT SIDE W/S PILLAR RH</b><br>(WCP)              | Bent        | 850.00 F   | *850.00 F |
| 92  | 1   |          | <b>*FRONT SIDE W/S PILLAR INNER PANEL RH</b><br>(WCP)  | Bent        | 680.00 F   | *680.00 F |
| 93  | 1   |          | <b>*FRONT DOOR RH</b><br>(WCP)                         | Bent        | 850.00 F   | *850.00 F |
| 94  | 1   |          | <b>*FRONT DOOR LH</b><br>(WCP)                         | Warped      | 850.00 F   | *850.00 F |
| 95  | 1   |          | <b>*FRONT DOOR OUTER HANDLE RH</b><br>(WCP)            | Serviceable | 180.00 F   | *- F      |
| 96  | 1   |          | <b>*FRONT DOOR OUTER HANDLE LH</b><br>(WCP)            | Serviceable | 180.00 F   | *- F      |
| 97  | 1   |          | <b>*FRONT DOOR HINGE TOP RH</b><br>(WCP)               | Bent        | 150.00 F   | *150.00 F |
| 98  | 1   |          | <b>*FRONT DOOR HINGE TOP LH</b><br>(WCP)               | Repair      | 150.00 F   | *- F      |
| 99  | 1   |          | <b>*FRONT DOOR HINGE BOTTOM RH</b><br>(WCP)            | Bent        | 160.00 F   | *160.00 F |
| 100 | 1   |          | <b>*FRONT DOOR HINGE BOTTOM LH</b><br>(WCP)            | Repair      | 160.00 F   | *- F      |
| 101 | 1   |          | <b>*FRONT DOOR OUTER MOUNLDING LH</b><br>(WCP)         | Serviceable | 120.00 F   | *- F      |
| 102 | 1   |          | <b>*FRONT DOOR OUTER MOUNLDING RH</b><br>(WCP)         | Bent        | 120.00 F   | *120.00 F |
| 103 | 1   |          | <b>*FRONT DOOR INNER MOUNLDING LH</b><br>(WCP)         | Serviceable | 110.00 F   | *- F      |
| 104 | 1   |          | <b>*FRONT DOOR INNER MOUNLDING RH</b><br>(WCP)         | Distorted   | 110.00 F   | *110.00 F |
| 105 | 1   |          | <b>*FRONT DOOR GLASS RH</b><br>(WCP)                   | Broken      | 295.00 F   | *295.00 F |
| 106 | 1   |          | <b>*FRONT DOOR GLASS CHANNEL RUBBER RH</b><br>(WCP)    | Dented      | 165.00 F   | *165.00 F |
| 107 | 1   |          | <b>*FRONT DOOR TRIM BOARD LH</b><br>(WCP)              | Serviceable | 330.00 F   | *- F      |
| 108 | 1   |          | <b>*FRONT DOOR TRIM BOARD RH</b><br>(WCP)              | Cracked     | 330.00 F   | *330.00 F |
| 109 | 1   |          | <b>*FRONT DOOR TRIM BOARD INNER HANDLE RH</b><br>(WCP) | Distorted   | 160.00 F   | *160.00 F |
| 110 | 1   |          | <b>*FRONT DOOR TRIM BOARD INNER HANDLE LH</b><br>(WCP) | Serviceable | 160.00 F   | *- F      |
| 111 | 1   |          | <b>*FRONT DOOR POWER WINDOW SWITCH RH</b><br>(WCP)     | Cracked     | 60.00 F    | *60.00 F  |
| 112 | 1   |          | <b>*FRONT DOOR GLASS REGULATOR RH</b><br>(WCP)         | Bent        | 285.00 F   | *285.00 F |
| 113 | 1   |          | <b>*FRONT DOOR GLASS REGULATOR MOTOR RH</b><br>(WCP)   | Jammed      | 280.00 F   | *280.00 F |
| 114 | 1   |          | <b>*SPEAKER RH</b><br>(WCP)                            | Shorted     | 120.00 F   | *120.00 F |
| 115 | 1   |          | <b>*FRONT DOOR CHECK LINE RH</b><br>(WCP)              | Bent        | 60.00 F    | *60.00 F  |
| 116 | 1   |          | <b>*FRONT DOOR CHECK LINE LH</b><br>(WCP)              | Serviceable | 60.00 F    | *- F      |
| 117 | 1   |          | <b>*FRONT DOOR RUBBER BEADING RH</b><br>(WCP)          | Dented      | 160.00 F   | *160.00 F |
| 118 | 1   |          | <b>*FRONT DOOR RUBBER BEADING LOWER RH</b><br>(WCP)    | Dented      | 120.00 F   | *120.00 F |
| 119 | 1   |          | <b>*FRONT DOOR TRIM INNER PLASTIC RH</b><br>(WCP)      | Serviceable | 80.00 F    | *- F      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                          | Condition   | Repairer's | Amount      |
|-----|-----|----------|------------------------------------------------------|-------------|------------|-------------|
| 120 | 1   |          | <b>*FRONT DOOR INNER LOCK ASSY RH</b><br>(WCP)       | Jammed      | 310.00 F   | *310.00 F   |
| 121 | 1   |          | <b>*FRONT DOOR 1/4 GLASS INNER COVER RH</b><br>(WCP) | Dented      | 60.00 F    | *60.00 F    |
| 122 | 1   |          | <b>*FRONT DOOR WING MIRROR RH</b><br>(WCP)           | Missing     | 350.00 F   | *350.00 F   |
| 123 | 1   |          | <b>*FRONT DOOR WING MIRROR LH</b><br>(WCP)           | Serviceable | 350.00 F   | *- F        |
| 124 | 1   |          | <b>*FRONT DOOR CATCH RH</b><br>(WCP)                 | Bent        | 35.00 F    | *35.00 F    |
| 125 | 1   |          | <b>*FRONT DOOR SWITCH</b><br>(WCP)                   | Dented      | 35.00 F    | *35.00 F    |
| 126 | 1   |          | <b>*FRONT DOOR PILLAR RUBBER BEADING</b><br>(WCP)    | Dented      | 110.00 F   | *110.00 F   |
| 127 | 1   |          | <b>*FRONT WHEEL GARNISH RH</b><br>(WCP)              | Cracked     | 140.00 F   | *140.00 F   |
| 128 | 1   |          | <b>*FRONT WHEEL PANEL RH</b><br>(WCP)                | Bent        | 450.00 F   | *450.00 F   |
| 129 | 1   |          | <b>*FRONT WHEEL INNER RH</b><br>(WCP)                | Bent        | 380.00 F   | *380.00 F   |
| 130 | 1   |          | <b>*STEP PANEL RH</b><br>(WCP)                       | Bent        | 420.00 F   | *420.00 F   |
| 131 | 1   |          | <b>*STEP PANEL GARNISH RH</b><br>(WCP)               | Cracked     | 150.00 F   | *150.00 F   |
| 132 | 1   |          | <b>*FRONT DOOR SIDE PANEL RH</b><br>(WCP)            | Bent        | 480.00 F   | *480.00 F   |
| 133 | 1   |          | <b>*FRONT DOOR SIDE PANEL INNER RH</b><br>(WCP)      | Bent        | 420.00 F   | *420.00 F   |
| 134 | 1   |          | <b>*FRONT DOOR SIDE PANEL GRILLE RH</b><br>(WCP)     | Cracked     | 90.00 F    | *90.00 F    |
| 135 | 1   |          | <b>*W/S GLASS</b><br>(WCP)                           | Cracked     | 800.00 F   | *800.00 F   |
| 136 | 1   |          | <b>*W/S GLASS MOUNLDING</b><br>(WCP)                 | Necessary   | 90.00 F    | *90.00 F    |
| 137 | 1   |          | <b>*W/S GLASS MIRROR</b><br>(WCP)                    | Missing     | 320.00 F   | *320.00 F   |
| 138 | 1   |          | <b>*W/S GLASS MIRROR COVER</b><br>(WCP)              | Missing     | 120.00 F   | *120.00 F   |
| 139 | 1   |          | <b>*WIPER BLADE RH</b><br>(WCP)                      | Cut         | 20.00 F    | *20.00 F    |
| 140 | 1   |          | <b>*WIPER BLADE LH</b><br>(WCP)                      | Cut         | 20.00 F    | *20.00 F    |
| 141 | 1   |          | <b>*WIPER ARM RH</b><br>(WCP)                        | Broken      | 180.00 F   | *180.00 F   |
| 142 | 1   |          | <b>*WIPER ARM LH</b><br>(WCP)                        | Serviceable | 200.00 F   | *- F        |
| 143 | 1   |          | <b>*WIPER ARM COVER RH</b><br>(WCP)                  | Serviceable | 30.00 F    | *- F        |
| 144 | 1   |          | <b>*WIPER ARM COVER LH</b><br>(WCP)                  | Serviceable | 30.00 F    | *- F        |
| 145 | 1   |          | <b>*WIPER GARNISH</b><br>(WCP)                       | Serviceable | 290.00 F   | *- F        |
| 146 | 1   |          | <b>*WIPER NOZZLE LH</b><br>(WCP)                     | Serviceable | 80.00 F    | *- F        |
| 147 | 1   |          | <b>*WIPER NOZZLE RH</b><br>(WCP)                     | Serviceable | 80.00 F    | *- F        |
| 148 | 1   |          | <b>*HORN HIGH</b><br>(WCP)                           | Serviceable | 90.00 F    | *- F        |
| 149 | 1   |          | <b>*HORN LOWER</b><br>(WCP)                          | Serviceable | 90.00 F    | *- F        |
| 150 | 1   |          | <b>*DASH BOARD</b><br>(WCP)                          | Cracked     | 1,200.00 F | *1,200.00 F |
| 151 | 1   |          | <b>*DASH BOARD LOWER COVER RH</b><br>(WCP)           | Cracked     | 280.00 F   | *280.00 F   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                    | Condition   | Repairer's | Amount      |
|-----|-----|----------|------------------------------------------------|-------------|------------|-------------|
| 152 | 1   |          | <b>*STEERING COVER TOP RH</b><br>(WCP)         | Distorted   | 200.00 F   | *200.00 F   |
| 153 | 1   |          | <b>*STEERING COVER BOTTOM</b><br>(WCP)         | Distorted   | 200.00 F   | *200.00 F   |
| 154 | 1   |          | <b>*SPEED METER</b><br>(WCP)                   | Serviceable | 1,100.00 F | *- F        |
| 155 | 1   |          | <b>*DASH BOARD GEAR LEVEL COVER</b><br>(WCP)   | Distorted   | 280.00 F   | *280.00 F   |
| 156 | 1   |          | <b>*HANDLE BRAKE LEVEL ASSY</b><br>(WCP)       | Serviceable | 420.00 F   | *- F        |
| 157 | 1   |          | <b>*AIR CON SWITCH PANEL</b><br>(WCP)          | Serviceable | 680.00 F   | *- F        |
| 158 | 1   |          | <b>*AIR CON SWITCH COVER</b><br>(WCP)          | Serviceable | 280.00 F   | *- F        |
| 159 | 1   |          | <b>*RADIO COVER</b><br>(WCP)                   | Serviceable | 120.00 F   | *- F        |
| 160 | 1   |          | <b>*GLOVE BOX TOP</b><br>(WCP)                 | Serviceable | 390.00 F   | *- F        |
| 161 | 1   |          | <b>*GLOVE BOX BOTTOM</b><br>(WCP)              | Serviceable | 450.00 F   | *- F        |
| 162 | 1   |          | <b>*AIR CON COOLING COIL</b><br>(WCP)          | Cracked     | 480.00 F   | *480.00 F   |
| 163 | 1   |          | <b>*AIR CON BOX ASSY</b><br>(WCP)              | Serviceable | 1,280.00 F | *- F        |
| 164 | 1   |          | <b>*AIR CON BLOWER ASSY</b><br>(WCP)           | Serviceable | 450.00 F   | *- F        |
| 165 | 1   |          | <b>*AIR CON INNER HOSE</b><br>(WCP)            | Serviceable | 120.00 F   | *- F        |
| 166 | 1   |          | <b>*AIR CON RESISTOR CONTROL</b><br>(WCP)      | Serviceable | 250.00 F   | *- F        |
| 167 | 1   |          | <b>*AIR CON VALVE</b><br>(WCP)                 | Serviceable | 80.00 F    | *- F        |
| 168 | 1   |          | <b>*DASH BOARD BAR ASSY</b><br>(WCP)           | Distorted   | 485.00 F   | *485.00 F   |
| 169 | 1   |          | <b>*HEADLAMP SWITCH CONTROL</b><br>(WCP)       | Serviceable | 465.00 F   | *- F        |
| 170 | 1   |          | <b>*WIPER SWITCH CONTROL</b><br>(WCP)          | Serviceable | 455.00 F   | *- F        |
| 171 | 1   |          | <b>*FRONT PILLAR INNER GARNISH LH</b><br>(WCP) | Serviceable | 185.00 F   | *- F        |
| 172 | 1   |          | <b>*FRONT PILLAR INNER GARNISH RH</b><br>(WCP) | Distorted   | 185.00 F   | *185.00 F   |
| 173 | 1   |          | <b>*FRONT PILLAR INNER HANDLE RH</b><br>(WCP)  | Serviceable | 110.00 F   | *- F        |
| 174 | 1   |          | <b>*SUN VISOR RH</b><br>(WCP)                  | Distorted   | 295.00 F   | *295.00 F   |
| 175 | 1   |          | <b>*SUN VISOR BRACKET RH</b><br>(WCP)          | Repair      | 60.00 F    | *- F        |
| 176 | 1   |          | <b>*ROOF TOP PANEL</b><br>(WCP)                | Bent        | 1,600.00 F | *1,600.00 F |
| 177 | 1   |          | <b>*ROOF TOP LINING</b><br>(WCP)               | Deformed    | 850.00 F   | *850.00 F   |
| 178 | 1   |          | <b>*ROOF TOP LAMP</b><br>(WCP)                 | Serviceable | 120.00 F   | *- F        |
| 179 | 1   |          | <b>*ROOF TOP INNER FRONT PANEL</b><br>(WCP)    | Bent        | 350.00 F   | *350.00 F   |
| 180 | 1   |          | <b>*ROOF TOP SIDE INNER PANEL RH</b><br>(WCP)  | Bent        | 380.00 F   | *380.00 F   |
| 181 | 1   |          | <b>*ROOF TOP OUTER FRONT PANEL RH</b><br>(WCP) | Bent        | 350.00 F   | *350.00 F   |
| 182 | 1   |          | <b>*AIR BAG RH</b><br>(WCP)                    | Burst       | 900.00 F   | *900.00 F   |
| 183 | 1   |          | <b>*AIR BAG COIL SENSOR</b><br>(WCP)           | Necessary   | 380.00 F   | *380.00 F   |

Report was unsubmitted during this print-out.



| No. | Qty | Part No. | Particulars                                     | Condition     | Repairer's | Amount    |
|-----|-----|----------|-------------------------------------------------|---------------|------------|-----------|
| 184 | 1   |          | <b>*AIR BAG SENSOR RH</b><br>(WCP)              | Necessary     | 280.00 F   | *280.00 F |
| 185 | 1   |          | <b>*AIR BAG SENSOR LH</b><br>(WCP)              | Necessary     | 280.00 F   | *280.00 F |
| 186 | 1   |          | <b>*AIR BAG CONTROL UNIT</b><br>(WCP)           | Necessary     | 800.00 F   | *800.00 F |
| 187 | 1   |          | <b>*FRONT SEAT BELT RH</b><br>(WCP)             | Jammed        | 700.00 F   | *700.00 F |
| 188 | 1   |          | <b>*FRONT SEAT BELT LH</b><br>(WCP)             | Jammed        | 700.00 F   | *700.00 F |
| 189 | 1   |          | <b>*FRONT SEAR CATCH RH</b><br>(WCP)            | Serviceable   | 300.00 F   | *- F      |
| 190 | 1   |          | <b>*FRONT SEAT ASSY RH</b><br>(WCP)             | Serviceable   | 950.00 F   | *- F      |
| 191 | 1   |          | <b>*FRONT SEAT CENTRE GLOVE BOX</b><br>(WCP)    | Serviceable   | 600.00 F   | *- F      |
| 192 | 1   |          | <b>*FRONT CARPET ASSY</b><br>(WCP)              | Serviceable   | 1,100.00 F | *- F      |
| 193 | 1   |          | <b>*FRONT SHOCK ABSORBER RH</b><br>(WCP)        | Serviceable   | 220.00 F   | *- F      |
| 194 | 1   |          | <b>*FRONT SHOCK ABSORBER LH</b><br>(WCP)        | Serviceable   | 220.00 F   | *- F      |
| 195 | 1   |          | <b>*FRONT SHOCK UPPER ARM RH</b><br>(WCP)       | Serviceable   | 550.00 F   | *- F      |
| 196 | 1   |          | <b>*FRONT SHOCK UPPER ARM LH</b><br>(WCP)       | Serviceable   | 550.00 F   | *- F      |
| 197 | 1   |          | <b>*FRONT SHOCK LOWER ARM RH</b><br>(WCP)       | Serviceable   | 560.00 F   | *- F      |
| 198 | 1   |          | <b>*FRONT SHOCK LOWER ARM LH</b><br>(WCP)       | Serviceable   | 560.00 F   | *- F      |
| 199 | 1   |          | <b>*FRONT ANTI ROLL BAR</b><br>(WCP)            | Serviceable   | 380.00 F   | *- F      |
| 200 | 1   |          | <b>*FRONT ANTI ROLL BAR LINK RH</b><br>(WCP)    | Serviceable   | 80.00 F    | *- F      |
| 201 | 1   |          | <b>*FRONT ANTI ROLL BAR LINK LH</b><br>(WCP)    | Serviceable   | 80.00 F    | *- F      |
| 202 | 1   |          | <b>*FRONT ANTI ROLL BAR BUSH RH</b><br>(WCP)    | Serviceable   | 30.00 F    | *- F      |
| 203 | 1   |          | <b>*FRONT ANTI ROLL BAR BUSH LH</b><br>(WCP)    | Serviceable   | 30.00 F    | *- F      |
| 204 | 1   |          | <b>*FRONT KNUCKLE ARM RH</b><br>(WCP)           | Serviceable   | 680.00 F   | *- F      |
| 205 | 1   |          | <b>*FRONT KNUCKLE ARM LH</b><br>(WCP)           | Serviceable   | 680.00 F   | *- F      |
| 206 | 1   |          | <b>*FRONT KNUCKLE WHEEL BEARING RH</b><br>(WCP) | Serviceable   | 150.00 F   | *- F      |
| 207 | 1   |          | <b>*FRONT KNUCKLE WHEEL BEARING LH</b><br>(WCP) | Not Necessary | 150.00 F   | *- F      |
| 208 | 1   |          | <b>*FRONT KNUCKLE WHEEL HUB LH</b><br>(WCP)     | Serviceable   | 380.00 F   | *- F      |
| 209 | 1   |          | <b>*FRONT KNUCKLE WHEEL HUB RH</b><br>(WCP)     | Serviceable   | 380.00 F   | *- F      |
| 210 | 1   |          | <b>*FRONT BRAKE CALIPER RH</b><br>(WCP)         | Serviceable   | 600.00 F   | *- F      |
| 211 | 2   |          | <b>*SET FRONT BRAKE DISC ROTOR ONE</b><br>(WCP) | Serviceable   | 300.00 F   | *- F      |
| 212 | 1   |          | <b>*ENGINE CROSSMEMBER</b><br>(WCP)             | Serviceable   | 950.00 F   | *- F      |
| 213 | 1   |          | <b>*ENGINE GEAR MOUNTING</b><br>(WCP)           | Serviceable   | 180.00 F   | *- F      |
| 214 | 1   |          | <b>*ENGINE CLUTCH ASSY</b><br>(WCP)             | Serviceable   | 480.00 F   | *- F      |
| 215 | 1   |          | <b>*ACCELERATOR PEDAL</b><br>(WCP)              | Repeated      | 480.00 F   | *- F      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                            | Condition   | Repairer's | Amount     |
|-----|-----|----------|----------------------------------------|-------------|------------|------------|
| 216 | 1   |          | *BRAKE PEDAL<br>(WCP)                  | Repeated    | 1,100.00 F | *- F       |
| 217 | 1   |          | *SLIDING DOOR RH<br>(WCP)              | Bent        | 280.00 F   | *280.00 F  |
| 218 | 1   |          | *FRONT WHEEL RIM RH<br>(WCP)           | Serviceable | 1,150.00 F | *- F       |
| 219 | 1   |          | *ALTERNATOR<br>(WCP)                   | Repeated    | 360.00 F   | *- F       |
| 220 | 1   |          | *WIPER MOTOR<br>(WCP)                  | Serviceable | 280.00 F   | *- F       |
| 221 | 1   |          | *WIPER LINK ASSY<br>(WCP)              | Serviceable | 280.00 F   | *- F       |
| 222 | 1   |          | *SET FRONT BUMPER CLIPS                | Necessary   | 50.00 FS   | *50.00 FS  |
| 223 | 1   |          | *SET FRONT GRILLE CLIPS                | Necessary   | 50.00 FS   | *50.00 FS  |
| 224 | 1   |          | *SET FRONT BUMPER PANEL CLIPS          | Necessary   | 50.00 FS   | *50.00 FS  |
| 225 | 1   |          | *FRONT NO PLATE                        | Missing     | 50.00 FS   | *25.00 FS  |
| 226 | 1   |          | *SET SUPPORT PANEL / TOP GARNISH CLIPS | Necessary   | 50.00 FS   | *50.00 FS  |
| 227 | 1   |          | *RADIATOR COOLANT                      | Necessary   | 120.00 FS  | *30.00 FS  |
| 228 | 1   |          | *PANEL INSULATOR CLIPS                 | Necessary   | 380.00 FS  | *380.00 FS |
| 229 | 1   |          | *FRONT TYRE RH                         | Serviceable | 280.00 FS  | *- FS      |
| 230 | 1   |          | *FRONT RIM COVER RH                    | Missing     | 280.00 FS  | *280.00 FS |
| 231 | 1   |          | *ENGINE OIL FILTER                     | Serviceable | 30.00 FS   | *- FS      |
| 232 | 1   |          | *FENDER INNER SHIELD CLIPS             | Necessary   | 80.00 FS   | *80.00 FS  |
| 233 | 1   |          | *FRONT W/S SEALANT                     | Necessary   | 50.00 FS   | *40.00 FS  |
| 234 | 1   |          | *FRONT W/S INNER SEAL                  | Necessary   | 50.00 FS   | *30.00 FS  |
| 235 | 1   |          | *FRONT W/S PRIMER AND CLEANER          | Serviceable | 30.00 FS   | *- FS      |
| 236 | 1   |          | *FRONT W/S ERP BRACKET                 | Necessary   | 12.00 FS   | *12.00 FS  |
| 237 | 1   |          | *FRONT ERP                             | Missing     | 180.00 FS  | *180.00 FS |
| 238 | 1   |          | *SET RADIO                             | Serviceable | 680.00 FS  | *- FS      |

F=Franchise part. S=SpcNett.

**Sub Total (\$\$) 82,005.00 36,902.00**  
**+ Margin on L,N Items 10.00/10.00% (\$\$) 7,958.30 3,564.50**

**Total Parts (\$\$) 89,963.30 40,466.50**

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                         | Lab.Type | Repairer's       | Amount          |
|--------------------------------|---------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>            |                                                                     |          |                  |                 |
| 1                              | STRAIGHTEN & PANEL BEAT ACCIDENT AREA                               | New      | 4,800.00         | 3,800.00        |
| 2                              | SPRAY PAINTING ON ACCIDENT AREA                                     | New      | 2,800.00         | 2,000.00        |
| 3                              | CHECK AND REPAIR WIRING SYSTEM, R&R WIRING TO ASSIST                | New      | 380.00           | 180.00          |
| 4                              | R&R RADIATOR AND PRESS TEST                                         | New      | 180.00           | 60.00           |
| 5                              | R&R CARPET & INNER TRIMBOARD TO ASSIST REPAIR                       | New      | 180.00           | 120.00          |
| 6                              | R&R AIR CON CONDENSOR AND TOP UP A/C GAS                            | New      | 180.00           | 100.00          |
| 7                              | R&R INTER COOLER ASSY                                               | New      | 180.00           | 60.00           |
| 8                              | RESPRAY KUFF TOTE                                                   | New      | 280.00           | 0.00            |
| 9                              | CONDUCT FULL WHEEL ALIGNMENT                                        | New      | 120.00           | 60.00           |
| 10                             | CONDUCT CHASSIS ALIGNMENT                                           | New      | 380.00           | 250.00          |
| 11                             | R&R FRONT W/S GLASS AND INSTALL                                     | New      | 180.00           | 120.00          |
| 12                             | R&R ROOF TOP LINING TO ASSIST REPAIR                                | New      | 180.00           | 80.00           |
| 13                             | R&R DASHBOARD TO ASSISR REPAIR                                      | New      | 380.00           | 250.00          |
| 14                             | R&R AIR CON COOLING COIL SYSTEM AND INSTALL & TOP UP COMPRESSOR OIL | New      | 380.00           | 80.00           |
| 15                             | R&R ENGINE TO ASSIST REPAIR                                         | New      | 500.00           | 0.00            |
| 16                             | R&R GEARBOX TO ASSIST REPAIR                                        | New      | 350.00           | 0.00            |
| 17                             | R&R AIR BAG SYSTEM AND INSTALL & RESETTNG SYSTEM                    | New      | 380.00           | 250.00          |
| 18                             | RESET ABS SYSTEM                                                    | New      | 180.00           | 150.00          |
| 19                             | RESET ENGINE SYSTEM                                                 | New      | 180.00           | 0.00            |
| 20                             | R&R STEERING RACK SYSTEM WITH INSTALL                               | New      | 280.00           | 0.00            |
| 21                             | R&R SUSPENSION SYSTEM AND REPAIR                                    | New      | 480.00           | 200.00          |
| 22                             | R&R DOOR COMPARTMENT RH                                             | New      | 120.00           | 60.00           |
| 23                             | R&R DOOR COMPARTMENT LH                                             | New      | 120.00           | 60.00           |
| 24                             | TOWING CHARGER                                                      | New      | 200.00           | 100.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                     |          | <b>13,390.00</b> | <b>7,980.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >