

2019/2020

ASS. REC. BY:

Surveyor: Hock Ann

REF: 033/SMO/190204/11803-1

Special Instruction:

ASSIGNMENT (Office)

From (Person): Unoh pun loong of SMO Date/Time: 28/01/2020

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 5673T Insured: GBJ 5062L

at Workshop in/s Motor 51 Tel: 8380 2233

of No. 464 Macpherson Road

Policy No: \_\_\_\_\_ Claim No: CMTD1905117/GPL

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 24/10/2019

(Chief's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 9:12am @ 19/11/19 Person Contacted: Julky H.O.D. Endorsement: \_\_\_\_\_

Vehicle IN/OUT

Date/Time	Action/Instruction	Column 1 X
	FBK 5673T - X	
	GBJ 5062L - X	
	Dismantle: 20/11/2019	
	After repair: 26/11/2019	

*[Signature]*  
7/2/2020

Submt LIS \$1,900/- @ 3 days  
( \$5,200/- Red - 73% )

RECEIVED 18 FEB 2020


490  
- 220  
270

PRS

SMO

# ASSIGNMENT

From: 19/11/19  
 Estimated Cost:  
 OD: TP / WS / TP RES / CD RES / EVA / INV / MV  
 To Inspect Vehicle No: FBK 5673T  
 at Workshop no: Motor 51  
 at No. 464 Macpherson Road  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured:  
 (Client's Record)  
 Make of Veh: jocky @ 8380 2233



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection

Bol. or Market Value:  
 IDAC Accident Rpt. Consistent? Yes or No  
 GIA / PR Seen Consistent? Yes or No  
 Est. Repairs: 3 days Res. Yes or No  
 Lum Sum. % 3 Val. Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBK 5673T Reg: 30/12/15  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: YAMAHA FZ150 cc 149  
 Colour: Red AC: Insured / Std / NI / NA  
 Sp Reading: NON C.L.L. Left T/Radio: Insured / Std / NI / NA  
 Engine:  
 C/No: ME1R 61616 F-2001547  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brakes: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / Si/Rim / STD A/Rim or  
 Tyre Size: F: 100/90/R17  
 R: 140/70/R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front: 5-METZELSA Rear: 5-Tim Sum  
 R/Bal: mm R/Bal: mm  
 L/Bal: mm L/Bal: mm  
 D.O.A: 24/11/17 D.O.I: 19/11/17 0128pm  
 Survey held at: motor 51  
 Des. of Damages: Frt / Rear O/S / M/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
* Range - 2-2.5 hr	* FBK 5673T
Days - 3	PRS can

RECEIVED 17 NOV 2019

MV - 6000  
 PV - 3249  
 NV - 2200

6842 0051

Days Of Repair: 3  
 Resurvey No. of Trip: 3

Days Of Repair: 3  
 Resurvey No. of Trip: 3

Days Of Repair: 3

3rd Fee: ☐ Site Insp 15  
☐ Interview 15  
☐ Truck Insp 15  
☐ Fuel Insp 15

Survey Fee:  
 Transportation: 100  
 60460  
 270

Export Fee: PRS

Long Time / 11/11/19

## Nivitha (LKK Auto)

---

**From:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>  
**Sent:** Tuesday, 28 January 2020 3:47 PM  
**To:** Weng Kit  
**Cc:** 'Jerone'; SUR; assignments  
**Subject:** Your ref : AS.191408.KC (PD) ; Sompo ref : CMTD1905117/GPL; RE: Our Ref: FBK5673T (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING FBK 5673T & GBJ 5062L ALONG BARTLEY ROAD ON 24 OCTOBER 2019

### Without Prejudice

Dear Sir,

With reference above, we acknowledge receipt of your letter dated 17/12/2019.

We have clarified with our surveyor, M/s LKK AUTO and that post repair inspection was done. In view of this, we will be conducting the paper resurvey and we will revert to you as soon as possible.

In the meantime, kindly hold hands, thank you.

By copy of Ms Nivitha of M/s LKK AUTO,

Please assist above, thank you.

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



**SOMPO**  
INSURANCE

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @



or



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## Automobile Inspection Report

To: Teng Fook Chee Blk 173 Hougang Ave 1 #10-1457 Singapore 530173		Date : 05/12/2019 Reference No : CAS/19-12/010	
<b><u>General Information</u></b>			
Registration No.	: FBK 5673T		
Accident Date	: 24/10/2019		
<b><u>Particulars of Damaged Vehicle</u></b>			
Colour	: Red	Make & Model	: Yamaha FZN150
Engine Capacity	: 149 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 72660	Engine No.	: G3E3E0004829
Chassis No.	: ME1RG1616F2001547	Steering	: Affected
Registration Date	: 30/10/2015	Brake	: In Order
<b><u>Tyre Condition</u></b>			
	Size	Make	Balance
Front Tyre	100/80R17	METZELER	40%
Rear Tyre	140/70R17	TIMSUN	90%
<b><u>Inspection</u></b>			
Repairer	: Moto 51 Pte Ltd 2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921		
<b><u>Adjustment And Recommendation Cost Of Repair</u></b>			
Repairer's Estimate	: \$10,775.20		
Revised Amount	: \$7,100.00		
Less Excess	: -		
Nett Total	: \$7,100.00		
<b><u>Remarks</u></b>			
(A) Survey was done on 15/11/2019 (B) Re-survey was done on 23/11/2019 (C) Re-survey after repair was done on 25/11/2019 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : FBK 5673T

Our ref : CAS/19-12/010

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Brake lever x (suc)	Serviceable	65.00	-
2	1pc	Brake pedal x (suc)	Serviceable	85.00	-
3	2pcs	Center body cover R/L @ \$156.00 x (R)	Grazed/Broken	312.00	312.00
4	1pc	Front brake disc x (suc)	Bent/Warped	285.00	285.00
5	1 2pcs	Front footrest bracket R/L @ \$85.00 R/H only K 6+	N/S Bent	170.00	<del>85.00</del> 45 ✓
6	1 2pcs	Front footrest R/L @ \$55.00 R/H only ✓ (suc)	N/S Grazed	110.00	55.00 ✓
7	2 2pcs	Front fork assy R/L @ \$650.00 x (R)	Bent/Twisted	1,300.00	1,300.00
8	1pc	Front fork top bracket x (suc)	Bent	165.00	165.00
9	1pc	Front fork under bracket x (suc)	Bent	235.00	235.00
10	1pc	Front mudguard x (R)	Grazed	170.00	170.00
11	1 2pcs	Front side cover R/L @ \$63.00 R/H only ✓ (suc)	Grazed/Broken	126.00	<del>126.00</del> 58 ✓
12	1 2pcs	Front signal lamp R/L @ \$75.00 R/H only ✓ (suc)	Grazed/Bent	150.00	<del>150.00</del> 50 ✓
13	1pc	Front wheel rim x (R)	Dented/Warped	485.00	485.00
14	1pc	Front wheel rim shaft x (suc)	Bent	78.00	78.00
15	1pc	Fuel tank assy x (suc)	Serviceable	450.00	-
16	1 2pcs	Fuel tank side cover R/L @ \$210.00 R/H only ✓ (suc)	Grazed/Broken	420.00	<del>420.00</del> 150 ✓
17	1pc	Fuel tank top cover x (R)	Repair	152.00	-
18	1pc	Gear pedal ✓ 6+	Bent	128.00	<del>128.00</del> 78 ✓
19	1pc	Handle bar ✓ R+	Bent	180.00	<del>180.00</del> 125 ✓
20	1pc	Headlamp assy ✓ suc	Grazed/Broken	325.00	<del>325.00</del> 185 ✓
21	1pc	Headlamp bracket x (R)	Bent	55.00	55.00
22	1 2pcs	Headlamp side cover R/L @ \$71.00 R/H only ✓ suc	Grazed/Broken	142.00	<del>142.00</del> 58 ✓
23	1pc	Headlamp top cover ✓ suc cut	Grazed	88.00	<del>88.00</del> 35 ✓
24	1pc	Meter assy ✓ suc cut	Dented/Grazed	455.00	<del>455.00</del> 250 ✓
25	1pc	Rear exhaust muffler x (R)	Repair	850.00	-
26	1pc	Rear exhaust muffler end cover ✓ (suc)	Grazed	68.00	<del>68.00</del> 55 ✓
27	1pc	Rear exhaust muffler protector ✓ (suc)	Grazed	142.00	<del>142.00</del> 68 ✓
28	2pcs	Rear footrest bracket R/L @ \$85.00 x (R)	N/S Bent	170.00	85.00
29	1 2pcs	Rear footrest R/L @ \$55.00 R/H only ✓ (suc)	N/S Grazed	110.00	55.00 ✓
30	1pc	Rear no plate holder x (suc)	Serviceable	141.00	-
31	2pcs	Rear side board R/L @ \$216.00 x (R)	Grazed/Broken	432.00	432.00
32	2pcs	Rear signal lamp R/L @ \$52.00 x (suc)	Serviceable	104.00	-
33	1pc	Rear wheel guard ✓ CRA	Grazed/Broken	176.00	<del>176.00</del> 95 ✓

**Constant Appraiser Services**

Vehicle No : FBK 5673T

Our ref : CAS/19-12/010

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>					
34	1pc	Rear wheel guard holder LH ✓ (sur)	Deformed/Twisted	91.00	✓ 91.00 40 ✓
35	1pc	Rear wheel guard holder RH X (sur)	Deformed/Twisted	91.00	91.00
36	1pc	Side stand X (R)	Grazed/Bent	96.00	96.00
37	1pc	Tailboard top cover X (sur)	Deformed/Broken	66.00	66.00
				8,668.00	6,541.00
		Less 10%		(866.80)	(654.10)
		Sub total		7,801.20	5,886.90
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1set	Body sticker set ✓ sur	Necessary	145.00	✓ 145.00 60 ✓
2	2pcs	Fork oil seal R/L @ \$25.00 ✓ sur	Necessary	50.00	✓ 50.00 30 ✓
3	1pc	Front no plate ✓ sur	Grazed	20.00	✓ 20.00 15 ✓
4	1pc	Front tyre X (sur)	Serviceable	220.00	-
5	1pc	Front wheel rim bearing X (sur)	Necessary	60.00	✓ 60.00
6	1set	Handle bar balancer set ✓ sur	Grazed	88.00	✓ 88.00 60 ✓
7	1set	Handle bar grip set ✓ sur	Grazed	74.00	✓ 74.00 30 ✓
8	1pc	I U unit ✓ sur	Grazed	192.00	✓ 192.00 157 ✓
9	1set	Mirror set ✓ sur	Grazed	220.00	✓ 220.00 80 ✓
10	1pc	Rear box ✓ sur	Grazed	380.00	✓ 380.00 180 ✓
11	1pc	Rear box bracket X (R)	Bent	160.00	160.00
12	1set	Steering cone/bearing set ✓ sur	Necessary	105.00	✓ 105.00 60 ✓
		Sub total		9,515.20	7,380.90
<u>LABOUR &amp; MISC. CHARGES</u>					
1		To remove, reinstall electrical wiring harness, check lighting. (to FR) ✓		60.00	✓ 30.00 23 ✓
2		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident ✓		450.00	✓ 350.00 150 ✓
3		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident ✓		400.00	✓ 300.00 240 ✓

### Constant Appraiser Services

Vehicle No : FBK 5673T

Our ref : CAS/19-12/010

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
4		<u>LABOUR &amp; MISC. CHARGES (CONT'D)</u>			
		To Straighten body frame to the original position ✓		350.00	<del>250.00</del> 60
		Grand total		10,775.20	8,310.90
Recommended cost of lump sum repair (To its pre-accident condition)					7,100.00

### Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$7,100.00** on a contractual basis. Under normal circumstances, the repair period would be about **10 (Ten)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA

*Paper survey making on  
7/2/20 11:30 AM  
without prejudice  
Arrange after part  
3 day  
Lump sum repair  
H. Ann  
Lhr*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 1402

Parts 10%  
10%

1261.80

Spw 672

Labour 470

2403.80

4 days less 20%

Total 1923.04

Lhr part

Page 4

\$ 1900.00

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## Automobile Inspection Report

To: Teng Fook Chee Blk 173 Hougang Ave 1 #10-1457 Singapore 530173		Date : 05/12/2019	Reference No : CAS/19-12/010
<b><u>General Information</u></b>			
Registration No.	: FBK 5673T		
Accident Date	: 24/10/2019		
<b><u>Particulars of Damaged Vehicle</u></b>			
Colour	: Red	Make & Model	: Yamaha FZN150
Engine Capacity	: 149 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 72660	Engine No.	: G3E3E0004829
Chassis No.	: ME1RG1616F2001547	Steering	: Affected
Registration Date	: 30/10/2015	Brake	: In Order
<b><u>Tyre Condition</u></b>			
	Size	Make	Balance
Front Tyre	100/80R17	METZELER	40%
Rear Tyre	140/70R17	TIMSUN	90%
<b><u>Inspection</u></b>			
Repairer	: Moto 51 Pte Ltd 2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921		
<b><u>Adjustment And Recommendation Cost Of Repair</u></b>			
Repairer's Estimate	: \$10,775.20		
Revised Amount	: \$7,100.00		
Less Excess	: -		
Nett Total	: \$7,100.00		
<b><u>Remarks</u></b>			
(A) Survey was done on 15/11/2019			
(B) Re-survey was done on 23/11/2019			
(C) Re-survey after repair was done on 25/11/2019			
(D) The survey was conducted entirely on WITHOUT PREJUDICE basis.			
(E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Constant Appraiser Services**

Vehicle No : FBK 5673T

Our ref : CAS/19-12/010

**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<b><u>PARTS REPLACEMENT – LIST ITEMS</u></b>			
1	1pc	Brake lever	Serviceable	65.00	-
2	1pc	Brake pedal	Serviceable	85.00	-
3	2pcs	Center body cover R/L @ \$156.00	Grazed/Broken	312.00	312.00
4	1pc	Front brake disc	Bent/Warped	285.00	285.00
5	2pcs	Front footrest bracket R/L @ \$85.00	N/S Bent	170.00	85.00
6	2pcs	Front footrest R/L @ \$55.00	N/S Grazed	110.00	55.00
7	2pcs	Front fork assy R/L @ \$650.00	Bent/Twisted	1,300.00	1,300.00
8	1pc	Front fork top bracket	Bent	165.00	165.00
9	1pc	Front fork under bracket	Bent	235.00	235.00
10	1pc	Front mudguard	Grazed	170.00	170.00
11	2pcs	Front side cover R/L @ \$63.00	Grazed/Broken	126.00	126.00
12	2pcs	Front signal lamp R/L @ \$75.00	Grazed/Bent	150.00	150.00
13	1pc	Front wheel rim	Dented/Warped	485.00	485.00
14	1pc	Front wheel rim shaft	Bent	78.00	78.00
15	1pc	Fuel tank assy	Serviceable	450.00	-
16	2pcs	Fuel tank side cover R/L @ \$210.00	Grazed/Broken	420.00	420.00
17	1pc	Fuel tank top cover	Repair	152.00	-
18	1pc	Gear pedal	Bent	128.00	128.00
19	1pc	Handle bar	Bent	180.00	180.00
20	1pc	Headlamp assy	Grazed/Broken	325.00	325.00
21	1pc	Headlamp bracket	Bent	55.00	55.00
22	2pcs	Headlamp side cover R/L @ \$71.00	Grazed/Broken	142.00	142.00
23	1pc	Headlamp top cover	Grazed	88.00	88.00
24	1pc	Meter assy	Dented/Grazed	455.00	455.00
25	1pc	Rear exhaust muffler	Repair	850.00	-
26	1pc	Rear exhaust muffler end cover	Grazed	68.00	68.00
27	1pc	Rear exhaust muffler protector	Grazed	142.00	142.00
28	2pcs	Rear footrest bracket R/L @ \$85.00	N/S Bent	170.00	85.00
29	2pcs	Rear footrest R/L @ \$55.00	N/S Grazed	110.00	55.00
30	1pc	Rear no plate holder	Serviceable	141.00	-
31	2pcs	Rear side board R/L @ \$216.00	Grazed/Broken	432.00	432.00
32	2pcs	Rear signal lamp R/L @ \$52.00	Serviceable	104.00	-
33	1pc	Rear wheel guard	Grazed/Broken	176.00	176.00

**Constant Appraiser Services**

Vehicle No : FBK 5673T

Our ref : CAS/19-12/010

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<b><u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u></b>			
34	1pc	Rear wheel guard holder LH	Deformed/Twisted	91.00	91.00
35	1pc	Rear wheel guard holder RH	Deformed/Twisted	91.00	91.00
36	1pc	Side stand	Grazed/Bent	96.00	96.00
37	1pc	Tailboard top cover	Deformed/Broken	66.00	66.00
				8,668.00	6,541.00
		Less 10%		(866.80)	(654.10)
		Sub total		7,801.20	5,886.90
		<b><u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u></b>			
1	1set	Body sticker set	Necessary	145.00	145.00
2	2pcs	Fork oil seal R/L @ \$25.00	Necessary	50.00	50.00
3	1pc	Front no plate	Grazed	20.00	20.00
4	1pc	Front tyre	Serviceable	220.00	-
5	1pc	Front wheel rim bearing	Necessary	60.00	60.00
6	1set	Handle bar balancer set	Grazed	88.00	88.00
7	1set	Handle bar grip set	Grazed	74.00	74.00
8	1pc	I U unit	Grazed	192.00	192.00
9	1set	Mirror set	Grazed	220.00	220.00
10	1pc	Rear box	Grazed	380.00	380.00
11	1pc	Rear box bracket	Bent	160.00	160.00
12	1set	Steering cone/bearing set	Necessary	105.00	105.00
		Sub total		9,515.20	7,380.90
		<b><u>LABOUR &amp; MISC. CHARGES</u></b>			
1		To remove, reinstall electrical wiring harness, check lighting. (to FR)		60.00	30.00
2		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		450.00	350.00
3		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		400.00	300.00

**Constant Appraiser Services**

Vehicle No : FBK 5673T

Our ref : CAS/19-12/010

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
4		<u>LABOUR &amp; MISC. CHARGES (CONT'D)</u>			
		To Straighten body frame to the original position		350.00	250.00
		Grand total		10,775.20	8,310.90
Recommended cost of lump sum repair (To its pre-accident condition)					7,100.00

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$7,100.00** on a contractual basis. Under normal circumstances, the repair period would be about **10 (Ten)** working days.

Yours faithfully,

**Constant Appraiser Services**

Lim Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	11/11/2019 13:04
Date Of Accident	24/10/2019 06:55
Exact Location Of Accident	ALONG ROAD 1 BARTLEY ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBK5673T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TENG FOOK CHEE
NRIC No	S7587524Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94227847
Alternative Phone No	OFFICE-94227847
<b>Vehicle Particulars</b>	
Manufacturer	YAMAHA
Model	FZN150-149CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MC/00697921
Cover Note Number	
<b>Driver</b>	
Name of Driver	TENG FOOK CHEE
NRIC No	S7587524Z
Date Of Birth	05/04/1975
Occupation	OUTDOOR
Date Of Driving Pass	09/03/2010
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94227847
Fax Number	
Contact Number	OFFICE-94227847
Email Address	NOEMAIL

Address	BLK 173 HOUGANG AVENUE 1 #10-1457
Postcode	530173
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PAYA LEBAR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 114 HOUGANG AVENUE 1 #01-1270 , POSTCODE: 530114 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2899999 - FAX NO: 62815961
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to Traffic Accident Report No: T/20191024/2096

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ5062L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZAKARIA BIN MOHD ALI
NRIC/Passport Number	S78071411
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	TENG FOOK CHEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBK5673T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 173 HOUGANG AVENUE 1 #10-1457
Postcode	530173

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name: JARCYNAH  
NRIC/FIN No.: S5431454F

### Sketch Plan #2

### SKETCH PLAN

A: 88K00751  
E: 88T5062L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refers do Report No 7/2019/2d/20AG

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: 400014141  
NRIC/PRN No.: 024214345

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



## Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
5 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0030 Fax (65) 6224 0030  
Operating Hours: Monday to Friday, 09:00 - 17:00  
UEN: S660000200 / GST Reg. No.: M100017255

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

#### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MBAN19142953 Vehicle Registration No: FBK 5673T  
Name (as shown in NRIC): Teng Fook Chue NRIC/FIN/Passport No: G7585242  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address: Blk 171 Hengsing Avenue 1 #10-1057 Singapore (S40173)  
Contact (Tel): \_\_\_\_\_ Mobile No: 94227647  
Email Address: \_\_\_\_\_  
Date of Accident: 24/11/2019 Time of Accident: 06:58 AM  
Place of Accident: Along Road 1 Bentley Road  
Insurance Company: Direct Asia Insurance (Singapore) Pte Ltd

#### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Change from Reporting to Third Party Claim

707  
Policyholder / Driver's Signature  
Date: 14/11/2019 @ 1:58 PM

DFW  
Reporting Centre Personnel's Signature  
Name: Chen Chuan Lim  
NRIC/FIN No: G7717255R  
Date: 14/11/2019

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/10/2019 18:52
Date Of Accident	24/10/2019 07:00
Exact Location Of Accident	BARTLEY ROAD AND SERANGOON AVENUE 1 JUNCTION.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ5062L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DIESEL INJECTRONIC PTE LTD
Co Reg No	200206731N
Email Address	ROSELIND@DIESELCOMMERCIAL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67491155

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE VAN TURBO 5DR MT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D18MTHCVE003196
Cover Note Number	

### Driver

Name of Driver	ZAKARIA BIN MOHD ALI
NRIC No	S78071411
Date Of Birth	05/04/1978
Occupation	INDOOR
Date Of Driving Pass	12/11/2015
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87178358
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SITI FAUZIAH GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TAMPINES NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to police report : On 24/10/2019 at about 0700hrs, while I was travelling along Bartley Road on second lane, the vehicle in front of me came to a stop, signalling right with the intention to cut into the first lane. As I wanted to proceed straight, I signaled left with the intention to filter into the left lane. After signaling left and checking my blind spot to ensure there is no oncoming vehicle, I slowly filtered into the left lane. All of a sudden, the motorcycle collided with the left front passenger area of my van. He skidded and fell onto the ground. Soon after traffic police and ambulance was called in. The person was conveyed conscious first before traffic police arrived. I was then informed by traffic police to lodge a traffic accident report. I would like to state that I have a front vehicle camera and the memory card have been taken away by traffic police. I did not suffer any injuries.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK5673T
Vehicle Make/Model/Colour	YAMAHA / FZN150
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TENG FOOK CHEE
NRIC/Passport Number	S7587524Z

Contact Number	84227847
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TENG FOOK CHEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBK5673T
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



**VERIFY BY AJAX MARS (ARC)  
REPORTING OFFICER  
VOO CHEON YEE**

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/YIN No.:

25-10-2019

# Sketch Plan #2

A-2536062L  
 B-2536062L

Along Bentley Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I hereby declare the foregoing particulars are true to my knowledge.

Witness's Signature  
 Date & Time

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

VERIFY BY ALAN MARS (AEC)  
 REPORTING OFFICER  
 YOU CHECK YES

Reporting Officer's Signature  
 Name  
 M00178-40

## Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



T/20191024/2186

1 of 3

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No: T/20191024/2186

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/10/2019 19:57		Vide Report No.:		Station Diary No.: 108	
<b>Informant's Particulars</b>					
Name of Informant: ZAKARIA BIN MOHD ALI		Address: APT BLK 897A TAMPINES STREET 81 #04-712 SINGAPORE 521897			
ID Type / ID No.: NRIC NO / 578071411		Contact No.: Home/Office:		Mobile: 67178358	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 41	Date of Birth: 05/04/1978	Type of Informant: Driver		
Race: Malay		Language:		Institution / School Name:	
Occupation: DELIVERY DRIVER		Driving Licence Information: Class: 3		Date of Expiry:	

## General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/10/2019 07:00	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 BARTLEY ROAD SERANGOON AVENUE 1 BEFORE THE JUNCTION				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance Yes

## Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
F8K5673T	Motorcycle					0
GBJ5062L	Van					1

## Details of Person Involved

Any Pedestrian involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20191024/2166

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

2 of 3

Report No: T/20191024/2166

## CONTINUATION OF REPORT

<b>Rider</b>			
Name	TENG FOOK CHEE		ID No. S7587524Z
Related Vehicle	FBK5673T (Motorcycle)		Contact No. 84227847
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	ZAKARIA BIN MOHD ALI		ID No. S78071411
Related Vehicle	GBJ5062L (Van)		Contact No. 67178358
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 24/10/19, at about 0700hrs, while I was travelling along Bartley Road on second lane, the vehicle in front of me came to a stop, signaling right with the intention to cut into the first lane. As I wanted to proceed straight, I signaled left with the intention to filter into the left lane. After signaling left and checking my blind spot to ensure there is no oncoming vehicle, I slowly filtered into the left lane. All of a sudden, the motorcycle collided with the left front passenger area of my van. He skidded and fell onto the ground. Soon after, traffic police and ambulance was called in. The person was conveyed conscious first before traffic police arrived. I was then informed by traffic police to lodge a traffic accident report.

I would like to state that I have a front vehicle camera and the memory card have been taken away by traffic police. I did not suffer any injuries.

Sketch Plan #5



**SINGAPORE  
POLICE FORCE**



T/20191024/2196

Police Station Of Origin  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529662  
Tel No: 1800-5871999

3 of 3

Report No: T/20191024/2196

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report  
G /  
Sgt 3 JONATHAN LIM XIONG HAI

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
24/10/2019 19:57

Officer In Charge Of Case:  
TP / QIT /  
Sr Staff Sgt SYED ZAYID MUHAMMAD BIN  
SYED ABDUL WAHID ALHINDUAN  
Contact No: 65476364

Authentication Stamp  
NP162

Classification Of Case:



SINGAPORE  
POLICE FORCE

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO19020470/Hsd3e2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 18-02-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBJ 5062L	Veh. Inspected	FBK 5673T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905117/GPL	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	28/01/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA FZN150	c.c	149	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ME1RG1616F2001547	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	100/80 R17	METZELER	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	TIMSUN	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/10/2019	Inspection Date	19/11/2019	
Survey held at	MOTOR 51-NO.464 MACPHERSON ROAD			
Repairer	-			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 5673T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BRAKE LEVER	SERVICEABLE	65.00	-
1	BRAKE PEDAL	SERVICEABLE	85.00	-
2	CENTER BODY COVER R/L @\$156.00	TO REPAIR SEE LABOUR	312.00	-
1	FRONT BRAKE DISC	SERVICEABLE	285.00	-
2	FRONT FOOTREST BRACKET R/L @\$85.00	O/S BENT	170.00	45.00
2	FRONT FOOTREST R/L @\$55.00	O/S SCRATCHED	110.00	55.00
2	FRONT FORK ASSY R/L @\$650.00	TO REPAIR SEE LABOUR	1,300.00	-
1	FRONT FORK TOP BRACKET	SERVICEABLE	165.00	-
1	FRONT FORK UNDER BRACKET	SERVICEABLE	235.00	-
1	FRONT MUDGUARD	TO REPAIR SEE LABOUR	170.00	-
2	FRONT SIDE COVER R/L @\$63.00	N/S CRACKED	126.00	58.00
2	FRONT SIGNAL LAMP R/L @\$75.00	N/S SCRATCHED	150.00	50.00
1	FRONT WHEEL RIM	TO REPAIR SEE LABOUR	485.00	-
1	FRONT WHEEL RIM SHAFT	SERVICEABLE	78.00	-
1	FUEL TANK ASSY	SERVICEABLE	450.00	-
2	FUEL TANK SIDE COVER R/L @\$210.00	N/S SCRATCHED	420.00	150.00
1	FUEL TANK TOP COVER	TO REPAIR SEE LABOUR	152.00	-
1	GEAR PEDAL	BENT	128.00	78.00
1	HANDLE BAR	BENT	180.00	125.00
1	HEADLAMP ASSY	SCRATCHED	325.00	185.00
1	HEADLAMP BRACKET	TO REPAIR SEE LABOUR	55.00	-
2	HEADLAMP SIDE COVER R/L @\$71.00	N/S SCRATCHED	142.00	58.00
1	HEADLAMP TOP COVER	SCRATCHED / CUT	88.00	35.00
1	METER ASSY	SCRATCHED / CUT	455.00	250.00
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	850.00	-
1	REAR EXHAUST MUFFLER END COVER	SCRATCHED	68.00	55.00

Report Ref No. CS3/SMO19020470/Hsd3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST MUFFLER PROTECTOR	SCRATCHED	142.00	68.00
2	REAR FOOTREST BRACKET R/L @\$85.00	TO REPAIR SEE LABOUR	170.00	-
2	REAR FOOTREST R/L @\$55.00	N/S SCRATCHED	110.00	55.00
1	REAR NO PLATE HOLDER	SERVICEABLE	141.00	-
2	REAR SIDE BOARD R/L @\$216.00	TO REPAIR SEE LABOUR	432.00	-
2	REAR SIGNAL LAMP R/L @\$52.00	SERVICEABLE	104.00	-
1	REAR WHEEL GUARD	CRACKED	176.00	95.00
1	REAR WHEEL GUARD HOLDER LH	SCRATCHED	91.00	40.00
1	REAR WHEEL GUARD HOLDER RH	SERVICEABLE	91.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	96.00	-
1	TAILBOARD TOP COVER	SERVICEABLE	66.00	-
	LESS 10% DISCOUNT		-866.80	-140.20
			7,801.20	1,261.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET BODY STICKER (SN)	NECESSARY	145.00	60.00
2	FORK OIL SEAL R/L @\$25.00 (SN)	NECESSARY	50.00	30.00
1	FRONT NO PLATE (SN)	SCRATCHED	20.00	15.00
1	FRONT TYRE (SN)	SERVICEABLE	220.00	-
1	FRONT WHEEL RIM BEARING (SN)	SERVICEABLE	60.00	-
1	SET HANDLE BAR BALANCER (SN)	SCRATCHED	88.00	60.00
1	SET HANDLE BAR GRIP (SN)	SCRATCHED	74.00	30.00
1	I U UNIT (SN)	SCRATCHED	192.00	157.00
1	SET MIRROR (SN)	CRUMPLED	220.00	80.00
1	REAR BOX (SN)	SCRATCHED	380.00	180.00
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	160.00	-
1	SET STEERING CONE / BEARING (SN)	NECESSARY	105.00	60.00
			1,714.00	672.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)		60.00	20.00

Report Ref No. CS3/SMO19020470/Hsd3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		450.00	150.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF CENTER BODY COVER R/L, FRONT FORK ASSY R/L, FRONT MUDGUARD, FRONT WHEEL RIM, FUEL TANK TOP COVER, HEADLAMP BRACKET, REAR EXHAUST MUFFLER, REAR FOOTREST BRACKET R/L, REAR SIDE BOARD R/L, SIDE STAND AND REAR BOX BRACKET.		400.00	240.00
	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.		350.00	60.00
			1,260.00	470.00
GRAND TOTAL			10,775.20	2,403.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS3/SMO19020470/Hsd3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.