

27/03/2001

ASS. REC. BY:

REF:

es/SMO20001444/RHd3ⁿ²

Special Instruction:

A Surveyor: KOSU

ASSIGNMENT (Office)

From (Person): Amce Teo

of

SMO

Date/Time: 28/1/2020 @ 4:49pm

Estimated Cost:

Bill to:

OD-TP-WS-TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 6250M

Insured:

ABG 5355H

at Workshop in/s

Wong Mong Motor

Tel:

631 61131

of

50 Bukit Batok St. 23 # 01-06

Policy No:

Claim No:

CMTD2000405/THE

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:52pm @ 28/1/2020

Person Contacted:

Ms. Henry

Vehicle IN/OUT

Date/Time

Action/Instruction

Johny/11

SKZ 6250M-X

ABG 5355H-X

6/2 @ 4:34pm. Revert pending estimate

Confirm Lump Sum \$3500 (Red. 3669.35: 51%)

RES. REC. BY:

Jasur

REF:

SMD

8776

ASSIGNMENT

From:

Date: 5/02/2020

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKZ 6250M

at Workshop m/s

Woon Meng Motor

of

50 Bukit Batok Street 23 #01-06

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

vehicle in Rdy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKZ 6250M

Yr Regn: 2016 / JAN

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

HONDA JAZZ 1.5 VTI

C.C. 1498

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

092986

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHM6K58506X201491

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

185/55R16

R:

7"

BS: ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/01/2020

D.O.I.

05/02/2020

Survey held at

WOON MENG

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimate not Ready

RECEIVED 25 FEB 2020

Date/Time, File Pass to?



Prel. Report

1) 24/2 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation:

S + RS. \$

Phone

Others

TOTAL

250

Report Format:

TP

Lump Sum / L.P.I. (\$)

3500/-

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 6 February 2020 4:34 PM
To: Admin-D (LKKAuto); 'Teo, Grace'; 'Choo, Thelma'; assignments
Cc: 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR
Subject: RE: CMTD2000405/THE - PRI/ GBG5355H (Sompo Insured) & SKZ6250M Along Sentosa Gantry On 22/01/2020

Dear Sir/Madam,

Please be informed that we have inspected the SKZ 6250M on 05/02/2020
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 28 January 2020 4:55 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Choo, Thelma' <thelma.choo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD2000405/THE - PRI/ GBG5355H (Sompo Insured) & SKZ6250M Along Sentosa Gantry On 22/01/2020

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

"Wishing you a Happy and Prosperous Lunar New Year"



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 28 January 2020 4:49 PM
To: Heng Sew Sow; Choo, Thelma; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com
Cc: Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD2000405/THE - PRI/ GBG5355H (Sompo Insured) & SKZ6250M Along Sentosa Gantry On 22/01/2020
Attachments: 20200123184003.tif

Our Reference : CMTD2000405/THE
Your Reference: SKZ6250M

Without Prejudice
EMAIL ONLY

Date: 28.01.2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S WOON MENG MOTOR PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING GBG5355H & SKZ6250M ON 22.01.2020

We refer to your email reply of today.

We will appoint Mr. Mohd Taufikh of LKK Auto Consultants to conduct the survey.

Hi **LKK Auto**,

Please make the arrangement to survey for **SKZ6250M** on a without prejudice basis and admission of liability.

Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63224 681/ thelma.choo@sompo.com.sg.

Please revert with your report upon completion of survey to my colleague, **Ms. Thelma.**

Thank you.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Heng Sew Sow <woonmeng@singnet.com.sg>

Sent: Tuesday, January 28, 2020 4:22 PM

To: Teo, Grace <grace.teo@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: CMTD2000405/THE - PRI/ GBG5355H (Sompo Insured) & SKZ6250M Along Sentosa Gantry On 22/01/2020

Dear Teo (Grace)

Mohd Taufikh (West area)

Best Regards,
Heng Sew Sow (Ms)
Woon Meng Motor Pte Ltd
Tel: 6316 1131/51
Fax: 6316 7050

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Tuesday, 28 January 2020 9:50 AM

To: Woon Meng <woonmeng@singnet.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD2000405/THE - PRI/ GBG5355H (Sompo Insured) & SKZ6250M Along Sentosa Gantry On 22/01/2020

Our Reference : CMTD2000405/THE
Your Reference: SKZ6250M

Without Prejudice
EMAIL ONLY

Date: 28.01.2020

Attention:
M/S WOON MENG MOTOR PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING GBG5355H & SKZ6250M ON 22.01.2020

We refer to your Notice of Accident dated 23.01.2020.

Please be informed that Ms. Thelma Choo the handler of this case who can be contacted at 63224 681/
thelma.choo@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Woon Meng <woonmeng@singnet.com.sg>

Sent: Thursday, January 23, 2020 6:48 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: Accident Involving SKZ6250M & GBG5355H (Sompo Insured) Along Sentosa Gantry On 22/01/2020

Dear Sir/Madam,

We refer to the above accident

Kindly be advised that we will be assisting our client, owner of vehicle no: SKZ6250M to submit a third party claim against your insured vehicle. We would like to proceed with direct settlement.

Please arrange for your surveyor to liaise with us for an inspection on our client's Vehicle at your earliest convenience.

Attached GIA report for your reference.

Location : 50, Bukit Batok St 23 # 01- 06 Midview Building (S) 659578

Thank you.

Woon Meng Motor Pte Ltd

Tel : 63161131

Fax : 63167050

Denise Tay (LKKAUTO)

From: Woon Meng <woonmeng@singnet.com.sg>
Sent: Thursday, 20 February 2020 2:29 PM
To: Rasul (LKKAUTO)
Subject: after photo of SKZ6250M

Dear Rasul,

We refer to the matter below for your kind attention.

Kindly be informed that we confirm acceptance of finalised amount \$ 3500.

Thank you & Warmest Regards,

Woon Meng Motor Pte Ltd
50, Bukit Batok Street 23
#01-06 Midview Building, Singapore (659578) Tel : 63161131 / 63161151 || Fax : 63167050

-----Original Message-----

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Wednesday, 19 February 2020 4:11 PM
To: Heng Sew Sow <woonmeng@singnet.com.sg>
Subject: RE: after photo of SKZ6250M

Hi Ms Heng,

As spoken, finalised amount is \$ 3500 / 6 days lump sum Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Heng Sew Sow [mailto:woonmeng@singnet.com.sg]
Sent: Wednesday, 19 February, 2020 2:28 PM
To: Rasul (LKKAUTO)
Subject: FW: after photo of SKZ6250M

Best Regards,

Heng Sew Sow (Ms)

Woon Meng Motor Pte Ltd

Tel: 6316 1131/51

Fax: 6316 7050

-----Original Message-----

From: Heng Sew Sow <woonmeng@singnet.com.sg>

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Address : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : Sompo Insurance Singapore Pte Ltd
 Motor Claims Dept

Date : 05 Feb 2020

Dear Sirs :

Fax : 6221 3147

RE : ESTIMATE COST FOR HONDA JAZZ 1.5 - SKZ6250M ACCIDENT INVOLVING SKZ6250M & GBG5355H ON 22/01/2020

ITEMS	DESCRIPTION	QTY	PRICE
1	Front bumper <i>de</i>	1pc	\$ 568.50
2	Front bumper retainer @\$35.12ea. <i>X su</i>	2pcs	\$ 70.24 X
3	Front bumper lower grille <i>X su</i>	1pc	\$ 258.60 X
4	Front bumper fog lamp o/s. ? <i>X su</i>	1pc	\$ 358.61 X
5	Front bumper fog lamp grille o/s. <i>cut</i>	1pc	\$ 35.20
6	Front center grille <i>ca</i>	1pc	\$ 415.23
7	Emblem <i>ca</i>	1pc	\$ 45.83
8	Front headlamp @\$1392.72ea <i>RH-ca / LH-? X su</i>	2pcs	\$ 2,785.44 <i>1392.72</i>
9	Front headlamp lower bracket @\$56.42ea <i>ca</i>	2pcs	\$ 112.84 <i>56.42</i>
10	Front bonnet <i>bt</i>	1pc	\$ 668.25
11	Front bonnet hinge @\$53.04ea. <i>X su</i>	2pcs	\$ 106.08 X
12	Front bonnet lock <i>X su</i>	1pc	\$ 114.28 X
13	Front support panel <i>repair</i>	1pc	\$ 489.50 X
			\$ 6,028.60
			\$ (1,205.72)
			\$ 4,822.88
	Less 20%		
	Sum Carried Forward		

3182.15
20%
2545.72

Sum Carried Forward

\$ 4,822.88

Labour Charge & Misc

To remove, repair, replace & install damaged

\$ ~~1,000.00~~ 700

To R & R wiring.

\$ ~~60.00~~ 30

To R & R front radiator.

\$ ~~120.00~~ 80

To R & R air con system. }

\$ ~~150.00~~ 100

To refill & top up air con gas }

To putty & spray painting.

\$ ~~900.00~~ 800

Total

\$ 7,052.88

1710

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

 24/2/2020

P - 2545.72

L - 1710.00

Suppl. p - 21.47

S/N - 35.00

T - 4372.19

20%

3,497.78

L/S - 3,500

6 days

Rasul

Hp 900/100 68

6 days

L/S

05/02/2020 @ 1645

Recovery after repair

7169.35!

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng@singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : Sampo Insurance Singapore Pte Ltd
Motor Claims Dept

Date : 05 Feb 2020

Dear Sirs :

Fax : 6221 3147

RE : ESTIMATE COST FOR HONDA JAZZ 1.5-SKZ6250M (SUPPLEMENTARY)
ACCIDENT INVOLVING SKZ6250M & GBG5355H ON 22/01/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front center grille emblem base <i>CR</i> ✓	1pc	\$ 101.83
			\$ 101.83
	Less 20%		\$ (20.36)
			\$ 81.47
2	Front number plate <i>BT</i> ✓	1pc	\$ 35.00
Total			\$ 116.47

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO20001494/R1td3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 26-02-2020	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 5355H	Veh. Inspected	SKZ 6250M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000405/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	28/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ 1.5 VTIR	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850GX201491	Colour	BLACK	
Odometer	92986	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	5 mm	
L/H Front Tyre	185/55 R16	DUNLOP	5 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/01/2020	Inspection Date	05/02/2020	
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 6250M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	568.50	568.50
2	FRONT BUMPER RETAINER @\$35.12	SERVICEABLE	70.24	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	258.60	-
1	FRONT BUMPER FOG LAMP O/S	SERVICEABLE	358.61	-
1	FRONT BUMPER FOG LAMP GRILLE O/S	CUT	35.20	35.20
1	FRONT CENTER GRILLE	CRACKED	415.23	415.23
1	EMBLEM	NECESSARY	45.83	45.83
2	FRONT HEADLAMP @\$1392.72	O/S CRACKED / N/S SERVICEABLE	2,785.44	1,392.72
2	FRONT HEADLAMP LOWER BRACKET @\$56.42	CRACKED (1 PC ONLY)	112.84	56.42
1	FRONT BONNET	BENT	668.25	668.25
2	FRONT BONNET HINGE @\$53.04	SERVICEABLE	106.08	-
1	FRONT BONNET LOCK	SERVICEABLE	114.28	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	489.50	-
1	FRONT CENTER GRILLE EMBLEM BASE (ADDITIONAL)	CRACKED	101.83	101.83
	LESS 20% DISCOUNT		-1,226.09	-656.80
			4,904.34	2,627.18
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (ADDITIONAL)(SN)	BENT	35.00	35.00
			35.00	35.00
LABOUR				
	TO REMOVE,REPAIR,REPLACE & INSTALL DAMAGED.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,000.00	700.00
	TO R&R WIRING.		60.00	30.00
	TO R&R FRONT RADIATOR.		120.00	80.00
	TO R&R AIR CON SYSTEM.		150.00	100.00
	TO REFILL & TOP UP AIR CON GAS.		900.00	800.00
	TO PUTTY & SPRAY PAINTING.		2,230.00	1,710.00

Report Ref No. CS/SMO20001494/R1td3n2



GRAND TOTAL		7,169.34	4,372.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00

Report Ref No. CS/SMO20001494/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.