

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



- CAR IN -

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

29 JAN 2020

Estimate No. : b1 54262
Date Estimated : 29/01/2020
Prepared By : Shukhaizi Bin Misbah

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Chan Hwee Keng
834 Hougang Central
#08-564

Singapore 530834

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX3659L	WBA2B32090V926348	26/03/2018	216d CAT	0

DESCRIPTION

To replace rear bumper including attachment

VALUE

1,275.00

To painting rear bumper

1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

177.00

sundries

80.00

Total Labour 1: **2,570.00**DESCRIPTION

REAR BUMPER PANEL PRIMED (PDC)

QTYPRICVALUE

RR BUMPER LH SIDE GUIDE

1

1,045.45

1,045.45

RR BUMPER RH SIDE GUIDE

1

61.35

61.35

WASHER GASKET

1

11.20

11.20

REAR BUMPER CARRIER

1

460.40

460.40

RR BUMPER LH INNER SIDE GUIDE

1

61.35

61.35

RR BUMPER RH INNER SIDE GUIDE

1

61.35

61.35

Total Parts : **1,762.45**

Labour 1 : 2,570.00

Parts : 1,762.45

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 303.27

Grand Total : **4,635.72**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **