

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27532

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0107/2020/NS
Date	:	24-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tan Choon Heng
Address	:	133 Serangoon Avenue 3 #03-09 Singapore 556113
Telephone	:	HP +65 97869681
Type of Claim	:	Own Damage Claims
Policy No.	:	1900163619
Vehicle No	:	EY 6262 E
Model Code	:	Audi A4 Sedan 2.0 TFSI 8W
Model / Year	:	Sep-19
Engine No	:	CVK 081954
Chassis No	:	WAUZZZF42KA073683
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	23-Jan-20
Place of Accident	:	CTE To Ang Mo Kio Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 6262 E

S/N Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1 To tow vehicle from scene of accident.	S/N \$ 280.00	X
2 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
3 To remove and renew aircond condenser and radiator. And charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	?
4 To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 350.00	X
SUB TOTAL LABOUR CHARGES		: <u>\$ 2,310.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 6262 E

<u>S/N Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
To dismantle and renew front bumper, rhs front fender, bonnet and both headlights.		
5 To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00	2000 (without lock carrier) 3250 (with lock carrier)
6 To respray front bumper, rhs front fender, lhs front fender, bonnet, hinges, both A-upper pillars and lhs front door.	\$ 5,600.00	2200
7 To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES	: <u>\$ 13,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 6262 E

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>del d</i>	\$ 2,068.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 553.00	X
3	FRONT BUMPER SECURING STRIP <i>?</i>	2 \$ 67.00	?
4	FRONT BUMPER GRILLE - CENTRE <i>del d</i>	\$ 185.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00	X
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2 \$ 118.00	X
7	RADIATOR GRILLE <i>del d</i>	\$ 2,058.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>del d</i>	2 \$ 688.00	344
9	FRONT BUMPER CARRIER <i>Best</i>	\$ 757.00	✓
10	FRONT BUMPER FOAM FILLER PIECE <i>del d</i>	\$ 117.00	✓
11	FRONT BUMPER COVER <i>del d</i>	\$ 120.00	✓
12	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 34.00	X
13	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 36.00	X
14	LOCK CARRIER <i>del d</i>	\$ 129.00	✓
15	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2 \$ 54.00	?
16	CAUTION SIGN STICKER <i>new</i>	NEC \$ 13.00	✓
17	AIRCON STICKER <i>new</i>	NEC \$ 7.00	✓
18	EXTERNAL TEMPERATURE SENSOR <i>?</i>	\$ 55.00	?
19	TEMPERATURE SENSOR BRACKET <i>?</i>	\$ 18.00	?
20	HORN - LH HIGH TONE <i>?</i>	\$ 38.00	?
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 7,313.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 6262 E

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	HORN - RH LOW TONE ?	\$	270.00 ?
22	SPRING SHACKLE - LH / RH ?	2 \$	54.00 ?
23	FRONT PARKING AID SENSOR - INNER / OUTER new	2	TBC +
24	FRONT PARKING AID SEAL RING new	4 \$	14.00 +
25	FRONT FENDER - RH Buckled	\$	722.00 ✓
26	FRONT FENDER ATTACHMENT PARTS ?	\$	190.00 ?
27	FRONT FENDER CLOSING ELEMENT - RH new	\$	47.00 +
28	FRONT FENDER BRACKET - RH new	\$	33.00 +
29	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH new	\$	46.00 +
30	FRONT FENDER BRACE - RH new	\$	112.00 +
31	FRONT WHEEL HOUSING LINER - RH } new	\$	228.00 +
32	WHEEL HOUSING LINER ATTACHMENT PARTS }	\$	219.00 +
33	FRONT WHEEL SPOILER - RH } Not new	\$	69.00 +
34	WHEEL SPOILER TRIM - RH }	\$	34.00 +
35	STONE CHIP GUARD - RH new	\$	48.00 ✓
36	BONNET Dented	\$	2,634.00 ✓
37	BONNET ATTACHMENT PARTS ?	\$	388.00 ?
38	BONNET LID HINGE - LH / RH new	2 \$	574.00 +
39	BONNET IMPACT PROTECTION - CENTRE Dented	\$	26.00 ✓
40	BONNET IMPACT PROTECTION - RH Dented ?	\$	26.00 ✓
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 5,734.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 6262 E

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
41	BONNET IMPACT PROTECTION - LH ?	\$	26.00	?
42	FENDER LEDGE COVER - RH ?	\$	29.00	?
43	FENDER LEDGE TOP COVER ?	\$	21.00	?
44	BONNET GAS FILLED STRUT ?	2 \$	224.00	+
45	BONNET STRIKER - LH / RH ?	2 \$	94.00	+
46	BONNET LID LOCK	2 \$	403.00	+
47	BONNET BOWDEN CABLE - CENTRE ?	\$	54.00	?
48	BONNET BOWDEN CABLE ?	\$	54.00	?
49	BONNET RELEASE LEVER ?	\$	13.00	?
50	BONNET LID LOCK CABLE	\$	69.00	+
51	PLENUM CHAMBER COVER	\$	92.00	+
52	BONNET SOUND ABSORBER	\$	323.00	+
53	LED HEADLIGHT - LH / RH	2 \$	14,642.00	✓
54	MAIN LIGHT ELECTRONIC POWER MODULE	\$	732.00	+
55	LIGHT CONTROL SYSTEM CONTROL UNIT	\$	707.00	+
56	HEADLIGHT HOSE - LH	\$	34.00	+
57	HEADLAMP ASSEMBLY SPACER ?	2 \$	75.00	?
58	HEADLAMP ASSEMBLY SPACER ?	2 \$	79.00	?
59	LIFT CYLINDER - LH / RH	2 \$	396.00	+
60	HEADLIGHT CORRUGATED PIPE	\$	88.00	+
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 18,155.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 29/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 07 Days (Without Load carrier)
10 Days (With Load carrier)

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant