

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

95070 - C00001

SL: SERVICE SALES - PC

Mr Yap Siong
18 Ceylon Road
#01-04

Singapore 429748

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 29/01/2020

WIP No. : 60271

Veh.In/Out:

*Tel.No. : Mobile: 94555419

Reg.No. : SLV4013D

Reg.date : 28/12/2017

Mileage : 0

Chassis No: SAJAB4AX2JCP28177

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Mr Yap Siong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, (900) FRT GRILLE, HEADLAMP RH, FRT BUMPER BEAM, FRT BUMPER FOAM, REPAIR FENDER RH, ETC	0	2700.00	0		2,700.00 S	1800
800	TO PUTTY SPRAYPAINT AND (800) BLENDING OF PAINT ON FRT BUMPER, FENDER RH, ETC	0	2400.00	0		2,400.00 S	1600
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	510.00	0		510.00 S	/
280	TO FOCUS HEADLAMP	0	170.00	0		170.00 S	/
R06	FRT NUMBER PLATE & HOLDER / BT	0	60.00	0		60.00 S	/
	COVER-BUMPER /	1.0 EA	1755.20			1,755.20 S	
	GRILLE-RADIA / CRA	1.0 EA	446.60			446.60 S	
	INSERT-FOAM ?	1.0 EA	54.20			54.20 S	
	JT2H25309/BEAM-BUMPE ?	1.0 EA	899.70			899.70 S	
	HEADLAMP / CRA	1.0 EA	3388.50			3,388.50 S	

SERVICE ESTIMATE

95070 - C00001	SL: SERVICE SALES - PC	GST Reg.No:M28920628X
Mr Yap Siong		Inv.No. . . : B&P 0 Page 2
18 Ceylon Road		Inv.date. . : 29/01/2020
#01-04		WIP No. . . : 60271
Singapore 429748		Veh.In/Out:
		*Tel.No. . . : Mobile: 94555419
		Reg.No. . . : SLV4013D
Closed by : Patricia Kueh Anak S		Reg.date. . : 28/12/2017
Svc Consultant :		Mileage . . : 0
Remarks : Mr Yap Siong		Chassis No: SAJAB4AX2JCP28177

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	PANEL-FENDER <i>Repair X</i>	1.0 EA	684.00			684.00	S
	MOUNTING-BRA <i>?</i>	1.0 EA	26.10			26.10	S
	JET-POWERWASH <i>?</i>	1.0 EA	88.30			88.30	S
	ADHESIVE SEALER FL2 <i>/ AC</i>	1.0 EA	682.50			682.50	S

4 Days. Not Authorised. \$750.
 before paint photos.
 Emo Qian - 82880282
 31/1/2020

	Gross Total.	13,865.10
Labour Total	5,840.00	Net.....
Parts Total	8,025.10	GST @ 7.0%
Package Total	0.00	Total.....
		Paid.....
		Please Pay..
		14,835.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated