

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X




Final Report

(S/L) SEAM SEAL 300ML	33.80	1	0	33.80
-----------------------	-------	---	---	-------

SUPPLEMENTARY ITEMS

Total Labour :	10,044.00
Total Parts :	4,708.69
Total Labour & Parts :	14,752.69
GST @7%:	1,032.69
Grand Total :	15,785.38



CAR RENTAL - \$1100.00 (11 DAYS)
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 54276**
Date Estimated : **29/01/2020**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Dolly Lim Mrs Dolly Looi
65 Stratton Drive

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 805663

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU6500T	WBA5A52090D8235	30/06/2015	528iA	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear right fender and right tail lamp etc including to make good rear bumper, to remove and install body parts in order to carry out painting job.	5,100.00	0	5,100.00
To respray rear right fende, rear bumper right roof frame and tail end panel etc.	2,802.00	0	2,802.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00	0	742.00
To carry out body cavity preservation. (For cut panel).	451.00	0	451.00
To replace rear windscreen glass.	574.00	0	574.00
To conduct water leak tests.	75.00	0	75.00
Sundries.	150.00	0	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
3M S/F PREMIUM REAR WINDSCREEN	252.34	1	0	252.34
RR RH FENDER	1,880.55	1	0	1,880.55
REINFORCEMENT PLATE C PILLAR RH	53.75	1	0	53.75
REINFORCEMENT PLATE ROCKEL PANEL RH	53.75	1	0	53.75
# RR RH MOUNT	193.15	1	0	193.15
RR WINDOW GREEN	921.00	1	0	921.00
RR RH LIGHT IN SIDE PANEL	625.45	1	0	625.45
BLIND RIVET AVIBVLB	0.55	30	0	16.50
# (S/L) CLEANER R2 500ML	12.50	1	0	12.50
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1	0	326.80
PUNCH RIVET N4	0.55	40	0	22.00
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2	0	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	27.85	1	0	27.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 54276**
Date Estimated : **29/01/2020**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Dolly Lim Mrs Dolly Looi
65 Stratton Drive

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 805663

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU6500T	WBA5A52090D8235	30/06/2015	528iA	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# RR RH MOUNT	193.15	1	0	193.15
# (S/L) CLEANER R2 500ML	12.50	1	0	12.50

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	205.65
Total Labour & Parts :	205.65