

Specialist

ASS. REC. BY:

REF:

09/MSG20001609 / Kg d3d

Special Instructions:

Surveyor: Kmhwh

ASSIGNMENT (Office)

From (Person):

Crystal Lee

of

MSG

Date/Time:

30/1/2020 @ 4:27pm

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SMG 2736G

Insured:

SMN 5252D

at Workshop m/s

Cheng Hwe Motor

Tel:

6755 6142

of

Blk 1019 Yishun Ind. park A # 01-374

Policy No:

29134373

Claim No:

618820

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/01/2020

(Client's Record)

31/01/2020

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

5:08pm @ 30/1/2020

Person Contacted:

June

Vehicle IN / OUT

Date/Time

Action/Instruction

Ishtoval ✓

SMG 2736G - X

SMN 5252D

04/2/20 @

4:01pm revised to Irene Tan via Mervin.

20/2

@ 11874.92 Car loan used \$ 7616.80, 18%.

REF: MS1G

ASSIGNMENT

From: _____ Date: 31/01/2020 Veh No: SMG 27366 Regn: 12 18

Estimated Cost: _____ Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

OD: TP / WS / TP RES / OD RES / EVA / INV / MV Make: Honda / Verde C.C. 1496

To Inspect Vehicle No: SMG 27366 Colour: M.D. Blue A/C: Insured / Std / NI / NA

at Workshop n/s: cheng for motor Sp. Reading: 29761 T/Ratio: Insured / Std / NI / NA

of Blk 1019 Yishun Ind Park A #01-374 Eng/No: _____

Insured: _____ C/No: RUI 1309813

Policy No: _____ Gen. Cond: Good / Fair / Poor / Burnt

Claims No: _____ Steering: In order / Jammed / Leaked / Burnt or

Sum Insured: _____ Excess: _____ Brake: In order / Jammed / Leaked / Burnt or

(Client's Record) Mod: Nil / 2Rim / STD A/Rim or

Make of Veh: _____ Tyre Size: F: 215/60R16
R: _____

(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value: Front: _____ Rear: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No R/Bal. 0 mm

GIA / PR Seen: _____ Consistent? : Yes or No L/Bal. 0 mm


Est. Repairs: 08 days Res.: Yes or No D.O.A. 29/1/20 D.O.I. 31/1/2020

Lum Sum: 1-B.1 % 3 Val: Yes or No Survey held at: ✓

CA / REV / REP. / 24 HRS 1wps Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____ Rear d/s & 1st

Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
<u>3/2</u>	<u>Est not ready</u> <u>Sent Insurance (Pending Estimate) email</u>
	<u>20/2/2020</u>

RECEIVED 24 FEB 2020

Date/Time, File Pass to? ☐ : Prel. Report

24/2 12:15 ☐ : Final Report

Date/Time, File Return to? _____

Days Of Repair: 9

Resurvey No. of Trip: 1

Survey Fee: 200

Transportation: _____

Site Fee: 11

Report Format: MER-TP

Line No / ID: 11874.92

Add Fee: ☐ : Site Insp. (\$) ☐ : Interview (\$) ☐ : Tech. Insp. (\$) ☐ : Workshop (\$)

TOTAL: 211

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, February 03, 2020 10:54 AM
To: 'Crystal Lee'; 'Ong Zi Hui'
Cc: SUR
Subject: Survey Request - Manual Assigned

Dear Sir,

Please be informed that we have inspected the vehicle SMG2736G on 31/01/2020.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler (BEHALF SHIAU CHAN)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, February 03, 2020 10:45 AM
To: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Subject: FW: Survey Request - Manual Assigned

Wishing you a Happy and Prosperous Lunar New Year



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Thursday, 30 January 2020 4:27 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

Repair Survey (Single Joint Expert) - SMG2736G DOA: 29/01/2020 YR INSD: SMN5252D (MSIG)

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua <helene_phua@sg.msig-asia.com>

Sent: Thursday, 30 January 2020 3:29 PM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: Repair Survey (Single Joint Expert) - SMG2736G DOA: 29/01/2020 YR INSD: SMN5252D (MSIG)

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Thursday, 30 January 2020 3:28 PM
To: 'Cheng Hoe Motor Pte Lts (Yishun -June)' <chmotor@singnet.com.sg>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: Repair Survey (Single Joint Expert) - SMG2736G DOA: 29/01/2020 YR INSD: SMN5252D (MSIG)

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

The officer in charge is Ms Chhia.

Please let us know the workshop details.

Thank you.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Cheng Hoe Motor Pte Lts (Yishun -June) <chmotor@singnet.com.sg>
Sent: Thursday, 30 January 2020 1:59 PM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>; chmotor@singnet.com.sg
Subject: RE: Repair Survey (Single Joint Expert) - SMG2736G DOA: 29/01/2020 YR INSD: SMN5252D (MSIG)

Hi,

(A) Our selection as below :-

1) LKK Auto Consultants Pte Ltd

Pls assist to arrange for survey.

(B) Please advise OIC.

Thank you.

Rgds

June

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

From: Helene Phua <helene_phua@sg.msig-asia.com>

Sent: Thursday, 30 January 2020 1:50 pm

To: chmotor@singnet.com.sg

Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>

Subject: RE: Repair Survey (Single Joint Expert) - SMG2736G DOA: 29/01/2020 YR INSD: SMN5252D (MSIG)

Hi,

We refer to your email dated 30/01/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd (not available from 30 Jan to 31 Jan)
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Efeeda (Cheng Hoe -Yishun) [<mailto:chmotor@singnet.com.sg>]

Sent: Thursday, 30 January 2020 12:11 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Cc: Chmotor <chmotor@singnet.com.sg>

Subject: Repair Survey (Single Joint Expert) - SMG2736G DOA: 29/01/2020 YR INSD: SMN5252D

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir,

OUR CLIENT : SMG2736G

DOA : 29/01/2020 @ 0645HRS

YOUR INSD : SMN5252D

Kindly provide us your surveyor listing for the selection on the survey.

Thank you.

Regards

Efeeda

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 04 Feb 2020

Preliminary Advice

Insured Vehicle No	: SMN5252D	Accident Date	: 29/01/2020
TP Vehicle No	: SMG2736G	Assignment Date	: 03/02/2020
Make	: HONDA VEZEL	Est. Duration of Repair	: 9.00
Date of Inspection	: 31/01/2020		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,641.96
Revised Amount	:S\$	9,424.44
Check Items (Estimated)	:S\$	3,597.84
Total	:S\$	13,022.28

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, 3 February 2020 10:54 AM
To: 'Crystal Lee'; 'Ong Zi Hui'
Cc: SUR
Subject: Survey Request - Manual Assigned

Dear Sir,

Please be informed that we have inspected the vehicle SMG2736G on 31/01/2020.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler (BEHALF SHIAU CHAN)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, February 03, 2020 10:45 AM
To: Yvonne Wong (LKK Auto) <yvonne.wong@lkkauto.com>
Subject: FW: Survey Request - Manual Assigned

Wishing you a Happy and Prosperous Lunar New Year~



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Crystal Lee [mailto:crystal_lee@sg.msig-asia.com]
Sent: Thursday, 30 January 2020 4:27 PM
To: Admin-D (LKKAuto); assignments

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	902E
Vehicle Details	
Vehicle No.:	SMG2736G
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	L15B5559821
Chassis No.:	RU11309813
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$24,248.00
Original Registration Date:	12 Dec 2018
First Registration Date:	12 Dec 2018
Transfer Count:	1
Actual ARF Paid:	\$15,948.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2028
PARF Rebate Amount:	\$11,961.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$23,568.00
COE Rebate Amount:	\$20,888.00
Total Rebate Amount:	\$32,849.00

The information contained herein is correct as at 30 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2020 09:45
Date Of Accident	29/01/2020 06:45
Exact Location Of Accident	BKE TOWRDS KJE (GALI BATU FLYOVER)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG2736G
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD SHADIQ BIN AZIZ
NRIC No	SXXXX902E
Email Address	PAYNEDEK@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91871714
Alternative Phone No	OTHERS-91871714

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PVT USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110232511
Cover Note Number	12/6/19-11/6/20

Driver

Name of Driver	MUHAMMAD SHADIQ BIN AZIZ
NRIC No	SXXXX902E
Date Of Birth	11/04/1983
Occupation	INDOOR
Date Of Driving Pass	16/11/2001
Driving Experience	18 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91871714
Fax Number	
Contact Number	OTHERS-91871714
EEmail Address	PAYNEDEK@HOTMAIL.COM

Address	BLK 799 YISHUN RING RD #06-3418
Postcode	760799
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MD LUTFI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ACCIDENT OCCURED ON 29/1/20 AT ABOUT 645AM. UPON NOTICED M/VEH(D) CAME TO A STOP, I ALSO FOLLOW TO BRAKE AND STOP BEHIND. THE NEXT MOMENT, I FELT A GREAT IMPACT ON MY REAR AND THE IMPACT CAUSE MY VEHICLE TO SURGE FORWARD AND HIT ONTO THE REAR OF M/VEH(D). I ALIGHTED AND REALIZED I AM INVOLVED IN A CHAIN ACCIDENT INVOLVING 4 VEHICLES INCLUDING MINE. ALL DRIVERS EXCHANGED PARTICULARS. I HAVE 1 PASSENGER ONBOARD. NO ONE WAS INJURED HOWEVER DUE TO THE IMPACT, I FELT DISCOMFORT AND HAD CONSULTED THE DOCTOR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN5252D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOONG CHEN YIT
NRIC/Passport Number	SXXXX332E
Contact Number	96985696
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBE6851X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver FANG BIN
NRIC/Passport Number SXXXX278F
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJE8777U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver GOH MENG HUAT
NRIC/Passport Number SXXXX680Z
Contact Number 91886555
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMMAD SHADIQ BIN AZIZ
Approximate Age
Injuries Sustain
Injured person in which vehicle? SMG2736G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN



A = SMG 27366
 B = SMN 5252D
 Loong Chen Yit
 S 7879332E
 hp: 9698 5696
 C = GBE 6851X
 Fang Bin
 S 7167278F
 hp: —

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

D = SJE 8777U
 Goh Meng Huan
 S 77336802
 hp: 9188 6555


DOA: 29/1/20 Time: 645AM
 Location: BKE towards KJE
 (@ Gall Bath Flyover)


Accident occurred on 29/1/20 at about 645am. Upon noticed m/veh (D) came to a stop, I also follow to brake and stop behind. The next moment, I felt a great impact on my rear and the impact cause my vehicle to surge forward and hit onto the rear of m/veh (D). I alighted and realized I am involved in a chain accident involving 4 vehicles including mine. All drivers exchanged particulars. I have 1 passenger onboard. No one was injured however due to the impact, I felt discomfort and had consulted the doctor.



Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: 
 NRIC/FIN No.: CYS

GIARMC SketchPlanForm_V3

() Claim Own Policy () Claim Third Party () Reporting Only
 () Claim OD/TP at other workshop ()

MT/1082181-001
SKETCH PLAN

VEHICLE NO.: SMG 2736G
INSURER: HTM
DATE & TIME: 29.01.2020


@ 6:45am


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: cyf
NRIC/FIN No.:

30/1/2020

ATTN: MARTIN

LT4/buy

SMG 22369 → P9 1/2

1 m de bumper Rec-

_____ reinforcement ?

_____ reinforcement top garnish rx

_____ R/n side reinforcement Dr-

6 m _____ clips rec-

1 m _____ R/n fog lamp garnish cr-

1 m de grille cr-

_____ housing cr-

_____ Chrome cr-

_____ logo rec-

4 m _____ clips rec-

1 m bonnet R-

_____ R/n hinge ?

_____ inner rubber rx

_____ inner lock garnish cr-

2 m head lamps als mg cr als ?

2 m _____ lower brackets cr-

1 m de support panel Rx

Sm 6 27369 → Pg 2/2

1 pr rear bumper Bar -
_____ R/H reflector Gr -
_____ R/H side pad Br -
6 pr _____ Clips rec

1 pr tail gate Br -
_____ emblem 'V600' rec -
_____ R/H reflector ?

1 pr rear panel Br -
1 pr rear exhaust pipe ?
1 pr _____ holder D.T. -
1 pr centre exhaust ?
1 pr rear R/H wheel arch garnish Br -

CHENG HOG
67887719

SMG 27369.

1 pr fu no plate did/en \$35/ SN ✓

1 pr rear wls gym m \$40/ SN ✓

1 set reverse sensor cm \$200/ SN ✓

① R & R rear wls glass \$120/ ✓

② R & R rear bumper assy, tail lamps,
rear top spoiler, reflectors, tail gate assy,
to cutting, welding and renew rear
end panel, R & R rear rin sender, rear spare

tyre panel and realign the same \$800/ 700

③ Putty & respray on rear spare tyre panel,
rear bumper, rear panel, tail gate,
and rear affected area

\$900/ 800

④ R & R ~~rear~~ exhaust pipe and
check system

\$120/ ~~\$200~~ ?

⑤ R & R reverse camera and
reset system

\$40/ ✓

SMG 27369

relates ✓

⑧ R & R for bumper assy, grille, head lamps, fog
lamps, bonnet and attachment, To ~~the~~ ^{cutting, welding and repair} ~~the~~
support panel, ^{RSC} for both fenders and
sealing the same

\$800/500

⑨ R & R air-con, check, vacuum
and re fill gas

\$100/✓?

⑩ body overspray on for both fenders,
support panel, bonnet, hinges,
for bumper, reinforcement and
all affected area

\$900/200

⑪ Rust proof

\$90/✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotors@singnet.com.sg
GST 201001158E RCB NO: 201001158E

SMG2736G
TP/MSIG

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 29/01/2020

TP Veh Reg No: SMN5252D

Estimate No: ES2090095/YISHUN

Date: 31 Jan 2020

Policy No: 5110232511

Veh Reg No: SMG2736G

Make/Model: HONDA VEZEL 1.5 CVT

Chassis No: RU11309813

Engine No: L15B5559821

Reg. Date: 12/12/2018

Estimate Repair Cost to Vehicle No :SMG2736G

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 FRONT BUMPER	801.70	1 PC	801.70	✓
2 FRONT BUMPER REINFORCEMENT	360.80	1 PC	360.80	✓
3 FRONT BUMPER REINFORCEMENT TOP GARNISH	24.20	1 PC	24.20	✓
4 FRONT BUMPER RH SIDE RETAINER	22.10	1 PC	22.10	✓
5 FRONT BUMPER CLIPS	3.90	6 PCS	23.40	✓
6 FRONT BUMPER RH FOG LAMP GARNISH	60.10	1 PC	60.10	✓
7 FRONT GRILLE	380.00	1 PC	380.00	✓
8 FRONT GRILLE CHROME	440.00	1 PC	440.00	✓
9 FRONT GRILLE LOGO	27.40	1 PC	27.40	✓
10 FRONT GRILLE CLIPS	3.90	4 PCS	15.60	✓
11 BONNET	892.50	1 PC	892.50	✓
12 BONNET RH HINGE	48.50	1 PC	48.50	✓
13 BONNET INNER RUBBER	24.60	1 PC	24.60	✓
14 BONNET INNER LOCK GARNISH	85.60	1 PC	85.60	✓
15 HEADLAMPS	1,820.50	2 PCS	3,641.00	✓
16 HEADLAMP LOWER BRACKETS	35.00	2 PCS	70.00	✓
17 FRT SUPPORT PANEL	576.50	1 PC	576.50	✓
18 REAR BUMPER	777.90	1 PC	777.90	✓
19 REAR BUMPER RH REFLECTOR	148.50	1 PC	148.50	✓
20 REAR BUMPER RH SIDE PAD	195.00	1 PC	195.00	✓
21 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
22 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓
23 TAILGATE EMBLEM "VEZEL"	43.00	1 PC	43.00	✓
24 TAILGATE RH REFLECTOR	380.60	1 PC	380.60	✓
25 REAR PANEL	411.90	1 PC	411.90	✓
26 REAR EXHAUST PIPE	528.00	1 PC	528.00	✓
27 REAR EXHAUST PIPE HOLDER	18.70	1 PC	18.70	✓
28 CENTRE EXHAUST PIPE	599.30	1 PC	599.30	✓
29 REAR RH WHEEL ARP GARNISH	150.00	1 PC	150.00	✓
			11,871.20	
		Less 20%	2,374.24	9,496.96
Special Net				
30 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
31 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
32 REVERSE SENSOR	200.00	1 SET	200.00	✓
			275.00	275.00

Not Authorised
Return by 8/2/20
811874.92
9 days

2/69P.100

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department
WS Ref: TP/MSIG/YS
Claim Type: Third Party
Accident Date: 29/01/2020
TP Veh Reg No: SMN5252D

Estimate No: ES2090095/YISHUN
Date: 31 Jan 2020
Policy No: 5110232511
Veh Reg No: SMG2736G
Make/Model: HONDA VEZEL 1.5 CVT
Chassis No: RU11309813
Engine No: L15B5559821
Reg. Date: 12/12/2018

Estimate Repair Cost to Vehicle No :SMG2736G

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
33 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
34 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR TOP SPOILER, REFLECTORS, TAILGATE ASSY, CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR RH FENDER, REAR SPARE TYRE PANEL & REALIGN THE SAME	800.00	1 LA	800.00	Foot
35 PUTTY & RESPRAY ON REAR SPARE TYRE PANEL, REAR BUMPER, REAR PANEL, TAILGATE & REAR AFFECTED AREAS	900.00	1 LA	900.00	800
36 REMOVE & REFIX EXHAUST PIPE & CHECK SYSTEM	120.00	1 LA	120.00	80
37 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	40.00	1 LA	40.00	✓
38 REMOVE & REFIX FRT BUMPER ASSY, GRILLE, RADIATOR, HEADLAMPS, FOG LAMPS, BONNET & ATTACHMENT, CUT, WELD & RENEW FRT SUPPORT PANEL, KNOCK & REPAIR FRT BOTH FENDERS & REALIGN THE SAME	800.00	1 LA	800.00	500
39 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
40 PUTTY & RESPRAY ON FRT BOTH FENDER, SUPPORT PANEL, BONNET, HINGES, FRT BUMPER, REINFORCEMENT & ALL AFFECTED AREAS	900.00	1 LA	900.00	800
41 RUSTPROOFING	90.00	1 LA	90.00	✓
			3,870.00	3,870.00
			Total	S\$ 13,641.96
			Add GST @ 7%	954.94
			Total Amount Payable	S\$ 14,596.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

14491.32

14491.56

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCH NO: 201001158E

SMG 2736 G

Supp 1

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department
WS Ref: TP/MSIG/YS
Claim Type: Third Party
Accident Date: 29/01/2020
TP Veh Reg No: SMN5252D

Estimate No: ES2090095/YISHUN
Date: 04 Feb 2020
Policy No: 5110232511
Veh Reg No: SMG2736G
Make/Model: HONDA VEZEL 1.5 CVT
Chassis No: RU11309813
Engine No: L15B5559821
Reg. Date: 12/12/2018

Estimate Repair Cost to Vehicle No :SMG2736G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 FRONT RH HEADLAMP EXT. MOULDING	89.50	1 PC	89.50	
2 RH TAILLAMP	474.60	1 PC	474.60	
3 REAR END PANEL TOP GARNISH	92.50	1 PC	92.50	
4 FRONT GRILLE TOP BRACKET INNER	174.50	1 PC	174.50	
5 front support top garnish	231.10		831.10	
		Less 20%	166.22	664.88
	1062.10	Total		S\$ 664.88
		GST Amount		S\$ 46.54
		Total Amount Payable		S\$ 711.42

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Parts # 9525.20
Supp # 1062.20
#70,587.40
2117.48
#8469.92
2735.50
Labor # 2130 3130
11,874.92

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Feb 2020		03 Feb 2020 15:26 Edit Adj Rpt	S\$11,874.92 Edit Estimates	S\$11,874.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------




































CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	ADVANCE LIMO & RENTAL PTE LTD, Co. Reg. No.: 201406694C	
Main Claimant:	MUHAMMAD SHADIQ BIN AZIZ, ID: S8310902E	
Vehicle Reg. No.:	SMG2736G	Date of Loss: 29/01/2020 06:00 - :59 [13 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 618828	Policy/Cover Note No.: 29134373 (Comprehensive) Coverage: 05/09/2019 - 04/09/2020
Vehicle Reg. No. (Insured):	SMN5252D	Policy No. (Claimant): 5110232511
		Excess:
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/03/2020]	
Driver/Custodian (Insured):	LOONG CHEN YIT (41 / Male), NRIC: S7879332E, Tel: +6596985696 Email:	
Adj Asg. Remarks:	on WP Manual assigned to LKK via email on 30/01/2020, (Manual Assign), Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Efeeda @ 6755 6142.	






































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMG2736G (618828)**
[SMN5252D]
TP
MUHAMMAD SHADIQ BIN AZIZ
Jan 29 2020 6:00AM
[ADVANCE LIMO & RENTAL PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/02/20 16:01	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
12	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
13	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
14	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
15	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
16	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
17	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
18	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
19	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
20	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
21	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
22	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
23	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
24	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
25	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
26	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
27	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
28	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
29	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
30	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
31	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	20/02/20 12:08	General View	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	20/02/20 12:08	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
36	20/02/20 12:08	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
37	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/02/20 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/02/20 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/02/20 15:03	E-FILE SMG2736G	 Load PDF	
2	03/02/20 15:12	Agree on SJE	 Load PDF	
3	03/02/20 17:09	Status of Driving Licence <small>From: SC - Reg. No: SMN5252D, Claimant: ADVANCE LIMO & RENTAL PTE LTD</small>	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20001609/KQD3E2

Date: 26/02/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29134373

Claimant Vehicle No : SMG2736G

Insured Vehicle No : SMN5252D

Date of Loss: 29/01/2020

Nature of Claim: TP Claim No: 618828

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG2736G

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B5559821

Reg. Date: 12/12/2018 (Man. Year: 2018)

Chassis No: RU11309813

Colour: Metallic Dark Blue

Odometer: 29761 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 8 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,701.56	8,744.92	1,956.64	18.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	3,130.00	740.00	19.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,571.56	11,874.92	2,696.64	18.51
+ GST 7.00/7.00% (S\$)	1,020.01	831.24	188.77	18.51
Nett Amount (S\$)	15,591.57	12,706.16	2,885.41	18.51

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 31/01/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG2736G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	801.70 FL	*801.70 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	360.80 FL	*360.80 FL
3	1		*FRONT BUMPER REINFORCEMENT TOP GARNISH	Serviceable	24.20 FL	*- FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	22.10 FL	*22.10 FL
5	6		*FRONT BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
6	1		*FRONT BUMPER RH FOG LAMP GARNISH	Cut	60.10 FL	*60.10 FL
7	1		*FRONT GRILLE	Cracked	380.00 FL	*380.00 FL
8	1		*FRONT GRILLE CHROME	Cracked	440.00 FL	*440.00 FL
9	1		*FRONT GRILLE LOGO	Necessary	27.40 FL	*27.40 FL
10	4		*FRONT GRILLE CLIPS	Necessary	15.60 FL	*15.60 FL
11	1		*BONNET	Bent	892.50 FL	*892.50 FL
12	1		*BONNET RH HINGE	Distorted	48.50 FL	*48.50 FL
13	1		*BONNET INNER RUBBER	Serviceable	24.60 FL	*- FL
14	1		*BONNET INNER LOCK GARNISH	Cracked	85.60 FL	*85.60 FL
15	1		*HEADLAMPS	O/S MtgCracked/N/S Serviceable	3,641.00 FL	*1,820.50 FL
16	2		*HEADLAMP LOWER BRACKETS	Cracked	70.00 FL	*70.00 FL
17	1		*FRT SUPPORT PANEL	Repair	576.50 FL	*- FL
18	1		*REAR BUMPER	Buckled	777.90 FL	*777.90 FL
19	1		*REAR BUMPER RH REFLECTOR	Scratched	148.50 FL	*148.50 FL
20	1		*REAR BUMPER RH SIDE PAD	Buckled	195.00 FL	*195.00 FL
21	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
22	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
23	1		*TAILGATE EMBLEM VEZEL	Necessary	43.00 FL	*43.00 FL
24	1		*TAILGATE RH REFLECTOR	Mtg Cracked	380.60 FL	*380.60 FL
25	1		*REAR PANEL	Bent	411.90 FL	*411.90 FL
26	1		*REAR EXHAUST PIPE	Bent	528.00 FL	*528.00 FL
27	1		*REAR EXHAUST PIPE HOLDER	Distorted	18.70 FL	*18.70 FL
28	1		*CENTRE EXHAUST PIPE	Bent	699.10 FL	*699.10 FL
29	1		*REAR RH WHEEL APP GARNISH	Buckled	150.00 FL	*150.00 FL
30	1		*FRONT NUMBER PLATE	Dented	35.00 FS	*35.00 FS
31	1		*ROLL REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
32	1		*SET REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
33	1		*FRONT RH HEADLAMP EXT. MOULDING	Necessary	89.50 FL	*89.50 FL
34	1		*RH TAILLAMP	Cut	474.60 FL	*474.60 FL
35	1		*REAR END PANEL TOP GARNISH	Dented	92.50 FL	*92.50 FL
36	1		*FRONT GRILLE TOP BRACKET INNER	Cracked	174.50 FL	*174.50 FL
37	1		*FRONT SUPPORT TOP GARNISH	Dented	231.10 FL	*231.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc						
Sub Total (\$\$)					13,308.20	10,862.40
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,806.64	2,117.48
Total Parts (\$\$)					10,701.56	8,744.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR TOP SPOILER, REFLECTORS, TAILGATE ASSY, CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR RH FENDER, REAR SPARE TYRE PANEL & REALIGN THE SAME	New	800.00	700.00
3	PUTTY & RESPRAY ON REAR SPARE TYRE PANEL, REAR BUMPER, REAR PANEL, TAILGATE & REAR AFFECTED AREAS	New	900.00	800.00
4	REMOVE & REFIX EXHAUST PIPE & CHECK SYSTEM	New	120.00	80.00
5	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	40.00	40.00
6	REMOVE & REFIX FRT BUMPER ASSY, GRILLE, RADIATOR, HEADLAMPS, FOG LAMPS, BONNET & ATTACHMENT, CUT, WELD & RENEW FRT SUPPORT PANEL, KNOCK & REPAIR FRT BOTH FENDERS & REALIGN THE SAME	New	800.00	500.00
7	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	0.00
8	PUTTY & RESPRAY ON FRT BOTH FENDER, SUPPORT PANEL, BONNET, HINGES, FRT BUMPER, REINFORCEMENT & ALL AFFECTED AREAS	New	900.00	800.00
9	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (S\$)			3,870.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >