

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	71230
Policy No:	Z20VP05025636	Date of Loss:	27/01/2020
Vehicle Reg. No.:	SJU64L	Driveable?	
Driver Age/Info:	53 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	SABRINA CHUA WAN KIANG	Contact No:	+6597310708
Driver:	SABRINA CHUA WAN KIANG		

Make/Model:	BMW 640I, 3.0 CONVERTIBLE M SPORT (A)	Vehicle Reg. Date:	21/01/2013
Vehicle Colour:	BLACK	Chassis No:	WBALW72080DK15603
Engine No:	09358354N55B30A		
Odometer:	72324 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO

8/5 days

not auth



*NOT Authorized
Resurvey B4 paint
Ex 8500h*

Description of Accident/Loss: PLEASE REFER TO SKETCH PLAN.
Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

Ref: 62564315

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

	Amount
LKK Auto Consultants hence notify the Repairer of the following:	
• To resurvey before/after spray painting	9,392.63
• To display damaged part(s) during resurvey	0.00
• Parts prices are subject to confirmation	860.00
• Third party survey is on a "Without Prejudice" basis	650.00
• No illegal modification(s) is allowed	0.00
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Calculated Gross Total (S\$)	10,902.63
Acknowledged by Repairer Signature: - Excess (S\$)	500.00
Date:	(S\$)
	10,402.63
+ GST 7.00% (S\$)	728.18
Nett Amount (S\$)	11,130.81

This claim is handled by: JENNY LIM LAI FOONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2020)
Parts: 143 BMW 640I 3.0 Convertible M Sport (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/30/01/2020 13:17
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	0.00	0.00	CM *1,180.00 F
2	1		*Front headlamp LH	Mrg cm 0.00	0.00	*3,350.00 F
3	1		*Front headlamp panel LH	0.00	0.00	CM *100.00 F
4	1		*Front fender LH	0.00	0.00	CM *730.00 F
5	1		*Front fender inner shield LH	0.00	0.00	bi *100.00 F
6	3		*Front fender inner shield rivets LH	0.00	0.00	na *10.50 F
7	1		*Front shock absorber LH	950 0.00	0.00	NEC *1,400.00 F
8	1		*Front control arm LH	0.00	0.00	ni *330.00 F
9	1		*Front lower arm LH	0.00	0.00	PM *310.00 F
10	1		*Front knuckle arm LH	SVC 0.00	0.00	na *450.00 F
11	1		*Front stabilizer bar link LH	0.00	0.00	PM *72.00 F
12	1		*Engine side cover LH	SVC 0.00	0.00	CM *135.00 F

F=Franchise part.

Sub Total (S\$) 8,167.50
 + Margin on L,N Items 15.00% (S\$) 1,225.13
Total Parts (S\$) 9,392.63

Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/30/01/2020 13:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To spray paint	New	500 650.00
Labour Items			
2	Towing fee (4-wheel)	New	(Bill) 150.00
3	To check wheel alignment (computerised)	New	80.00
4	To check/clear fault codes	New	80.00
5	To straighten front body, to dismantle + renew of parts	New	550.00
Gross Labour Cost (S\$)			1,510.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/30/01/2020 13:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

SUPPLEMENTARY

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2020)
Parts: 143 BMW 640I 3.0 Convertible M Sport (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/28/05/2020 09:54
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper lower corner cover LH	0.00	0.00	CM *35.00 F ✓
2	1		*Front fender inner shield LH (rear portion)	0.00	0.00	CM *92.00 F ✓
Sub Total (S\$)						127.00
+ Margin on L,N Items 15.00% (S\$)						19.05
Total Parts (S\$)						146.05

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/28/05/2020 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

SUPPLEMENTARY

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Labour to reprogram EDCSVL damper satellite, front left	New	250.00 ✓
Gross Labour Cost (S\$)			250.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/28/05/2020 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >