

REPAIR DETAILS

SUPPLEMENTARY

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2020)
Parts: 143 BMW 640I 3.0 Convertible M Sport (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/28/05/2020 09:54
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper lower corner cover LH	0.00	0.00	CM *35.00 F ✓
2	1		*Front fender inner shield LH (rear portion)	0.00	0.00	CM *92.00 F ✓
Sub Total (S\$)						127.00
+ Margin on L,N Items 15.00% (S\$)						19.05
Total Parts (S\$)						146.05

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/28/05/2020 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

SUPPLEMENTARY

No	Particulars	Lab.Type	Amount
Labour Items			
1	Labour to reprogram EDCSVL damper satellite, front left	New	250.00
Gross Labour Cost (S\$)			250.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJU64L/28/05/2020 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >