



SMRT Accident Vehicle Repair Estimates

60 Woodlands Industrial Park E4, Singapore 757703
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/01/2020

User ID : kimmingchin

Section A - Accident Details	
Registration Number	SHB5025R
Case Reference Number	TAX/01/20/2123
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEE LOI FOOK
Type of Accident	Side Swipe
Accident Date and Time	28/1/2020 3:00 PM
Accident Reported Date and Time	28/1/2020 4:19 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105446
Special Instruction to ARC, if any	LEFT HAND FRONT PORTION
Prepared Date and Time	29/1/2020 7:11 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$350.00
Total Spray Cost	\$2,034.00	\$450.00
Total Spare Part Cost	\$8,154.00	\$3,621.59
Total Other Cost	\$950.00	\$90.00
TOTAL COST	\$11,983.00	\$4,511.59
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN
ARC / Surveyor Sign Off Date	29/01/2020 7:29 AM	29/01/2020 3:48 PM
Signature		
Remarks		P/P repair, take before spray.

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

60 Woodlands Industrial Park E4, Singapore 737703
FAX Number : 6385592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/01/2020

User ID : kimmingchin

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	\$845.00	\$350.00
Total Labour	\$845.00	\$350.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT WHEEL HOUSE LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
RESPRAY WHEEL CAP	\$180.00	\$50.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,034.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 / MK
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$120.00	\$20.00 / MK
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$20.00 / MK
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 / MK
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$950.00	\$90.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace / DR
		8122047020	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Check X NM
		5211647050	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.72	Replace	Replace / DR
		8118547691	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace / CM
		8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given X NM
		5380247100	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace / DO
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.67	Replace	Replace / MK
		5387647110	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace / TN
		5387930050	RETAINER, FR FENDER NO. 2	0.00	\$16.80	0.00	\$0.00	Replace	Not Given X NM
		5387947020	RETAINER, FR FENDER NO. 1	0.00	\$4.90	0.00	\$0.00	Replace	Not Given X NM
		5321447050	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given X NM
		5370247101	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	0.00	\$0.00	Replace	Not Given X NM
		5370647901	BRACE SUB-ASSY, FENDER APRON, LH	0.00	\$282.70	0.00	\$0.00	Replace	Not Given X NM
		5320347901	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given X NM
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given X NM
		4260247180	CAP SUB-ASSY, WHEEL	1.00	\$175.80	100.00	\$0.00	Replace	Repair X NM

SMRT Accident Vehicle Repair Estimates

60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/01/2020

User ID : kimmingchin

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5330147110	HOOD SUB-ASSY	0.00	\$938.40	0.00	\$0.00	Replace	Not Given <i>X NA</i>
		5342047130	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given <i>X NA</i>
		5341047130	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given <i>X NA</i>
Total					\$10,059.20		\$3,621.59		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: